

# Property Statement from the Listed Land Use Register

Visit [ecan.govt.nz/HAIL](http://ecan.govt.nz/HAIL) for more information or  
contact Customer Services at [ecan.govt.nz/contact/](http://ecan.govt.nz/contact/) and quote ENQ418816

**Date generated:** 17 June 2025  
**Land parcels:** Section 1 SO 429894



The information presented in this map is specific to the area within a 500m radius of property you have selected. Information on properties outside the search radius may not be shown on this map, even if the property is visible.

## Sites at a glance

 **Sites within enquiry area**

Site number	Name	Location	HAIL activity(s)	Category
-------------	------	----------	------------------	----------

Please note that the above table represents a summary of sites and HAILS intersecting the area of enquiry only.

 **Nearby sites**

Site number	Name	Location	HAIL activity(s)	Category
260	Haldon Landfill	Haldon Arm Road, approximately 15km southeast of Twizel.	G3 - Landfill sites;	Not Investigated

Please note that the above table represents a summary of sites and HAILS intersecting the area of enquiry within a 500m buffer.

## More detail about the sites

**Site 260: Haldon Landfill** (Within 500m of enquiry area.)

**Category:** Not Investigated

Definition: Verified HAIL has not been investigated.

Location: Haldon Arm Road, approximately 15km southeast of Twizel.

Legal description(s): Section 1 SO 19933

HAIL activity(s):

Period from	Period to	HAIL activity
1986	2004	Landfill sites

#### Notes:

4 Jul 2005

The landfill is located at the Haldon campground, approx 700m from the north shore of Lake Benmore and 15km southeast of Twizel. The closed landfill has been covered with gravel, and the new landfill only receives material from the camping grounds during the summer camping season. It comprises a very small pit-type operation of 32sqm.

28 Aug 2006

Response from site owner including information supplied by lessees of site: "Landfill closed 2 years, rubbish transported back to Timaru for disposal. Landfill enclosed by 6ft fence with barbed wire on top and a locked gate".



#### Investigations:

There are no investigations associated with this site.



#### Nearby investigations of interest

There are no investigations associated with the area of enquiry.

## Disclaimer

The enclosed information is derived from Environment Canterbury's Listed Land Use Register and is made available to you under the Local Government Official Information and Meetings Act 1987.

The information contained in this report reflects the current records held by Environment Canterbury regarding the activities undertaken on the site, its possible contamination and based on that information, the categorisation of the site. Environment Canterbury has not verified the accuracy or completeness of this information. It is released only as a copy of Environment Canterbury's records and is not intended to provide a full, complete or totally accurate assessment of the site. It is provided on the basis that Environment Canterbury makes no warranty or representation regarding the reliability, accuracy or completeness of the information provided or the level of contamination (if any) at the relevant site or that the site is suitable or otherwise for any particular purpose. Environment Canterbury accepts no responsibility for any loss, cost, damage or expense any person may incur as a result of the use, reference to or reliance on the information contained in this report.

Any person receiving and using this information is bound by the provisions of the Privacy Act 1993.