




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -51/137
Traverse: N/A
Borehole: UW66

Processed by: VR
Date: 22/05/2017
Defect type: Joints
Stratigraphy: N/A



Symbol	TYPE	Quantity
▲	JT	128
Plot Mode		Pole Vectors
Vector Count		128 (128 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
▲	JT	128
Color		Density Concentrations
		0.00 - 1.00
		1.00 - 2.00
		2.00 - 3.00
		3.00 - 4.00
		4.00 - 5.00
		5.00 - 6.00
		6.00 - 7.00
Maximum Density		6.60%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		128 (128 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -51/137
Traverse: N/A
Borehole: UW66

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	VN	354
Plot Mode Pole Vectors		
Vector Count 354 (354 Entries)		
Hemisphere Lower		
Projection Equal Area		



Symbol	TYPE	Quantity
•	VN	354
Color		
Density Concentrations		
0.00 - 0.70		
0.70 - 1.40		
1.40 - 2.10		
2.10 - 2.80		
2.80 - 3.50		
3.50 - 4.20		
4.20 - 4.90		
Maximum Density 4.83%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 354 (354 Entries)		
Hemisphere Lower		
Projection Equal Area		




PSM125
ORI CORE
BOREHOLE

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -50/309
Traverse: N/A
Borehole: UW68

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	62
×	Breccia	1
●	CN	38
●	FT	1
▲	JT	78
■	SH	13
●	VN	779

Plot Mode	Pole Vectors
Vector Count	972 (972 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
□	BG	62
×	Breccia	1
●	CN	38
●	FT	1
▲	JT	78
■	SH	13
●	VN	779

Color	Density Concentrations
	0.00 - 0.90
	0.90 - 1.80
	1.80 - 2.70
	2.70 - 3.60
	3.60 - 4.50
	4.50 - 5.40
	5.40 - 6.30

Maximum Density	6.15%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%


Plot Mode	Pole Vectors
Vector Count	972 (972 Entries)
Hemisphere	Lower
Projection	Equal Area

**PSM125
ORI CORE
BOREHOLE**


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -50/309
Traverse: N/A
Borehole: UW68

Processed by: VR
Date: 22/05/2017
Defect type: Bedding/Contact
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	62
●	CN	38
Plot Mode		Pole Vectors
Vector Count		100 (100 Entries)
Hemisphere		Lower
Projection		Equal Area




Symbol	TYPE	Quantity
□	BG	62
●	CN	38
Color	Density Concentrations	
	0.00	- 1.30
	1.30	- 2.60
	2.60	- 3.90
	3.90	- 5.20
	5.20	- 6.50
	6.50	- 7.80
	7.80	- 9.10
Maximum Density		8.57%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		100 (100 Entries)
Hemisphere		Lower
Projection		Equal Area

**PSM125
ORI CORE
BOREHOLE**

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -50/309
Traverse: N/A
Borehole: UW68

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
◊	Breccia	1
•	FT	1
■	SH	13

Plot Mode	Pole Vectors
Vector Count	15 (15 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
◊	Breccia	1
•	FT	1
■	SH	13

Color	Density Concentrations
	0.00 - 3.60
	3.60 - 7.20
	7.20 - 10.80
	10.80 - 14.40
	14.40 - 18.00
	18.00 - 21.60
	21.60 - 25.20

Maximum Density	24.96%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%


Plot Mode	Pole Vectors
Vector Count	15 (15 Entries)
Hemisphere	Lower
Projection	Equal Area

**PSM125
ORI CORE
BOREHOLE**


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -50/309
Traverse: N/A
Borehole: UW68

Processed by: VR
Date: 22/05/2017
Defect type: Joints
Stratigraphy: N/A



Symbol	TYPE	Quantity
▲	JT	78
Plot Mode		Pole Vectors
Vector Count		78 (78 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
▲	JT	78
Color		Density Concentrations
		0.00 - 1.30
		1.30 - 2.60
		2.60 - 3.90
		3.90 - 5.20
		5.20 - 6.50
		6.50 - 7.80
		7.80 - 9.10
Maximum Density		8.98%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		78 (78 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -50/309
Traverse: N/A
Borehole: UW68

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	VN	779
Plot Mode Pole Vectors		
Vector Count 779 (779 Entries)		
Hemisphere Lower		
Projection Equal Area		




Symbol	TYPE	Quantity
•	VN	779
Color		
Density Concentrations		
0.00 - 1.00		
1.00 - 2.00		
2.00 - 3.00		
3.00 - 4.00		
4.00 - 5.00		
5.00 - 6.00		
6.00 - 7.00		
Maximum Density 6.59%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 779 (779 Entries)		
Hemisphere Lower		
Projection Equal Area		

**PSM125
ORI CORE
BOREHOLE**

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -51/315
Traverse: N/A
Borehole: UW70

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	52
●	CN	20
×	CZ	1
▲	JT	46
■	SH	70
●	VN	427

Plot Mode	Pole Vectors
Vector Count	616 (616 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
□	BG	52
●	CN	20
×	CZ	1
▲	JT	46
■	SH	70
●	VN	427

Color	Density Concentrations
	0.00 - 0.50
	0.50 - 1.00
	1.00 - 1.50
	1.50 - 2.00
	2.00 - 2.50
	2.50 - 3.00
	3.00 - 3.50

Maximum Density	3.32%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	616 (616 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -51/315
Traverse: N/A
Borehole: UW70

Processed by: VR
Date: 22/05/2017
Defect type: Bedding/Contact
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	52
●	CN	20
Plot Mode		
Pole Vectors		
Vector Count		
72 (72 Entries)		
Hemisphere		
Lower		
Projection		
Equal Area		




Symbol	TYPE	Quantity
□	BG	52
●	CN	20
Color		
Density Concentrations		
0.00 - 1.40		
1.40 - 2.80		
2.80 - 4.20		
4.20 - 5.60		
5.60 - 7.00		
7.00 - 8.40		
8.40 - 9.80		
Maximum Density		
9.65%		
Contour Data		
Pole Vectors		
Contour Distribution		
Fisher		
Counting Circle Size		
1.0%		
Plot Mode		
Pole Vectors		
Vector Count		
72 (72 Entries)		
Hemisphere		
Lower		
Projection		
Equal Area		

**PSM125
ORI CORE
BOREHOLE**

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -51/315
Traverse: N/A
Borehole: UW70

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
x	CZ	1
■	SH	70

Plot Mode	Pole Vectors
Vector Count	71 (71 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
x	CZ	1
■	SH	70

Color	Density Concentrations
	0.00 - 1.40
	1.40 - 2.80
	2.80 - 4.20
	4.20 - 5.60
	5.60 - 7.00
	7.00 - 8.40
	8.40 - 9.80

Maximum Density	9.67%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	71 (71 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -51/315
Traverse: N/A
Borehole: UW70

Processed by: VR
Date: 22/05/2017
Defect type: Joints
Stratigraphy: N/A



Symbol	TYPE	Quantity
▲	JT	46
Plot Mode Pole Vectors		
Vector Count 46 (46 Entries)		
Hemisphere Lower		
Projection Equal Area		



Symbol	TYPE	Quantity
▲	JT	46
Color		
Density Concentrations		
0.00 - 1.40		
1.40 - 2.80		
2.80 - 4.20		
4.20 - 5.60		
5.60 - 7.00		
7.00 - 8.40		
8.40 - 9.80		
Maximum Density 9.40%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 46 (46 Entries)		
Hemisphere Lower		
Projection Equal Area		




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -51/315
Traverse: N/A
Borehole: UW70

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	VN	427
Plot Mode Pole Vectors		
Vector Count 427 (427 Entries)		
Hemisphere Lower		
Projection Equal Area		




Symbol	TYPE	Quantity
•	VN	427
Color		
Density Concentrations		
0.00 - 0.70		
0.70 - 1.40		
1.40 - 2.10		
2.10 - 2.80		
2.80 - 3.50		
3.50 - 4.20		
4.20 - 4.90		
Maximum Density 4.57%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 427 (427 Entries)		
Hemisphere Lower		
Projection Equal Area		

PSM125
ORI CORE
BOREHOLE

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -49/315
Traverse: N/A
Borehole: UW72

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	17
X	Breccia	2
●	CN	12
▲	JT	66
■	SH	35
●	VN	156

Plot Mode	Pole Vectors
Vector Count	288 (288 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
□	BG	17
X	Breccia	2
●	CN	12
▲	JT	66
■	SH	35
●	VN	156

Color	Density Concentrations
	0.00 - 0.80
	0.80 - 1.60
	1.60 - 2.40
	2.40 - 3.20
	3.20 - 4.00
	4.00 - 4.80
	4.80 - 5.60

Maximum Density	5.06%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%


Plot Mode	Pole Vectors
Vector Count	288 (288 Entries)
Hemisphere	Lower
Projection	Equal Area

**PSM125
ORI CORE
BOREHOLE**


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -49/315
Traverse: N/A
Borehole: UW72

Processed by: VR
Date: 22/05/2017
Defect type: Bedding/Contact
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	17
●	CN	12
Plot Mode		Pole Vectors
Vector Count		29 (29 Entries)
Hemisphere		Lower
Projection		Equal Area




Symbol	TYPE	Quantity
□	BG	17
●	CN	12
Color		Density Concentrations
		0.00 - 3.20
		3.20 - 6.40
		6.40 - 9.60
		9.60 - 12.80
		12.80 - 16.00
		16.00 - 19.20
		19.20 - 22.40
Maximum Density		22.27%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		29 (29 Entries)
Hemisphere		Lower
Projection		Equal Area

PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -49/315
Traverse: N/A
Borehole: UW72

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
○	Breccia	2
■	SH	35
Plot Mode		Pole Vectors
Vector Count		37 (37 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
○	Breccia	2
■	SH	35
Color		Density Concentrations
		0.00 - 1.60
		1.60 - 3.20
		3.20 - 4.80
		4.80 - 6.40
		6.40 - 8.00
		8.00 - 9.60
		9.60 - 11.20
Maximum Density		10.55%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		37 (37 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -49/315
Traverse: N/A
Borehole: UW72

Processed by: VR
Date: 22/05/2017
Defect type: Joints
Stratigraphy: N/A



Symbol	TYPE	Quantity
▲	JT	66
Plot Mode		Pole Vectors
Vector Count		66 (66 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
▲	JT	66
Color		Density Concentrations
		0.00 - 1.30
		1.30 - 2.60
		2.60 - 3.90
		3.90 - 5.20
		5.20 - 6.50
		6.50 - 7.80
		7.80 - 9.10
Maximum Density		8.76%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		66 (66 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -49/315
Traverse: N/A
Borehole: UW72

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	VN	156
Plot Mode		Pole Vectors
Vector Count		156 (156 Entries)
Hemisphere		Lower
Projection		Equal Area




Symbol	TYPE	Quantity
•	VN	156
Color		Density Concentrations
		0.00 - 1.00
		1.00 - 2.00
		2.00 - 3.00
		3.00 - 4.00
		4.00 - 5.00
		5.00 - 6.00
		6.00 - 7.00
Maximum Density		6.56%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		156 (156 Entries)
Hemisphere		Lower
Projection		Equal Area

PSM125
ORI CORE
BOREHOLE

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -55/317
Traverse: N/A
Borehole: UW74

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	1
×	Breccia	1
▲	JT	53
■	SH	7
●	VN	88

Plot Mode	Pole Vectors
Vector Count	150 (150 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
□	BG	1
×	Breccia	1
▲	JT	53
■	SH	7
●	VN	88

Color	Density Concentrations
	0.00 - 0.90
	0.90 - 1.80
	1.80 - 2.70
	2.70 - 3.60
	3.60 - 4.50
	4.50 - 5.40
	5.40 - 6.30

Maximum Density	5.73%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	150 (150 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -55/317
Traverse: N/A
Borehole: UW74

Processed by: VR
Date: 22/05/2017
Defect type: Bedding/Contact
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	1
Plot Mode		Pole Vectors
Vector Count		1 (1 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
□	BG	1
Color		Density Concentrations
		0.00 - 14.20
		14.20 - 28.40
		28.40 - 42.60
		42.60 - 56.80
		56.80 - 71.00
		71.00 - 85.20
		85.20 - 99.40
Maximum Density		98.81%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		1 (1 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -55/317
Traverse: N/A
Borehole: UW74

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
◊	Breccia	1
■	SH	7

Plot Mode	Pole Vectors
Vector Count	8 (8 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
◊	Breccia	1
■	SH	7

Color	Density Concentrations
	0.00 - 3.40
	3.40 - 6.80
	6.80 - 10.20
	10.20 - 13.60
	13.60 - 17.00
	17.00 - 20.40
	20.40 - 23.80

Maximum Density	23.49%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	8 (8 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -55/317
Traverse: N/A
Borehole: UW74

Processed by: VR
Date: 22/05/2017
Defect type: Joints
Stratigraphy: N/A



Symbol	TYPE	Quantity
▲	JT	53
Plot Mode		
Vector Count		53 (53 Entries)
Hemisphere		Lower
Projection		Equal Area




Symbol	TYPE	Quantity
▲	JT	53
Color		
Density Concentrations		
0.00 - 1.30		
1.30 - 2.60		
2.60 - 3.90		
3.90 - 5.20		
5.20 - 6.50		
6.50 - 7.80		
7.80 - 9.10		
Maximum Density		8.48%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		
Vector Count		53 (53 Entries)
Hemisphere		Lower
Projection		Equal Area

**PSM125
ORI CORE
BOREHOLE**


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -55/317
Traverse: N/A
Borehole: UW74

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
	VN	88
Plot Mode Pole Vectors		
Vector Count 88 (88 Entries)		
Hemisphere Lower		
Projection Equal Area		




Symbol	TYPE	Quantity
	VN	88
Color		
Density Concentrations		
0.00 - 1.30		
1.30 - 2.60		
2.60 - 3.90		
3.90 - 5.20		
5.20 - 6.50		
6.50 - 7.80		
7.80 - 9.10		
Maximum Density 8.69%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 88 (88 Entries)		
Hemisphere Lower		
Projection Equal Area		

**PSM125
ORI CORE
BOREHOLE**

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -51/109
Traverse: N/A
Borehole: UW82

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	31
×	Breccia	10
●	CN	4
▲	JT	316
■	SH	39
●	VN	1586

Plot Mode	Pole Vectors
Vector Count	1986 (1986 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
□	BG	31
×	Breccia	10
●	CN	4
▲	JT	316
■	SH	39
●	VN	1586

Color	Density Concentrations
	0.00 - 0.70
	0.70 - 1.40
	1.40 - 2.10
	2.10 - 2.80
	2.80 - 3.50
	3.50 - 4.20
	4.20 - 4.90

Maximum Density	4.73%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	1986 (1986 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -51/109
Traverse: N/A
Borehole: UW82

Processed by: VR
Date: 22/05/2017
Defect type: Bedding/Contact
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	31
•	CN	4

Plot Mode	Pole Vectors
Vector Count	35 (35 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
□	BG	31
•	CN	4

Color	Density Concentrations
	0.00 - 4.30
	4.30 - 8.60
	8.60 - 12.90
	12.90 - 17.20
	17.20 - 21.50
	21.50 - 25.80
	25.80 - 30.10

Maximum Density	29.44%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	35 (35 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -51/109
Traverse: N/A
Borehole: UW82

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
◊	Breccia	10
■	SH	39

Plot Mode	Pole Vectors
Vector Count	49 (49 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
◊	Breccia	10
■	SH	39

Color	Density Concentrations
	0.00 - 1.10
	1.10 - 2.20
	2.20 - 3.30
	3.30 - 4.40
	4.40 - 5.50
	5.50 - 6.60
	6.60 - 7.70

Maximum Density	7.17%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	49 (49 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -51/109
Traverse: N/A
Borehole: UW82

Processed by: VR
Date: 22/05/2017
Defect type: Joints
Stratigraphy: N/A



Symbol	TYPE	Quantity
▲	JT	316
Plot Mode		Pole Vectors
Vector Count		316 (316 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
▲	JT	316
Color		Density Concentrations
		0.00 - 1.10
		1.10 - 2.20
		2.20 - 3.30
		3.30 - 4.40
		4.40 - 5.50
		5.50 - 6.60
		6.60 - 7.70
Maximum Density		7.21%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		316 (316 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -51/109
Traverse: N/A
Borehole: UW82

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	VN	1586
Plot Mode Pole Vectors		
Vector Count 1586 (1586 Entries)		
Hemisphere Lower		
Projection Equal Area		




Symbol	TYPE	Quantity
•	VN	1586
Color		
Density Concentrations		
0.00 - 0.90		
0.90 - 1.80		
1.80 - 2.70		
2.70 - 3.60		
3.60 - 4.50		
4.50 - 5.40		
5.40 - 6.30		
Maximum Density 5.62%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 1586 (1586 Entries)		
Hemisphere Lower		
Projection Equal Area		

**PSM125
ORI CORE
BOREHOLE**

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -48/111
Traverse: N/A
Borehole: UW148

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
●	CN	5
◆	FT	5
▲	JT	64
■	VN	41

Plot Mode	Pole Vectors
Vector Count	115 (115 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
●	CN	5
◆	FT	5
▲	JT	64
■	VN	41

Color	Density Concentrations
	0.00 - 1.20
	1.20 - 2.40
	2.40 - 3.60
	3.60 - 4.80
	4.80 - 6.00
	6.00 - 7.20
	7.20 - 8.40

Maximum Density	7.92%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%
Plot Mode	Pole Vectors
Vector Count	115 (115 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -48/111
Traverse: N/A
Borehole: UW148

Processed by: VR
Date: 22/05/2017
Defect type: Bedding/Contact
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	CN	5
Plot Mode		Pole Vectors
Vector Count		5 (5 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
•	CN	5
Color		Density Concentrations
		0.00 - 4.90
		4.90 - 9.80
		9.80 - 14.70
		14.70 - 19.60
		19.60 - 24.50
		24.50 - 29.40
		29.40 - 34.30
Maximum Density		34.13%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		5 (5 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -48/111
Traverse: N/A
Borehole: UW148

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	FT	5
Plot Mode Pole Vectors		
Vector Count 5 (5 Entries)		
Hemisphere Lower		
Projection Equal Area		



Symbol	TYPE	Quantity
•	FT	5
Color		
Density Concentrations		
0.00 - 5.60		
5.60 - 11.20		
11.20 - 16.80		
16.80 - 22.40		
22.40 - 28.00		
28.00 - 33.60		
33.60 - 39.20		
Maximum Density 38.67%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 5 (5 Entries)		
Hemisphere Lower		
Projection Equal Area		




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -48/111
Traverse: N/A
Borehole: UW148

Processed by: VR
Date: 22/05/2017
Defect type: Joints
Stratigraphy: N/A



Symbol	TYPE	Quantity
▲	JT	64
Plot Mode		Pole Vectors
Vector Count		64 (64 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
▲	JT	64
Color		Density Concentrations
		0.00 - 1.60
		1.60 - 3.20
		3.20 - 4.80
		4.80 - 6.40
		6.40 - 8.00
		8.00 - 9.60
		9.60 - 11.20
Maximum Density		10.65%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		64 (64 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -48/111
Traverse: N/A
Borehole: UW148

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	VN	41
Plot Mode		Pole Vectors
Vector Count		41 (41 Entries)
Hemisphere		Lower
Projection		Equal Area




Symbol	TYPE	Quantity
•	VN	41
Color		Density Concentrations
		0.00 - 1.60
		1.60 - 3.20
		3.20 - 4.80
		4.80 - 6.40
		6.40 - 8.00
		8.00 - 9.60
		9.60 - 11.20
Maximum Density		10.63%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		41 (41 Entries)
Hemisphere		Lower
Projection		Equal Area

**PSM125
ORI CORE
BOREHOLE**

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -43/276
Traverse: N/A
Borehole: UW175

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	1
×	Breccia	2
●	CN	1
★	FT	2
▲	JT	120
■	SH	1
●	VN	218

Plot Mode	Pole Vectors
Vector Count	345 (345 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
□	BG	1
×	Breccia	2
●	CN	1
★	FT	2
▲	JT	120
■	SH	1
●	VN	218

Color	Density Concentrations
	0.00 - 0.90
	0.90 - 1.80
	1.80 - 2.70
	2.70 - 3.60
	3.60 - 4.50
	4.50 - 5.40
	5.40 - 6.30

Maximum Density	6.09%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	345 (345 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -43/276
Traverse: N/A
Borehole: UW175

Processed by: VR
Date: 22/05/2017
Defect type: Bedding/Contact
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	1
•	CN	1
Plot Mode Pole Vectors		
Vector Count 2 (2 Entries)		
Hemisphere Lower		
Projection Equal Area		



Symbol	TYPE	Quantity
□	BG	1
•	CN	1
Color		
Density Concentrations		
0.00 - 7.20		
7.20 - 14.40		
14.40 - 21.60		
21.60 - 28.80		
28.80 - 36.00		
36.00 - 43.20		
43.20 - 50.40		
Maximum Density 49.79%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 2 (2 Entries)		
Hemisphere Lower		
Projection Equal Area		




PSM125
ORI CORE
BOREHOLE

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -43/276
Traverse: N/A
Borehole: UW175

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
◊	Breccia	2
•	FT	2
■	SH	1

Plot Mode	Pole Vectors
Vector Count	5 (5 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
◊	Breccia	2
•	FT	2
■	SH	1

Color	Density Concentrations
	0.00 - 2.90
	2.90 - 5.80
	5.80 - 8.70
	8.70 - 11.60
	11.60 - 14.50
	14.50 - 17.40
	17.40 - 20.30

Maximum Density	19.77%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%


Plot Mode	Pole Vectors
Vector Count	5 (5 Entries)
Hemisphere	Lower
Projection	Equal Area

**PSM125
ORI CORE
BOREHOLE**


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -43/276
Traverse: N/A
Borehole: UW175

Processed by: VR
Date: 22/05/2017
Defect type: Joints
Stratigraphy: N/A



Symbol	TYPE	Quantity
▲	JT	120
Plot Mode		Pole Vectors
Vector Count		120 (120 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
▲	JT	120
Color	Density Concentrations	
	0.00	- 1.10
	1.10	- 2.20
	2.20	- 3.30
	3.30	- 4.40
	4.40	- 5.50
	5.50	- 6.60
	6.60	- 7.70
Maximum Density		7.25%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		120 (120 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -43/276
Traverse: N/A
Borehole: UW175

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
●	VN	218
Plot Mode Pole Vectors		
Vector Count 218 (218 Entries)		
Hemisphere Lower		
Projection Equal Area		




Symbol	TYPE	Quantity
●	VN	218
Color		
Density Concentrations		
0.00 - 1.00		
1.00 - 2.00		
2.00 - 3.00		
3.00 - 4.00		
4.00 - 5.00		
5.00 - 6.00		
6.00 - 7.00		
Maximum Density 6.38%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 218 (218 Entries)		
Hemisphere Lower		
Projection Equal Area		

**PSM125
ORI CORE
BOREHOLE**

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -44/303
Traverse: N/A
Borehole: UW180

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	26
●	CN	10
×	CZ	2
★	FT	7
▲	JT	26
●	VN	101

Plot Mode	Pole Vectors
Vector Count	172 (172 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
□	BG	26
●	CN	10
×	CZ	2
★	FT	7
▲	JT	26
●	VN	101

Color	Density Concentrations
	0.00 - 1.20
	1.20 - 2.40
	2.40 - 3.60
	3.60 - 4.80
	4.80 - 6.00
	6.00 - 7.20
	7.20 - 8.40
Maximum Density	8.00%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	172 (172 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -44/303
Traverse: N/A
Borehole: UW180

Processed by: VR
Date: 22/05/2017
Defect type: Bedding/Contact
Stratigraphy: N/A



Symbol	TYPE	Quantity
□	BG	26
●	CN	10
Plot Mode		
Pole Vectors		
Vector Count		
36 (36 Entries)		
Hemisphere		
Lower		
Projection		
Equal Area		



Symbol	TYPE	Quantity
□	BG	26
●	CN	10
Color		
Density Concentrations		
0.00 - 2.00		
2.00 - 4.00		
4.00 - 6.00		
6.00 - 8.00		
8.00 - 10.00		
10.00 - 12.00		
12.00 - 14.00		
Maximum Density		
13.72%		
Contour Data		
Pole Vectors		
Contour Distribution		
Fisher		
Counting Circle Size		
1.0%		
Plot Mode		
Pole Vectors		
Vector Count		
36 (36 Entries)		
Hemisphere		
Lower		
Projection		
Equal Area		




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -44/303
Traverse: N/A
Borehole: UW180

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
×	CZ	2
•	FT	7
Plot Mode		Pole Vectors
Vector Count		9 (9 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
×	CZ	2
•	FT	7
Color		Density Concentrations
		0.00 - 3.10
		3.10 - 6.20
		6.20 - 9.30
		9.30 - 12.40
		12.40 - 15.50
		15.50 - 18.60
		18.60 - 21.70
Maximum Density		21.00%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		9 (9 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -44/303
Traverse: N/A
Borehole: UW180

Processed by: VR
Date: 22/05/2017
Defect type: Joints
Stratigraphy: N/A



Symbol	TYPE	Quantity
▲	JT	26
Plot Mode		
Pole Vectors		
Vector Count		
26 (26 Entries)		
Hemisphere		
Lower		
Projection		
Equal Area		



Symbol	TYPE	Quantity
▲	JT	26
Color		
Density Concentrations		
0.00 - 1.90		
1.90 - 3.80		
3.80 - 5.70		
5.70 - 7.60		
7.60 - 9.50		
9.50 - 11.40		
11.40 - 13.30		
Maximum Density		
13.30%		
Contour Data		
Pole Vectors		
Contour Distribution		
Fisher		
Counting Circle Size		
1.0%		
Plot Mode		
Pole Vectors		
Vector Count		
26 (26 Entries)		
Hemisphere		
Lower		
Projection		
Equal Area		




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -44/303
Traverse: N/A
Borehole: UW180

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	VN	101
Plot Mode Pole Vectors		
Vector Count 101 (101 Entries)		
Hemisphere Lower		
Projection Equal Area		



Symbol	TYPE	Quantity
•	VN	101
Color		
		
Density Concentrations		
0.00 - 1.30		
1.30 - 2.60		
2.60 - 3.90		
3.90 - 5.20		
5.20 - 6.50		
6.50 - 7.80		
7.80 - 9.10		
Maximum Density 8.87%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 101 (101 Entries)		
Hemisphere Lower		
Projection Equal Area		




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -42/276
Traverse: N/A
Borehole: UW184

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	FT	1
•	VN	92
Plot Mode		Pole Vectors
Vector Count		93 (93 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
•	FT	1
•	VN	92
Color	Density Concentrations	
	0.00	- 1.20
	1.20	- 2.40
	2.40	- 3.60
	3.60	- 4.80
	4.80	- 6.00
	6.00	- 7.20
	7.20	- 8.40
Maximum Density		8.15%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		93 (93 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -42/276
Traverse: N/A
Borehole: UW184

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	FT	1
Plot Mode		Pole Vectors
Vector Count		1 (1 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
•	FT	1
Color		Density Concentrations
		0.00 - 14.20
		14.20 - 28.40
		28.40 - 42.60
		42.60 - 56.80
		56.80 - 71.00
		71.00 - 85.20
		85.20 - 99.40
Maximum Density		99.16%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		1 (1 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -42/276
Traverse: N/A
Borehole: UW184

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	VN	92
Plot Mode Pole Vectors		
Vector Count 92 (92 Entries)		
Hemisphere Lower		
Projection Equal Area		



Symbol	TYPE	Quantity
•	VN	92
Color		
Density Concentrations		
0.00 - 1.20		
1.20 - 2.40		
2.40 - 3.60		
3.60 - 4.80		
4.80 - 6.00		
6.00 - 7.20		
7.20 - 8.40		
Maximum Density 8.24%		
Contour Data Pole Vectors		
Contour Distribution Fisher		
Counting Circle Size 1.0%		
Plot Mode Pole Vectors		
Vector Count 92 (92 Entries)		
Hemisphere Lower		
Projection Equal Area		




PSM125
ORI CORE
BOREHOLE

Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All


North datum: Grid North
Dip/Azi: -47/290
Traverse: N/A
Borehole: UW540

Processed by: VR
Date: 22/05/2017
Defect type: All defects
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	FT	3
•	VN	55

Plot Mode	Pole Vectors
Vector Count	58 (58 Entries)
Hemisphere	Lower
Projection	Equal Area



Symbol	TYPE	Quantity
•	FT	3
•	VN	55

Color	Density Concentrations
	0.00 - 1.10
	1.10 - 2.20
	2.20 - 3.30
	3.30 - 4.40
	4.40 - 5.50
	5.50 - 6.60
	6.60 - 7.70

Maximum Density	7.41%
Contour Data	Pole Vectors
Contour Distribution	Fisher
Counting Circle Size	1.0%

Plot Mode	Pole Vectors
Vector Count	58 (58 Entries)
Hemisphere	Lower
Projection	Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -47/290
Traverse: N/A
Borehole: UW540

Processed by: VR
Date: 22/05/2017
Defect type: Faults/Shears
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	FT	3
Plot Mode		Pole Vectors
Vector Count		3 (3 Entries)
Hemisphere		Lower
Projection		Equal Area



Symbol	TYPE	Quantity
•	FT	3
Color		Density Concentrations
		0.00 - 4.80
		4.80 - 9.60
		9.60 - 14.40
		14.40 - 19.20
		19.20 - 24.00
		24.00 - 28.80
		28.80 - 33.60
Maximum Density		33.21%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		3 (3 Entries)
Hemisphere		Lower
Projection		Equal Area




PSM125
ORI CORE
BOREHOLE


Project: Project Pye
Job no: PSM125
Location: Gladstone
Lithology: All

North datum: Grid North
Dip/Azi: -47/290
Traverse: N/A
Borehole: UW540

Processed by: VR
Date: 22/05/2017
Defect type: Veins
Stratigraphy: N/A



Symbol	TYPE	Quantity
•	VN	55
Plot Mode		Pole Vectors
Vector Count		55 (55 Entries)
Hemisphere		Lower
Projection		Equal Area




Symbol	TYPE	Quantity
•	VN	55
Color		Density Concentrations
		0.00 - 1.20
		1.20 - 2.40
		2.40 - 3.60
		3.60 - 4.80
		4.80 - 6.00
		6.00 - 7.20
		7.20 - 8.40
Maximum Density		7.81%
Contour Data		Pole Vectors
Contour Distribution		Fisher
Counting Circle Size		1.0%
Plot Mode		Pole Vectors
Vector Count		55 (55 Entries)
Hemisphere		Lower
Projection		Equal Area

Appendix D

Hydrographs



Groundwater levels P60 and Cumulative Excess Rainfall




Notes: 1) Daily rainfall data from Mill Station



Pells Sullivan Meynink Pty Ltd

Anderson Lloyd	
OceanaGold Project Pye	
Waihi, New Zealand	
DIPPED PIEZOMETER WATER LEVELS	
P60	
PSM125-260R	Appendix D

Groundwater levels P60 and Daily Rainfall




Notes: 1) Daily rainfall data from Mill Station



Pells Sullivan Meynink Pty Ltd

Anderson Lloyd	
OceanaGold Project Pye	
Waihi, New Zealand	
DIPPED PIEZOMETER WATER LEVELS	
P60	
PSM125-260R	Appendix D

Groundwater levels P61 and Cumulative Excess Rainfall




Notes: 1) Daily rainfall data from Mill Station



Pells Sullivan Meynink Pty Ltd

Anderson Lloyd	
OceanaGold Project Pye	
Waihi, New Zealand	
DIPPED PIEZOMETER WATER LEVELS	
P61	
PSM125-260R	Appendix D

Groundwater levels P61 and Daily Rainfall




Notes: 1) Daily rainfall data from Mill Station



Pells Sullivan Meynink Pty Ltd

Anderson Lloyd	
OceanaGold Project Pye	
Waihi, New Zealand	
DIPPED PIEZOMETER WATER LEVELS	
P61	
PSM125-260R	Appendix D

Groundwater levels P75 and Cumulative Excess Rainfall




Notes: 1) Daily rainfall data from Mill Station



Pells Sullivan Meynink Pty Ltd

Anderson Lloyd	
OceanaGold Project Pye	
Waihi, New Zealand	
DIPPED PIEZOMETER WATER LEVELS	
P75	
PSM125-260R	Appendix D

Groundwater levels P75 and Daily Rainfall




Notes: 1) Daily rainfall data from Mill Station



Pells Sullivan Meynink Pty Ltd

Anderson Lloyd	
OceanaGold Project Pye	
Waihi, New Zealand	
DIPPED PIEZOMETER WATER LEVELS	
P75	
PSM125-260R	Appendix D

Groundwater levels P79 and Cumulative Excess Rainfall




Notes: 1) Daily rainfall data from Mill Station



Pells Sullivan Meynink Pty Ltd

Anderson Lloyd OceanaGold Project Pye Waihi, New Zealand DIPPED PIEZOMETER WATER LEVELS P79	
PSM125-260R	Appendix D

Groundwater levels P79 and Daily Rainfall



Notes: 1) Daily rainfall data from Mill Station



Pells Sullivan Meynink Pty Ltd



Anderson Lloyd	
OceanaGold Project Pye	
Waihi, New Zealand	
DIPPED PIEZOMETER WATER LEVELS	
P79	
PSM125-260R	Appendix D

Appendix E

OCG Aquifer





Waihi Stratigraphy: Upper & Lower Aquifer Sequence

ASH 	<table> <thead> <tr> <th>DESCRIPTION</th><th>THICKNESS (approx)</th></tr> </thead> <tbody> <tr> <td>Yellow-brown, crumbly, unconsolidated or weakly consolidated soil. The volcanic ash component of the soil gives it a gritty texture. The ash soil grades downwards to a heavier clay-rich soil.</td><td>0-10m</td></tr> <tr> <td>Soft pale coloured clays OR grey to brown silt, sand & clay, black or grey mud and peat, grading downwards into a pebble-cobble-boulder gravel.</td><td>0-20m</td></tr> </tbody> </table>	DESCRIPTION	THICKNESS (approx)	Yellow-brown, crumbly, unconsolidated or weakly consolidated soil. The volcanic ash component of the soil gives it a gritty texture. The ash soil grades downwards to a heavier clay-rich soil.	0-10m	Soft pale coloured clays OR grey to brown silt, sand & clay, black or grey mud and peat, grading downwards into a pebble-cobble-boulder gravel.	0-20m
DESCRIPTION	THICKNESS (approx)						
Yellow-brown, crumbly, unconsolidated or weakly consolidated soil. The volcanic ash component of the soil gives it a gritty texture. The ash soil grades downwards to a heavier clay-rich soil.	0-10m						
Soft pale coloured clays OR grey to brown silt, sand & clay, black or grey mud and peat, grading downwards into a pebble-cobble-boulder gravel.	0-20m						
CLAYS & LAKE SEDIMENTS 	UPPER AQUIFER						
WELDED IGNIMBRITE 	<table> <tbody> <tr> <td>Light to mid grey extremely hard ignimbrite. Contains small white flattened pumice fragments. Grades downwards into sandy ignimbrite. Planar fractures.</td><td>0-30m</td></tr> </tbody> </table>	Light to mid grey extremely hard ignimbrite. Contains small white flattened pumice fragments. Grades downwards into sandy ignimbrite. Planar fractures.	0-30m				
Light to mid grey extremely hard ignimbrite. Contains small white flattened pumice fragments. Grades downwards into sandy ignimbrite. Planar fractures.	0-30m						
SANDY IGNIMBRITE 	<table> <tbody> <tr> <td>Pale brown, grey or dark brown, sandy ignimbrite, moderately soft to very soft, crumbly or may occur as loose running sand.</td><td>0-30m</td></tr> </tbody> </table>	Pale brown, grey or dark brown, sandy ignimbrite, moderately soft to very soft, crumbly or may occur as loose running sand.	0-30m				
Pale brown, grey or dark brown, sandy ignimbrite, moderately soft to very soft, crumbly or may occur as loose running sand.	0-30m						
PUMICEOUS IGNIMBRITE 	<table> <tbody> <tr> <td>Pale orange to grey ignimbrite, varies from soft to moderately hard, contains pumice fragments up to 30 mm diameter and small dark-coloured rock fragments generally less than 10mm diameter. Very small, highly reflective glass fragments can sometimes be observed in the matrix of the rock and are a good indicator of the upper aquifer sequence.</td><td>0-100m</td></tr> </tbody> </table>	Pale orange to grey ignimbrite, varies from soft to moderately hard, contains pumice fragments up to 30 mm diameter and small dark-coloured rock fragments generally less than 10mm diameter. Very small, highly reflective glass fragments can sometimes be observed in the matrix of the rock and are a good indicator of the upper aquifer sequence.	0-100m				
Pale orange to grey ignimbrite, varies from soft to moderately hard, contains pumice fragments up to 30 mm diameter and small dark-coloured rock fragments generally less than 10mm diameter. Very small, highly reflective glass fragments can sometimes be observed in the matrix of the rock and are a good indicator of the upper aquifer sequence.	0-100m						
ALLUVIUM 	<table> <tbody> <tr> <td>Gravel horizons - there are several boulder beds within and at the base of the upper aquifer, containing rounded pebbles of dark greenish-grey andesite and occasional quartz in a pale coloured silty matrix. Orange-brown iron-oxide staining is common.</td><td>0-10m</td></tr> </tbody> </table>	Gravel horizons - there are several boulder beds within and at the base of the upper aquifer, containing rounded pebbles of dark greenish-grey andesite and occasional quartz in a pale coloured silty matrix. Orange-brown iron-oxide staining is common.	0-10m				
Gravel horizons - there are several boulder beds within and at the base of the upper aquifer, containing rounded pebbles of dark greenish-grey andesite and occasional quartz in a pale coloured silty matrix. Orange-brown iron-oxide staining is common.	0-10m						
DACITE 	<table> <tbody> <tr> <td>Dacite lava (in the Black Hill area). Light grey-green, often with black (manganese oxide) or orange-brown (iron-oxide) coatings on fractures. Weathered and moderately soft to a depth of approx 50m below surface, otherwise hard. The dacite can be distinguished from andesite lavas in the lower aquifer by the complete absence of fine brassy-coloured pyrite.</td><td>0-250m</td></tr> </tbody> </table>	Dacite lava (in the Black Hill area). Light grey-green, often with black (manganese oxide) or orange-brown (iron-oxide) coatings on fractures. Weathered and moderately soft to a depth of approx 50m below surface, otherwise hard. The dacite can be distinguished from andesite lavas in the lower aquifer by the complete absence of fine brassy-coloured pyrite.	0-250m				
Dacite lava (in the Black Hill area). Light grey-green, often with black (manganese oxide) or orange-brown (iron-oxide) coatings on fractures. Weathered and moderately soft to a depth of approx 50m below surface, otherwise hard. The dacite can be distinguished from andesite lavas in the lower aquifer by the complete absence of fine brassy-coloured pyrite.	0-250m						
CONTACT ZONE 	LOWER AQUIFER						
ANDESITE 	<table> <tbody> <tr> <td>The contact between upper and lower aquifers is commonly marked by the transition from gravel boulder beds or dacite (above) to several metres of iron-stained, clay-rich weathered andesite rock. The iron staining is caused by the oxidation of pyrite, which is an iron sulphide mineral that occurs throughout the lower aquifer. Thickness varies from 0.5m to 30m.</td><td></td></tr> <tr> <td>The lower aquifer occurs within andesite lavas and breccias. The andesites can vary in hardness from very soft to very hard. Colour and appearance vary depending on the extent of hydrothermal clay alteration, but they are generally grey or greenish-grey. They can be distinguished from volcanic rocks of the upper aquifer by the presence of fine-grained pyrite throughout the rock mass. Pyrite has a silvery or brassy metallic appearance and gives an overall grey colour to the rock. The presence of quartz and calcite veins is also characteristic of the lower aquifer sequence.</td><td></td></tr> </tbody> </table>	The contact between upper and lower aquifers is commonly marked by the transition from gravel boulder beds or dacite (above) to several metres of iron-stained, clay-rich weathered andesite rock. The iron staining is caused by the oxidation of pyrite, which is an iron sulphide mineral that occurs throughout the lower aquifer. Thickness varies from 0.5m to 30m.		The lower aquifer occurs within andesite lavas and breccias. The andesites can vary in hardness from very soft to very hard. Colour and appearance vary depending on the extent of hydrothermal clay alteration, but they are generally grey or greenish-grey. They can be distinguished from volcanic rocks of the upper aquifer by the presence of fine-grained pyrite throughout the rock mass. Pyrite has a silvery or brassy metallic appearance and gives an overall grey colour to the rock. The presence of quartz and calcite veins is also characteristic of the lower aquifer sequence.			
The contact between upper and lower aquifers is commonly marked by the transition from gravel boulder beds or dacite (above) to several metres of iron-stained, clay-rich weathered andesite rock. The iron staining is caused by the oxidation of pyrite, which is an iron sulphide mineral that occurs throughout the lower aquifer. Thickness varies from 0.5m to 30m.							
The lower aquifer occurs within andesite lavas and breccias. The andesites can vary in hardness from very soft to very hard. Colour and appearance vary depending on the extent of hydrothermal clay alteration, but they are generally grey or greenish-grey. They can be distinguished from volcanic rocks of the upper aquifer by the presence of fine-grained pyrite throughout the rock mass. Pyrite has a silvery or brassy metallic appearance and gives an overall grey colour to the rock. The presence of quartz and calcite veins is also characteristic of the lower aquifer sequence.							

Appendix F

Old Sections





Pells Sullivan Meynink

Anderson Lloyd
OceanaGold Project Pye
Favona & Gladstone Pits

GLADSTONE PIT
SECTION LOCATIONS

PSM 125-260R

Figure D

RL1150m

RL1100m

RL1050m

RL1000m

RL950m

RT

UW21
UW23

RT

HBX


UW74

Andesite

Andesite

Andesite

UW77




Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits

GLADSTONE PIT
SECTION A

PSM 125-260R

Figure D1



0 10 20 30 40 50
Scale(m)




Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits


GLADSTONE PIT
SECTION B

PSM 125-260R

Figure D2




Litho	Major Defect	Hardness					Weathering	
		1	2	3	4	5	SW	FW
0-10								
10-20								
20-30								
30-40								
40-50								
50-60								
60-70								
70-80								
80-90								
90-100								
100-110								
110-120								
120-130								
130-140								
140-150								
150-160								
160-170								
170-180								
180-190								
190-200								



Pells Sullivan Meynink

OceanaGold Preliminary Geotechnical Study Favona & Gladstone Pits	
GLADSTONE PIT SECTION C	
PSM 125-260R	Figure D3



0 10 20 30 40 50
Scale(m)





Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits
GLADSTONE PIT
SECTION D

PSM 125-260R

Figure D4




Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits

GLADSTONE PIT
SECTION E

PSM 125-260R

Figure D5



1200mRL

1150mRL

1100mRL

1050mRL

1000mRL

HBX

RT

UW24

UW10

HBX

UW500

UW329


RT

Dacite

HBX

Andesite

Andesite



Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits

GLADSTONE PIT
SECTION H

PSM 125-260R

Figure D8



1200mRL

1150mRL

1100mRL

1050mRL

1000mRL





Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits
GLADSTONE PIT
SECTION I

PSM 125-260R

Figure D9




Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits

GLADSTONE PIT
SECTION J

PSM 125-260R

Figure D10



0 10 20 30 40 50
Scale(m)




Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits

GLADSTONE PIT
SECTION K

PSM 125-260R

Figure D11



0 10 20 30 40 50
Scale(m)



Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits

GLADSTONE PIT
SECTION M

PSM 125-260R

Figure D13

1150mRL

1100mRL

1050mRL

1000mRL

950mRL

P82



UW60

HBX

UW51

UW40

RT

UW510

UW357

UW359

RT

HBX

Dacite

Volcaniclastic

HBX

Andesite

Andesite

0 10 20 30 40 50
Scale(m)



Pells Sullivan Meynink

OceanaGold
Preliminary Geotechnical Study
Favona & Gladstone Pits

GLADSTONE PIT
SECTION N

PSM 125-260R

Figure D14

Appendix G

Histograms





Pells Sullivan Meynink

Engineering Consultants
Rock - Soil - Water







Geotechnical Database Borehole Data Histograms

Job Number: PSM125
Project: Project Quattro - Geotechnical Boreholes






Produced by: AGI
Date: 11-Jul-17

Rock Mass Unit: Ignimbrite
Stratigraphy: N/A
Borehole: Multiple holes
Length of Core: 86.7m

Defect types: Multiple Types
No defects: 93



Mean Axial = 0.62
Mean Diam = 0.30
Numb = 6
Numb = 6











Pells Sullivan Meynink






Engineering Consultants
Rock - Soil - Water

Geotechnical Database Borehole Data Histograms

Job Number:	PSM125	Produced by:	AGI
Project:	Project Quattro - Geotechnical Boreholes	Date:	11-Jul-17
Rock Mass Unit:	Dacite	Borehole:	Multiple holes
Stratigraphy:	N/A	Length of Core:	19.3m
		Defect types:	Multiple Types
		No defects:	56



Mean Axial = 0.52 Numb = 6
Mean Diam = 0.25 Numb = 3











Pells Sullivan Meynink

Engineering Consultants
Rock - Soil - Water

Geotechnical Database Borehole Data Histograms






Job Number:	PSM125	Produced by:	AGI
Project:	Project Quattro - Geotechnical Boreholes	Date:	11-Jul-17
Rock Mass Unit:	Volcaniclastic	Borehole:	Multiple holes
Stratigraphy:	N/A	Length of Core:	9.45m
		Defect types:	Multiple Types
		No defects:	6



Mean Axial =
Mean Diam =

Numb=
Numb=

Mean=
Numb=











Pells Sullivan Meynink






Engineering Consultants
Rock - Soil - Water

Geotechnical Database Borehole Data Histograms

Job Number:	PSM125	Produced by:	AGI
Project:	Project Quattro - Geotechnical Boreholes	Date:	11-Jul-17
Rock Mass Unit:	Class 4	Borehole:	Multiple holes
Stratigraphy:	N/A	Length of Core:	132.73m
		Defect types:	Multiple Types
		No defects:	311



Mean Axial = 0.18 Numb = 22
Mean Diam = 0.07 Numb = 17











Pells Sullivan Meynink

Engineering Consultants
Rock - Soil - Water






Geotechnical Database Borehole Data Histograms

Job Number:	PSM125	Produced by:	AGI
Project:	Project Quattro - Geotechnical Boreholes	Date:	11-Jul-17
Rock Mass Unit:	Class 3	Borehole:	Multiple holes
Stratigraphy:	N/A	Length of Core:	251.42m
		Defect types:	Multiple Types
		No defects:	953



Mean Axial = 0.86 Numb= 65
Mean Diam = 0.79 Numb= 51

Mean= #####
Numb=











Pells Sullivan Meynink






Engineering Consultants
Rock - Soil - Water

Geotechnical Database Borehole Data Histograms

Job Number:	PSM125	Produced by:	AGI
Project:	Project Quattro - Geotechnical Boreholes	Date:	11-Jul-17
Rock Mass Unit:	Class 2	Borehole:	Multiple holes
Stratigraphy:	N/A	Length of Core:	349.75m
		Defect types:	Multiple Types
		No defects:	1186



Mean Axial = 0.89 Numb= 80
Mean Diam = 0.87 Numb= 70



Appendix H

RMZ Sheets Updated




RHYOLITIC TUFF/IGNIMBRITE

Typical Rock Mass Photographs



Shear Strength Estimate



Intact Strength Estimate

Non-welded – S2 – S5, Welded – R0 - R2

DACITE

Typical Rock Mass Photographs



GSI Estimate

Visual GSI Estimate = 30 - 45


		SURFACE CONDITIONS				
		VERY GOOD	GOOD	FAIR	POOR	VERY POOR
STRUCTURE		DECREASING SURFACE QUALITY →				
     	INTACT OR MASSIVE - intact rock specimens or massive in situ rock with few widely spaced discontinuities	90	80		N/A	N/A
	BLOCKY - well interlocked undisturbed rock mass consisting of cubical blocks formed by three intersecting discontinuity sets		70	60		
	VERY BLOCKY- interlocked, partially disturbed mass with multi-faceted angular blocks formed by 4 or more joint sets			50		
	BLOCKY/DISTURBED/SEAMY - folded with angular blocks formed by many intersecting discontinuity sets. Persistence of bedding planes or schistosity			40		
	DISINTEGRATED - poorly interlocked, heavily broken rock mass with mixture of angular and rounded rock pieces				30	
	LAMINATED/SHEARED - Lack of blockiness due to close spacing of weak schistosity or shear planes					20
		N/A	N/A			10

Intact Strength Estimate


R1 – R3

VOLCANICLASTIC

Typical Rock Mass Photographs



Shear Strength Estimate



	Cohesion (kPa)	Friction Angle (deg)
Upper Bound	52	15
Lower Bound	26	15
Indicated Strength	39	15



Pells Sullivan Meynink

Anderson Lloyd
OceanaGold Project Quattro
Waihi, New Zealand

TRIAXIAL 'p' q' PLOT
VOLCANICLASTIC

PSM125

Appendix K

Intact Strength Estimate


S4 – S5

CLASS 4 ANDESITE AND BRECCIA

Typical Rock Mass Photographs



Shear Strength Estimate



Intact Strength Estimate

S5 – R1

CLASS 3 ANDESITE

Typical Rock Mass Photographs



GSI Estimate

Visual GSI Estimate = 20 - 35

		SURFACE CONDITIONS				
		VERY GOOD	GOOD	FAIR	POOR	VERY POOR
STRUCTURE		DECREASING SURFACE QUALITY →				
 INTACT OR MASSIVE - intact rock specimens or massive in situ rock with few widely spaced discontinuities	DECREASING INTERLOCKING OF ROCK PIECES  BLOCKY - well interlocked undisturbed rock mass consisting of cubical blocks formed by three intersecting discontinuity sets	90			N/A	N/A
		80				
			70			
			60			
				50		
				40		
 VERY BLOCKY - interlocked, partially disturbed mass with multi-faceted angular blocks formed by 4 or more joint sets	 BLOCKY/DISTURBED/SEAMY - folded with angular blocks formed by many intersecting discontinuity sets. Persistence of bedding planes or schistosity			30		
					20	
 DISINTEGRATED - poorly interlocked, heavily broken rock mass with mixture of angular and rounded rock pieces	 LAMINATED/SHEARED - Lack of blockiness due to close spacing of weak schistosity or shear planes					10
		N/A	N/A			

Intact Strength Estimate

R2 – R3

CLASS 2 ANDESITE

Typical Rock Mass Photographs



GSI Estimate

Visual GSI Estimate = 30 - 50

		SURFACE CONDITIONS				
		VERY GOOD	GOOD	FAIR	POOR	VERY POOR
STRUCTURE		DECREASING SURFACE QUALITY →				
	INTACT OR MASSIVE - intact rock specimens or massive in situ rock with few widely spaced discontinuities	90	80		N/A	N/A
	BLOCKY - well interlocked undisturbed rock mass consisting of cubical blocks formed by three intersecting discontinuity sets		70			
	VERY BLOCKY- interlocked, partially disturbed mass with multi-faceted angular blocks formed by 4 or more joint sets		60			
	BLOCKY/DISTURBED/SEAMY - folded with angular blocks formed by many intersecting discontinuity sets. Persistence of bedding planes or schistosity			50		
	DISINTEGRATED - poorly interlocked, heavily broken rock mass with mixture of angular and rounded rock pieces			40	30	
	LAMINATED/SHEARED - Lack of blockiness due to close spacing of weak schistosity or shear planes				20	10
		N/A	N/A			

Intact Strength Estimate

R3 – R4

Appendix I

Lab Testing





Our Ref: 1003796, 1003798

Customer Ref: PSM125

9 August 2017

Pells Sullivan Meynink
G3 56 Delhi Road
North Ryde
NSW 2113
AUSTRALIA

Attention: Adam Irvine

Dear Mr. Irvine

Waihi, NZ -- PSM125
Laboratory Test Report

Introduction

Geotechnics was engaged to carry out laboratory testing on samples from the above mentioned location.

Sampling Procedure

Samples have been tested as received from the customer.

Sample Location Plan

Not applicable.

Samples

Numerous core samples were received. All samples were labelled with sample ID and depth.

Date of Sample Receipt

30 June 2017

Customer's Instructions

The detailed testing instructions were provided via e-mail, dated from 3 July to 28 July 2017, from Mr. Irvine.

Test Method(s)

NZS 4402:1986 Test 6.3.1 Determination of the unconfined compressive strength of cohesive soil
BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS 1377:Part 8:1990 Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

Material Description

Sample descriptions are included in the presentation pages.

Test Results

Test results are attached on page 2 to page 51.

Test Remarks

Test remarks are detailed in the presentation pages.

General Remarks

Samples not destroyed during testing, will be retained for one month from the date of this report before being discarded.

Descriptions are enclosed for your information, are not covered under the IANZ endorsement of this report.

Please reproduce this report in full when transmitting to others or including in internal reports.

If we can be of any further assistance, feel free to get in touch. Contact details are provided at the bottom of the letterhead page.

GEOTECHNICS LTD

Report prepared by:

Helen Wang

.....
Helen Wang
Triaxial Laboratory Manager

Authorised for Geotechnics by:

.....
Steven Anderson
Project Director
Approved Signatory

Report checked by:

.....
Steven Anderson
Regional Manager
Approved Signatory



All tests reported
herein have been
performed in accordance
with the laboratory's
scope of accreditation

9-Aug-17

t:\geotechnicsgroup\projects\1003796\issueddocuments\20170809.yhw.rep1.docx



19 - 23 Morgan Street
Newmarket
Auckland 1023
New Zealand

p. +64 9 356 3510

Geotechnics Project ID 1003798.0000
Customer Project ID PSM 125


Determination of the unconfined compressive strength of cohesive soil - NZS 4402:1986 Test 6.3.1

Sample Details

Geotechnics Sample ID	---				
Site	Waihi, NZ				
BH No	GT011	Sample ID	GTO11-005	Depth (m)	79.58-79.77m
Sample Description Supplied by Client:	Weakly altered and fresh R2 Andesite				

Test Result

Unconfined Compressive Strength Test Axial Stress vs Strain



Sample Parameters

Sample Height (mm)	113.56	Bulk Density (t/m ³)	2.38
Sample Diameter (mm)	83.35	Dry Density (t/m ³)	2.22
Test Height (mm)	113.56	Water Content (%)	7.1
Test H/D Ratio	1.36		

Failure Value

Axial Strain (%)	Unconfined Compressive Strength q_u (kPa)	Rate of Compression (mm/min)	Modulus of Elasticity (MPa)
2.07	1282	0.24	117

Mode of Failure Shear

Sample History Undisturbed core trimmed at natural water content.

Test Remarks

The sample height to diameter ratio is less than the required 2. The strength may be lower, due to the height to diameter ratio.

Unconfined Compressive Strength reported to the nearest 1 kPa and provided as indicative only.

Modulus of Elasticity value reported based on the straight line portion of the curve and provided as indicative only.

Sample description, UCS and modulus of elasticity value reported are not IANZ accredited.

Entered by ST Date 9/08/2017 Checked by JK Date 9/08/2017



19 - 23 Morgan Street
Newmarket
Auckland 1023
New Zealand

p. +64 9 356 3510

Geotechnics Project ID

1003798.0000

Customer Project ID

PSM 125


Determination of the unconfined compressive strength of cohesive soil - NZS 4402:1986 Test 6.3.1

Sample Details

Geotechnics Sample ID	---				
Site	Waihi, NZ				
BH No	GTO13	Sample ID	GTO13-005	Depth (m)	68.80-69.00m
Sample Description Supplied by Client:	Moderately altered and slightly weathered R2 Andesite				

Test Result

Unconfined Compressive Strength Test Axial Stress vs Strain



Sample Parameters

Sample Height (mm)	110.33	Bulk Density (t/m ³)	2.03
Sample Diameter (mm)	83.77	Dry Density (t/m ³)	1.79
Test Height (mm)	110.33	Water Content (%)	13.6
Test H/D Ratio	1.32		

Failure Value

Axial Strain (%)	Unconfined Compressive Strength q_u (kPa)	Rate of Compression (mm/min)	Modulus of Elasticity (MPa)
1.22	1785	0.17	222

Mode of Failure

Shear

Sample History

Undisturbed core trimmed at natural water content.

Test Remarks

The sample height to diameter ratio is less than the required 2. The strength may be lower, due to the height to diameter ratio.

Unconfined Compressive Strength reported to the nearest 1 kPa and provided as indicative only.

Modulus of Elasticity value reported based on the straight line portion of the curve and provided as indicative only.

Sample description, UCS and modulus of elasticity value reported are not IANZ accredited.

Entered by ST

Date 9/08/2017

Checked by JK

Date 9/08/2017



19 - 23 Morgan Street
Newmarket
Auckland 1023
New Zealand

p. +64 9 356 3510

Geotechnics Project ID

1003798.0000

Customer Project ID

PSM 125


Determination of the unconfined compressive strength of cohesive soil - NZS 4402:1986 Test 6.3.1

Sample Details

Geotechnics Sample ID	---				
Site	Waihi, NZ				
BH No	GTO14	Sample ID	GTO14-007	Depth (m)	21.35-21.58m
Sample Description Supplied by Client:	Weakly altered and slightly to moderately weathered R2 Dacite				

Test Result

Unconfined Compressive Strength Test Axial Stress vs Strain



Sample Parameters

Sample Height (mm)	158.27	Bulk Density (t/m ³)	1.75
Sample Diameter (mm)	76.66	Dry Density (t/m ³)	1.20
Test Height (mm)	158.27	Water Content (%)	45.1
Test H/D Ratio	2.06		

Failure Value

Axial Strain (%)	Unconfined Compressive Strength q_u (kPa)	Rate of Compression (mm/min)	Modulus of Elasticity (MPa)
1.01	2199	0.26	364

Mode of Failure

Shear

Sample History

Undisturbed core trimmed at natural water content.

Test Remarks

Unconfined Compressive Strength reported to the nearest 1 kPa.

Modulus of Elasticity value reported based on the straight line portion of the curve and provided as indicative only.

Sample description and modulus of elasticity value reported are not IANZ accredited.

Entered by ST

Date 9/08/2017

Checked by JK

Date 9/08/2017



19 - 23 Morgan Street
Newmarket
Auckland 1023
New Zealand

p. +64 9 356 3510

Geotechnics Project ID 1003798.0000
Customer Project ID PSM 125


Determination of the unconfined compressive strength of cohesive soil - NZS 4402:1986 Test 6.3.1

Sample Details

Geotechnics Sample ID	---				
Site	Waihi, NZ				
BH No	GTO16	Sample ID	GTO16-013	Depth (m)	60.90-61.20m
Sample Description Supplied by Client:	Moderately altered and moderately weathered R2 andesite				

Test Result

Unconfined Compressive Strength Test Axial Stress vs Strain



Sample Parameters

Sample Height (mm)	168.68	Bulk Density (t/m ³)	2.30
Sample Diameter (mm)	82.43	Dry Density (t/m ³)	2.12
Test Height (mm)	168.68	Water Content (%)	8.6
Test H/D Ratio	2.05		

Failure Value

Axial Strain (%)	Unconfined Compressive Strength q_u (kPa)	Rate of Compression (mm/min)	Modulus of Elasticity (MPa)
1.30	1591	0.27	210

Mode of Failure Shear

Sample History Undisturbed core trimmed at natural water content.

Test Remarks

Unconfined Compressive Strength reported to the nearest 1 kPa.
Modulus of Elasticity value reported based on the straight line portion of the curve and provided as indicative only.
Sample description and modulus of elasticity value reported are not IANZ accredited.

Entered by ST Date 9/08/2017 Checked by JK Date 9/08/2017



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000

Location ID: GT011

Sample Ref.: GT011-002


Depth: 9.28 -- 9.50 (m)

Test method used: BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS1377:Part 8:1990:Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

CONSOLIDATED-UNDRAINED TRIAXIAL COMPRESSION TEST (3 STAGES) MOHR CIRCLES OF TOTAL AND EFFECTIVE STRESSES



Initial Sample Height:	164.68	mm	Initial Water Content:	15.4	%
Initial Sample Diameter:	81.78	mm	Initial Bulk Density:	2.23	t/m ³
Initial B Value:	--	%	Initial Dry Density:	1.93	t/m ³
B Value before Consolidation:	100	%	Final Water Content:	14.6	%

	Consolidation Stage			Failure Values				
	Cell Pressure (kPa)	Back Pressure (kPa)	Eff. Consol. Stress (kPa)	Deviator Stress (kPa)	Pore Pressure Change During Shearing $\delta\mu$ (kPa)	Effective Principal Stress (kPa)		Vertical Strain (%)
						Major σ_1'	Minor σ_3'	
STAGE 1	500	300	200	501.98	74.5	627.48	125.50	1.57
STAGE 2	800	300	500	963.30	171.2	1292.10	328.80	1.60
STAGE 3	1100	300	800	1382.59	215.6	1966.99	584.40	2.62

Angle of Frictional Resistance:	Total		Effective	
	$\phi =$	25 °	$\phi' =$	29 °
	Cohesion:	c = 68 kPa	c' =	84 kPa
Linear Regression Coefficient:	r =	1.000	r =	0.998

Sample History: Undisturbed core trimmed at natural water content.

Soil description: Gladstone, GT011-002, 9.28-9.50m, R1, Class 4 Andesite Breccia.

Failure Mode: Planar / Plastic

Test Speed: 0.015 (mm/min)

Test Remarks: The sample was saturated by increments of cell pressure and back pressure.

Failure for each stage was determined by either the maximum effective stress ratio or the maximum deviator stress. Strength parameters have been derived by using a linear regression fitting method.

Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT011

Sample Ref.: GT011-002


Depth: 9.28 -- 9.50 (m)

GRAPHS

STRESS PATH



PORE PRESSURE Vs VERTICAL STRAIN



Entered by: *[Signature]*

Date: 9/08/17

Checked by: *[Signature]*

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT011

Sample Ref.: GT011-002


Depth: 9.28 -- 9.50 (m)

STAGE 1 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT011

Sample Ref.: GT011-002


Depth: 9.28 -- 9.50 (m)

STAGE 2 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *[Signature]*

Date: 9/08/17

Checked by: *[Signature]*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT011

Sample Ref.: GT011-002


Depth: 9.28 -- 9.50 (m)

STAGE 3 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000

Location ID: GT012

Sample Ref.: GT012-003


Depth: 25.15 -- 25.35 (m)

Test method used: BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS1377:Part 8:1990:Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

CONSOLIDATED-UNDRAINED TRIAXIAL COMPRESSION TEST (3 STAGES) MOHR CIRCLES OF TOTAL AND EFFECTIVE STRESSES



Initial Sample Height:	170.02	mm	Initial Water Content:	15.3	%
Initial Sample Diameter:	82.85	mm	Initial Bulk Density:	2.23	t/m ³
Initial B Value:	18	%	Initial Dry Density:	1.94	t/m ³
B Value before Consolidation:	96	%	Final Water Content:	14.7	%

	Consolidation Stage			Failure Values				
	Cell Pressure (kPa)	Back Pressure (kPa)	Eff. Consol. Stress (kPa)	Deviator Stress (kPa)	Pore Pressure Change During Shearing $\delta\mu$ (kPa)	Effective Principal Stress (kPa)		Vertical Strain (%)
						Major σ_1'	Minor σ_3'	
STAGE 1	500	300	200	228.26	48.3	379.96	151.70	3.19
STAGE 2	800	300	500	498.01	119.9	878.11	380.10	3.34
STAGE 3	1100	300	800	771.78	178.5	1393.28	621.50	3.21

Angle of Frictional Resistance:	Total		Effective	
	$\phi =$	18 °	$\phi' =$	22 °
	Cohesion:	c = 17 kPa	c' =	19 kPa
Linear Regression Coefficient:	r =	1.000	r =	1.000

Sample History: Undisturbed core trimmed at natural water content.

Soil description: Gladstone, GT012-003, 25.15-25.35m, R0, Class 4 Andesite.

Failure Mode: Planar / Plastic

Test Speed: 0.018 (mm/min)

Test Remarks: The sample was saturated by increments of cell pressure and back pressure.
Failure for each stage was determined by the maximum effective stress ratio. Strength parameters have been derived by using a linear regression fitting method.

Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT012

Sample Ref.: GT012-003


Depth: 25.15 -- 25.35 (m)

GRAPHS

STRESS PATH



PORE PRESSURE Vs VERTICAL STRAIN



Entered by: *Y*

Date: 9/08/17

Checked by: *JAR*

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT012

Sample Ref.: GT012-003


Depth: 25.15 -- 25.35 (m)

STAGE 1 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT012

Sample Ref.: GT012-003


Depth: 25.15 -- 25.35 (m)

STAGE 2 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT012

Sample Ref.: GT012-003


Depth: 25.15 -- 25.35 (m)

STAGE 3 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000

Location ID: GT013

Sample Ref.: GT013-001


Depth: 38.83 -- 39.08 (m)

Test method used: BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS1377:Part 8:1990:Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

CONSOLIDATED-UNDRAINED TRIAXIAL COMPRESSION TEST (3 STAGES) MOHR CIRCLES OF TOTAL AND EFFECTIVE STRESSES



Initial Sample Height:	161.43	mm	Initial Water Content:	25.1	%
Initial Sample Diameter:	81.72	mm	Initial Bulk Density:	1.97	t/m ³
Initial B Value:	--	%	Initial Dry Density:	1.58	t/m ³
B Value before Consolidation:	98	%	Final Water Content:	25.7	%

	Consolidation Stage			Failure Values				
	Cell Pressure (kPa)	Back Pressure (kPa)	Eff. Consol. Stress (kPa)	Deviator Stress (kPa)	Pore Pressure Change During Shearing $\delta\mu$ (kPa)	Effective Principal Stress (kPa)		Vertical Strain (%)
						Major σ_1'	Minor σ_3'	
STAGE 1	500	300	200	419.07	89	530.07	111.00	0.40
STAGE 2	800	300	500	805.49	200.1	1105.39	299.90	0.30
STAGE 3	1100	300	800	1170.78	270.1	1700.68	529.90	0.28

Angle of Frictional Resistance:	Total		Effective	
	$\phi =$	23 °	$\phi' =$	28 °
	Cohesion:	c = 57 kPa	c' =	71 kPa
Linear Regression Coefficient:	r =	1.000	r =	0.999

Sample History: Undisturbed core trimmed at natural water content.

Soil description: Gladstone, GT013-001, 38.83-39.08m, R1, Class 4 Andesite.

Failure Mode: Planar / Plastic

Test Speed: 0.06 (mm/min)

Test Remarks: The sample was saturated by increments of cell pressure and back pressure.
Failure for each stage was determined by the maximum effective stress ratio. Strength parameters have been derived by using a linear regression fitting method.

Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT013

Sample Ref.: GT013-001


Depth: 38.83 -- 39.08 (m)

GRAPHS

STRESS PATH



PORE PRESSURE Vs VERTICAL STRAIN



Entered by: *Yan*

Date: 9/08/17

Checked by: *JAR*

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT013

Sample Ref.: GT013-001


Depth: 38.83 -- 39.08 (m)

STAGE 1 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *[Signature]*

Date: 9/08/17

Checked by: *[Signature]*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT013

Sample Ref.: GT013-001


Depth: 38.83 -- 39.08 (m)

STAGE 2 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *[Signature]*

Date: 9/08/17

Checked by: *[Signature]*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT013

Sample Ref.: GT013-001


Depth: 38.83 -- 39.08 (m)

STAGE 3 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000

Location ID: GT014

Sample Ref.: GT014-004


Depth: 28.15 -- 28.31 (m)

Test method used: BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS1377:Part 8:1990:Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

CONSOLIDATED-UNDRAINED TRIAXIAL COMPRESSION TEST (3 STAGES) MOHR CIRCLES OF TOTAL AND EFFECTIVE STRESSES



Initial Sample Height:	160.23	mm	Initial Water Content:	36.4	%
Initial Sample Diameter:	85.00	mm	Initial Bulk Density:	1.80	t/m ³
Initial B Value:	4	%	Initial Dry Density:	1.32	t/m ³
B Value before Consolidation:	90	%	Final Water Content:	38.9	%

	Consolidation Stage			Failure Values				
	Cell Pressure (kPa)	Back Pressure (kPa)	Eff. Consol. Stress (kPa)	Deviator Stress (kPa)	Pore Pressure Change During Shearing $\delta\mu$ (kPa)	Effective Principal Stress (kPa)		Vertical Strain (%)
						Major σ_1'	Minor σ_3'	
STAGE 1	550	350	200	177.58	98.7	278.88	101.30	6.59
STAGE 2	850	350	500	326.21	198.1	628.11	301.90	8.55
STAGE 3	1150	350	800	508.09	240.3	1067.79	559.70	5.32

	Total		Effective
Angle of Frictional Resistance:	$\phi = 12^\circ$		$\phi' = 15^\circ$
Cohesion:	$c = 25$ kPa		$c' = 40$ kPa
Linear Regression Coefficient:	$r = 0.998$		$r = 1.000$

Sample History: Undisturbed core trimmed at natural water content.

Soil description: Favona, GT014-004, 28.15-28.13m, S4, Volcaniclastic.

Failure Mode: Planar / Plastic

Test Speed: 0.02 (mm/min)

Test Remarks: The sample was saturated by increments of cell pressure and back pressure.
Failure for each stage was determined by the maximum Deviator stress. Strength parameters have been derived by using a linear regression fitting method.

Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT014

Sample Ref.: GT014-004


Depth: 28.15 -- 28.31 (m)

GRAPHS

STRESS PATH



PORE PRESSURE Vs VERTICAL STRAIN



Entered by: *[Signature]*

Date: 9/08/17

Checked by: *[Signature]*

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT014

Sample Ref.: GT014-004


Depth: 28.15 -- 28.31 (m)

STAGE 1 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT014

Sample Ref.: GT014-004


Depth: 28.15 -- 28.31 (m)

STAGE 2 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *[Signature]*

Date: 9/08/17

Checked by: *[Signature]*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT014

Sample Ref.: GT014-004


Depth: 28.15 -- 28.31 (m)

STAGE 3 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000

Location ID: GT014

Sample Ref.: GT014-011


Depth: 43.94 -- 44.15 (m)

Test method used: BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS1377:Part 8:1990:Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

CONSOLIDATED-UNDRAINED TRIAXIAL COMPRESSION TEST (3 STAGES) MOHR CIRCLES OF TOTAL AND EFFECTIVE STRESSES



Initial Sample Height:	123.60	mm	Initial Water Content:	16.5	%
Initial Sample Diameter:	60.01	mm	Initial Bulk Density:	2.06	t/m ³
Initial B Value:	26	%	Initial Dry Density:	1.77	t/m ³
B Value before Consolidation:	96	%	Final Water Content:	19.0	%

	Consolidation Stage			Failure Values				
	Cell Pressure (kPa)	Back Pressure (kPa)	Eff. Consol. Stress (kPa)	Deviator Stress (kPa)	Pore Pressure Change During Shearing $\delta\mu$ (kPa)	Effective Principal Stress (kPa)		Vertical Strain (%)
						Major σ_1'	Minor σ_3'	
STAGE 1	500	300	200	294.16	49	445.16	151.00	3.29
STAGE 2	800	300	500	522.95	100.6	922.35	399.40	2.69
STAGE 3	1100	300	800	735.24	117.7	1417.54	682.30	2.99

Angle of Frictional Resistance:	Total		Effective	
	$\phi =$	16 °	$\phi' =$	17 °
	Cohesion:	c = 57 kPa	c' =	65 kPa
Linear Regression Coefficient:	r =	1.000	r =	0.998

Sample History: Undisturbed core trimmed at natural water content.

Soil description: Favona, GT014-011, 43.94-44.15m, R1, Class 4 Andesite Breccia.

Failure Mode: Planar / Plastic

Test Speed: 0.012 (mm/min)

Test Remarks: The sample was saturated by increments of cell pressure and back pressure.
Failure for each stage was determined by either the maximum effective stress ratio or the maximum deviator stress. Strength parameters have been derived by using a linear regression fitting method.

Entered by: *Yan*

Date: 9/08/17

Checked by: *JAR*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT014

Sample Ref.: GT014-011


Depth: 43.94 -- 44.15 (m)

GRAPHS

STRESS PATH



PORE PRESSURE Vs VERTICAL STRAIN



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT014

Sample Ref.: GT014-011


Depth: 43.94 -- 44.15 (m)

STAGE 1 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *[Signature]*

Date: 9/08/17

Checked by: *[Signature]*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT014

Sample Ref.: GT014-011


Depth: 43.94 -- 44.15 (m)

STAGE 2 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *Y*

Date: 9/08/17

Checked by: *THR*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT014

Sample Ref.: GT014-011


Depth: 43.94 -- 44.15 (m)

STAGE 3 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *Yan*

Date: 9/08/17

Checked by: *JAR*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000

Location ID: GT015

Sample Ref.: GT015-002


Depth: 14.08 -- 14.24 (m)

Test method used: BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS1377:Part 8:1990:Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

CONSOLIDATED-UNDRAINED TRIAXIAL COMPRESSION TEST (3 STAGES) MOHR CIRCLES OF TOTAL AND EFFECTIVE STRESSES



Initial Sample Height:	169.50	mm	Initial Water Content:	69.2	%
Initial Sample Diameter:	85.54	mm	Initial Bulk Density:	1.60	t/m ³
Initial B Value:	100	%	Initial Dry Density:	0.94	t/m ³
B Value before Consolidation:	100	%	Final Water Content:	51.1	%

	Consolidation Stage			Failure Values				
	Cell Pressure (kPa)	Back Pressure (kPa)	Eff. Consol. Stress (kPa)	Deviator Stress (kPa)	Pore Pressure Change During Shearing $\delta\mu$ (kPa)	Effective Principal Stress (kPa)		Vertical Strain (%)
						Major σ_1'	Minor σ_3'	
STAGE 1	500	300	200	198.61	132	266.61	68.00	5.77
STAGE 2	800	300	500	410.71	322.2	588.51	177.80	3.91
STAGE 3	1100	300	800	618.80	511.3	907.50	288.70	4.43

Angle of Frictional Resistance:	Total		Effective	
	$\phi =$	15 °	$\phi' =$	29 °
	Cohesion:	c = 23 kPa	c' =	21 kPa
Linear Regression Coefficient:	r =	1.000	r =	1.000

Sample History: Undisturbed core trimmed at natural water content.

Soil description: Favona, GT015-002, 14.08-14.24m, S3, Ignimbrite.

Failure Mode: Plastic

Test Speed: 0.021 (mm/min)

Test Remarks: The sample was saturated by increments of cell pressure and back pressure.
Failure for each stage was determined by either the maximum effective stress ratio or the maximum deviator stress. Strength parameters have been derived by using a linear regression fitting method.

Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT015

Sample Ref.: GT015-002


Depth: 14.08 -- 14.24 (m)

GRAPHS

STRESS PATH



PORE PRESSURE Vs VERTICAL STRAIN



Entered by: *Y*

Date: 9/08/17

Checked by: *AKR*

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT015

Sample Ref.: GT015-002


Depth: 14.08 -- 14.24 (m)

STAGE 1 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT015

Sample Ref.: GT015-002


Depth: 14.08 -- 14.24 (m)

STAGE 2 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *Y*

Date: 9/08/17

Checked by: *ABR*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT015

Sample Ref.: GT015-002


Depth: 14.08 -- 14.24 (m)

STAGE 3 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *Y*

Date: 9/08/17

Checked by: *JAR*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000

Location ID: GT016

Sample Ref.: GT016-005


Depth: 34.20 -- 34.47 (m)

Test method used: BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS1377:Part 8:1990:Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

CONSOLIDATED-UNDRAINED TRIAXIAL COMPRESSION TEST (3 STAGES) MOHR CIRCLES OF TOTAL AND EFFECTIVE STRESSES



Initial Sample Height:	149.89	mm	Initial Water Content:	73.6	%
Initial Sample Diameter:	71.76	mm	Initial Bulk Density:	1.47	t/m ³
Initial B Value:	44	%	Initial Dry Density:	0.85	t/m ³
B Value before Consolidation:	96	%	Final Water Content:	64.2	%

	Consolidation Stage			Failure Values				
	Cell Pressure (kPa)	Back Pressure (kPa)	Eff. Consol. Stress (kPa)	Deviator Stress (kPa)	Pore Pressure Change During Shearing $\delta\mu$ (kPa)	Effective Principal Stress (kPa)		Vertical Strain (%)
						Major σ_1'	Minor σ_3'	
STAGE 1	500	300	200	285.98	120.5	365.48	79.50	0.81
STAGE 2	800	300	500	411.48	320.5	590.98	179.50	1.90
STAGE 3	1100	300	800	522.05	493.2	828.85	306.80	3.51

Angle of Frictional Resistance:	Total		Effective	
	$\phi =$	9 °	$\phi' =$	20 °
	Cohesion:	c = 89 kPa	c' =	75 kPa
Linear Regression Coefficient:	r =	0.999	r =	0.994

Sample History: Undisturbed core trimmed at natural water content.

Soil description: Favona, GT016-005, 34.2-34.47m, S4, Ignimbrite.

Failure Mode: Plastic

Test Speed: 0.016 (mm/min)

Test Remarks: The sample was saturated by increments of cell pressure and back pressure.

Failure for each stage was determined by the maximum Deviator stress. Strength parameters have been derived by using a linear regression fitting method.

Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT016

Sample Ref.: GT016-005


Depth: 34.20 -- 34.47 (m)

GRAPHS

STRESS PATH



PORE PRESSURE Vs VERTICAL STRAIN



Entered by: *Y*

Date: 9/08/17

Checked by: *AR*

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT016

Sample Ref.: GT016-005


Depth: 34.20 -- 34.47 (m)

STAGE 1 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT016

Sample Ref.: GT016-005


Depth: 34.20 -- 34.47 (m)

STAGE 2 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT016

Sample Ref.: GT016-005


Depth: 34.20 -- 34.47 (m)

STAGE 3 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

ARR

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000

Location ID: GT017

Sample Ref.: GT017-006


Depth: 23.60 -- 23.90 (m)

Test method used: BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS1377:Part 8:1990:Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

CONSOLIDATED-UNDRAINED TRIAXIAL COMPRESSION TEST (3 STAGES) MOHR CIRCLES OF TOTAL AND EFFECTIVE STRESSES



Initial Sample Height:	169.20	mm	Initial Water Content:	37.2	%
Initial Sample Diameter:	82.84	mm	Initial Bulk Density:	1.88	t/m ³
Initial B Value:	12	%	Initial Dry Density:	1.37	t/m ³
B Value before Consolidation:	96	%	Final Water Content:	34.6	%

	Consolidation Stage			Failure Values				
	Cell Pressure (kPa)	Back Pressure (kPa)	Eff. Consol. Stress (kPa)	Deviator Stress (kPa)	Pore Pressure Change During Shearing δu (kPa)	Effective Principal Stress (kPa)		Vertical Strain (%)
						Major σ_1'	Minor σ_3'	
STAGE 1	500	300	200	118.94	54.2	264.74	145.80	3.69
STAGE 2	800	300	500	244.69	133.9	610.79	366.10	4.75
STAGE 3	1100	300	800	391.65	206.4	985.25	593.60	4.94

Angle of Frictional Resistance:	Total		Effective	
	$\phi =$	11 °	$\phi' =$	14 °
	Cohesion:	c = 10 kPa	c' =	11 kPa
Linear Regression Coefficient:	r =	0.999	r =	0.999

Sample History: Undisturbed core trimmed at natural water content.

Soil description: Favona, GT017-006, 23.6-23.9, S5, Class 4 Andesite Breccia.

Failure Mode: Planar / Plastic

Test Speed: 0.019 (mm/min)

Test Remarks: The sample was saturated by increments of cell pressure and back pressure.

Failure for each stage was determined by the maximum Deviator stress. Strength parameters have been derived by using a linear regression fitting method.

Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT017

Sample Ref.: GT017-006


Depth: 23.60 -- 23.90 (m)

GRAPHS

STRESS PATH



PORE PRESSURE Vs VERTICAL STRAIN



Entered by: *Yan*

Date: 9/08/17

Checked by: *ARR*

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT017

Sample Ref.: GT017-006


Depth: 23.60 -- 23.90 (m)

STAGE 1 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT017

Sample Ref.: GT017-006


Depth: 23.60 -- 23.90 (m)

STAGE 2 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT017

Sample Ref.: GT017-006


Depth: 23.60 -- 23.90 (m)

STAGE 3 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

P. +64 9 356 3510

W. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000

Location ID: GT017

Sample Ref.: GT017-007


Depth: 41.40 -- 41.56 (m)

Test method used: BS1377:Part 8:1990:Clause 5 Saturation

BS1377:Part 8:1990:Clause 6 Consolidation

BS1377:Part 8:1990:Clause 7 Consolidated-undrained triaxial compression test with pore pressure measurement

CONSOLIDATED-UNDRAINED TRIAXIAL COMPRESSION TEST (3 STAGES) MOHR CIRCLES OF TOTAL AND EFFECTIVE STRESSES



Initial Sample Height:	172.19	mm	Initial Water Content:	15.6	%
Initial Sample Diameter:	81.32	mm	Initial Bulk Density:	2.24	t/m ³
Initial B Value:	10	%	Initial Dry Density:	1.94	t/m ³
B Value before Consolidation:	100	%	Final Water Content:	17.1	%

	Consolidation Stage			Failure Values				
	Cell Pressure (kPa)	Back Pressure (kPa)	Eff. Consol. Stress (kPa)	Deviator Stress (kPa)	Pore Pressure Change During Shearing $\delta\mu$ (kPa)	Effective Principal Stress (kPa)		Vertical Strain (%)
						Major σ_1'	Minor σ_3'	
STAGE 1	500	300	200	138.31	52.5	285.81	147.50	3.02
STAGE 2	800	300	500	283.26	117.6	665.66	382.40	3.06
STAGE 3	1100	300	800	434.62	161.3	1073.32	638.70	5.02

Angle of Frictional Resistance:	Total		Effective	
	$\phi =$	11 °	$\phi' =$	13 °
	Cohesion:	c = 16 kPa	c' =	20 kPa
Linear Regression Coefficient:	r =	1.000	r =	1.000

Sample History: Undisturbed core trimmed at natural water content.

Soil description: Favona, GT017-007, 41.40-41.56m, R1, Class 4 Andesite.

Failure Mode: Planar / Plastic

Test Speed: 0.02 (mm/min)

Test Remarks: The sample was saturated by increments of cell pressure and back pressure.
Failure for each stage was determined by the maximum effective stress ratio. Strength parameters have been derived by using a linear regression fitting method.

Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT017

Sample Ref.: GT017-007


Depth: 41.40 -- 41.56 (m)

GRAPHS

STRESS PATH



PORE PRESSURE Vs VERTICAL STRAIN



Entered by: *Ym*

Date: 9/08/17

Checked by: *ARR*

Date:

9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT017

Sample Ref.: GT017-007


Depth: 41.40 -- 41.56 (m)

STAGE 1 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT017

Sample Ref.: GT017-007


Depth: 41.40 -- 41.56 (m)

STAGE 2 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by: *[Signature]*

Date: 9/08/17

Checked by: *[Signature]*

Date: 9/08/17



23 Morgan Street, Newmarket
Auckland 1023, New Zealand

p. +64 9 356 3510

w. www.geotechnics.co.nz

Site: Waihi, NZ

Your Project ID: PSM125

Project ID: 1003796.0000


Location ID: GT017

Sample Ref.: GT017-007


Depth: 41.40 -- 41.56 (m)

STAGE 3 GRAPHS

CONSOLIDATION



STRESS-STRAIN CURVE



Entered by:

Date: 9/08/17

Checked by:

Date:

9/08/17

Appendix J

Raw Point Load





Job No.	PSM125										Sheet	1	of	2		
Project	Project Pye GT011										Core Shed					
Test Method	AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index						Sampling Technique	Coring				Sampling Date				
							Storage History	Core Shed				Testing Date 27/06/2017				
Test Machine	GSA 6500						Moisture Condition	Field Moisture				Tested By AGI				
Calibration Date	1/2/2012						Loading Rate	< 30 seconds				UCS / Is(50) 18.0				
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests							PSM Strength Class	
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode		
Andesite	GT011	3.10	80	100	0.5	0.09		80	65		0.3	0	0.05		R0 / R1	
Andesite	GT011	5.90	80	100	0.2	0.03		80	55		0.3	0.1	0.06		R0	
Andesite	GT011	9.00	80	100	0.2	0.04		80	50		0.2	0	0.04		R0	
Andesite	GT011	12.80	72	100	0.6	0.14		72	45		0.5	0.1	0.14		R1	
Andesite	GT011	20.10	80	100	1.6	0.31		80	50		0.4	0.1	0.09	Break along existing	R1 / R2	
Andesite	GT011	26.70	80	100	2.7	0.51		80	50		1.9	0.4	0.45		R2	
Andesite	GT011	28.50	80	100	2.3	0.44		80	50		0.6	0.1	0.15	Break along existing	R1 / R2	
Andesite	GT011	33.00	80	100	1.9	0.37	Break along incipient	80	52		2.6	0.5	0.58		R2 / R3	
Andesite	GT011	35.00	80	100	0.9	0.17	Break along incipient	80	40		1.5	0.4	0.4	Break along existing	R1 / R2	
Andesite	GT011	38.00	80	100	0.6	0.11		80	57		1.2	0.2	0.25		R1 / R2	
Andesite	GT011	42.00		100				34	35		0.2	0.1	0.1	Disaggregates along quartz veining	R1	
Andesite	GT011	45.40		100				80	48		0.6	0.1	0.15		R1	
Andesite	GT011	47.90	80	100	0.6	0.11		80	60		0.3	0	0.06		R0	
Andesite	GT011	49.70	80	100	0.7	0.14	Break along incipient	80	50		0.4	0.1	0.1	Break along incipient	R1	
Andesite	GT011	52.80	80	100	2	0.38	Break along incipient	75	50		1.2	0.3	0.29	Break along incipient	R2	
Andesite	GT011	55.35	80	100	0.3	0.06	Break along incipient	80	40		0.7	0.2	0.18		R0 / R2	
Andesite	GT011	58.42	80	100	0.6	0.11	Break along incipient	64	40		0.9	0.3	0.28		R1 / R2	
Andesite	GT011	60.50	80	100	0.7	0.13	Break along incipient	80	55		1.2	0.2	0.26		R1 / R2	
Andesite	GT011	65.00	80	100	1.9	0.36	Break along incipient	80	43		2.3	0.5	0.59		R2 / R3	
Andesite	GT011	69.00	80	100	2.7	0.52		80	36		2.2	0.6	0.65		R2 / R3	
Andesite	GT011	70.00	80	100	3	0.57		60	45		1.7	0.5	0.54		R2 / R3	
Andesite	GT011	72.80	80	100	2.6	0.5		60	48		2.8	0.8	0.82		R2 / R3	
Andesite	GT011	74.60	80	100	3.7	0.71		57	40		2.2	0.8	0.78		R3	
Andesite	GT011	77.20	80	100	0.3	0.06	Disintegration along incipient	78	45		0.7	0.2	0.18		R0 / R2	
Andesite	GT011	80.00	80	100	0.8	0.15		80	38		0.8	0.2	0.24		R1 / R2	
Andesite	GT011	87.70	80	100	0.8	0.15		80	40		1.2	0.3	0.33		R1 / R2	
By:	AGI						Checked:							Date:	27/6/2017	

[illegible]



POINT LOAD STRENGTH INDEX TEST RESULTS

Job No.		PSM125										Sheet		1	of		2										
Project		Project Pye										GT012										Core Shed					
Test Method		AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique		Coring				Sampling Date									
												Storage History		Core Shed				Testing Date				29/06/2017					
Test Machine		GSA 6500										Moisture Condition		Field Moisture				Tested By				AGI					
Calibration Date		1/2/2012										Loading Rate		< 30 seconds				UCS / Is(50)				18.0					
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests										PSM Strength Class									
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode													
Andesite	GT012	29.50	80	100	0.5	0.09	Break along incipient	81	80		0.3	0	0.05	Partial break along incipient	R0 / R1												
Andesite	GT012	32.50	80	100	1.3	0.25		80	45		0.9	0.2	0.22		R2												
Andesite	GT012	36.25	80	100	1.5	0.29		80	56		0.9	0.2	0.19		R2												
Andesite	GT012	38.75	80	100	1.9	0.36		80	42		1.6	0.4	0.42		R2												
Andesite	GT012	41.70	80	100	1	0.2		80	49		2	0.4	0.47		R2												
Andesite	GT012	45.58	80	100	1.2	0.23		48	35		1.2	0.6	0.55		R2												
Andesite	GT012	48.20	80	100	5	0.97		80	50		3.4	0.7	0.79		R3												
Andesite	GT012	49.70	80	100	0.5	0.1		62	39		0.4	0.1	0.15		R1												
Andesite	GT012	53.35	80	100	4.4	0.85		70	34		1.9	0.6	0.64		R3												
Andesite	GT012	57.00	80	100	3.2	0.61		80	42		3.5	0.8	0.91		R3												
Andesite	GT012	58.80		100			45	30		0.6	0.3	0.32	R2														
Andesite	GT012	61.25	80	100	3.4	0.66	80	66		3.5	0.5	0.65	R3														
Andesite	GT012	65.23	80	100	2.9	0.56	80	48		3.2	0.6	0.75	R3														
Andesite	GT012	68.20	80	100	1.2	0.23	Break along incipient	80	51		1.2	0.2	0.27	Break along incipient	R2												
Andesite	GT012	72.30	80	100	1	0.19	Break along incipient	80	47		1.5	0.3	0.36	R2													
Andesite	GT012	75.00	90	100	0.3	0.05	Break along incipient	60	44		0.3	0.1	0.09	R0 / R1													
Andesite	GT012	76.90	80	100	2.5	0.48	Partial break along incipient	80	70		4.5	0.6	0.79	R2 / R3													
Andesite	GT012	78.80	80	100	0.5	0.09		52	44		0.3	0.1	0.1	R1													
Andesite	GT012	81.10	80	100	5.8	1.12		62	38		1.8	0.6	0.61	Partial break along incipient	R3												
Andesite	GT012	83.62	80	100	0.3	0.05		80	39		0.1	0	0.03	Break along incipient	R0												
Andesite	GT012	87.00	80	100	5.7	1.1		60	37		2.5	0.9	0.91	R3													
Andesite	GT012	90.00	80	100	3.9	0.75	Partial break along incipient	80	58		5.9	1	1.21	R3													
Andesite	GT012	93.00	60	100	5.3	1.6		60	40		6.9	2.3	2.36	R4													
Andesite	GT012	96.65	58	100	4.1	1.31		58	40		3.3	1.1	1.15	R3													
Andesite	GT012	100.40	58	100	5.5	1.73		58	35		3.7	1.4	1.42	R4													
Andesite	GT012	104.50		100			Refusal						Refusal														
By:		AGI										Checked:												Date:		29/6/2017	



POINT LOAD STRENGTH INDEX TEST RESULTS

By: <i>AGI</i>	Checked:	Date: <i>29/6/2017</i>
----------------	----------	------------------------



POINT LOAD STRENGTH INDEX TEST RESULTS

Job No.		PSM125										Sheet		1		of		2					
Project		Project Pye										GT013										Core Shed	
Test Method		AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique		Coring		Sampling Date							
												Storage History		Core Shed		Testing Date		24/06/2017					
Test Machine		GSA 6500										Moisture Condition		Field Moisture		Tested By		AGI					
Calibration Date		1/2/2012										Loading Rate		< 30 seconds		UCS / Is(50)		18.0					
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests							PSM Strength Class								
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode									
Andesite	GT013	4.80	80	100	0.1	0.02	No reading, breaks along incipient	80	45					No reading	R0 / R1								
Andesite	GT013	6.25	80	100				80	46					No reading									
Andesite	GT013	23.70	80	100	0.1	0.02		56	51		0.1	0	0.02										
Andesite	GT013	26.75	80	100	0.1	0.02		67	46		0.1	0	0.02										
Andesite	GT013	32.02	80	100	0.4	0.08		80	31		0.3	0.1	0.09										
Andesite	GT013	29.85		100			No reading, breaks along incipient	60	41		0.4	0.1	0.14										
Andesite	GT013	35.45		100			No reading, breaks along incipient	80	63		0.5	0.1	0.09										
Andesite	GT013	38.45	80	100	0.2	0.03		80	49		0.2	0	0.05										
Andesite	GT013	40.70		100			No reading, breaks along incipient	80	56		0.8	0.1	0.16										
Andesite	GT013	42.00		100			No reading, breaks along incipient	55	45		0.2	0	0.05										
Andesite	GT013	30.75		100			No reading, breaks along incipient	76	30		0.3	0.1	0.09										
Andesite	GT013	46.00	80	100			No reading, breaks along incipient	50	33		0.2	0.1	0.08										
Andesite	GT013	47.20	80	100	0.1	0.03		50	33		0.1	0	0.04	Break along incipient									
Andesite	GT013	50.70		100			No reading, breaks along incipient	78	45		0.6	0.1	0.15	Break along incipient	R1								
Andesite	GT013	53.60		100			No reading, breaks along incipient	80	53		1.3	0.2	0.28		R2								
Andesite	GT013	57.50		100			No reading, breaks along incipient	60	39		1.4	0.5	0.5		R2								
Andesite	GT013	62.90		100			Disaggregates along incipient							Disaggregates along incipient									
Andesite	GT013	66.30		100			Disaggregates along incipient	48	46		0.2	0.1	0.08	Break along incipient	R0								
Andesite	GT013	68.00		100			Disaggregates along incipient	69	50		0.4	0.1	0.1		R1								
Andesite	GT013	70.00	80	100	0.3	0.05	Break along incipient	80	28		0.3	0.1	0.12	Break along incipient	R1								
Andesite	GT013	73.00	80	100	4.2	0.8		80	55		2	0.4	0.43		R2 / R3								
Andesite	GT013	76.00	80	100	3.4	0.65		58	45		1.2	0.4	0.38		R2 / R3								
Andesite	GT013	78.40	80	100	3.6	0.7		80	53		2.3	0.4	0.5		R2 / R3								
Andesite	GT013	80.72	80	100	4.1	0.79		80	49		2.5	0.5	0.59		R3								
Andesite	GT013	83.00		100			Refusal							Refusal									
Andesite	GT013	88.20	80	100	3.5	0.67		80	65		4.6	0.7	0.87		R3								
By:		AGI										Checked:				Date:		24/6/2017					



Job No.	PSM125						Sheet 2 of 2									
Project	Project Pye GT013							Core Shed								
Test Method	AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index						Sampling Technique	Coring					Sampling Date			
							Storage History	Core Shed					Testing Date 24/06/2017			
Test Machine	GSA 6500						Moisture Condition	Field Moisture					Tested By AGI			
Calibration Date	1/2/2012						Loading Rate	< 30 seconds					UCS / Is(50) 18.0			
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests							PSM Strength Class	
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode		
Andesite	GT013	90.66	80	100	0.6	0.12	Break along incipient	80	70		0.4	0.1	0.07		R0 / R1 R2 / R3 R1 R2 / R3	
Andesite	GT013	94.75	80	100	1.3	0.25		70	44		3.3	0.8	0.93			
Andesite	GT013	97.65	80	100	0.6	0.11		80	66		0.8	0.1	0.14			
Andesite	GT013	99.60	80	100	2.2	0.42		80	46		4.1	0.9	1			
By: AGI Checked:																
Date: 24/6/2017																



POINT LOAD STRENGTH INDEX TEST RESULTS

Job No.		PSM125										Sheet		1		of		1					
Project		Project Pye										GT014										Core Shed	
Test Method		AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique		Coring				Sampling Date					
												Storage History		Core Shed				Testing Date				22/06/2017	
Test Machine		GSA 6500										Moisture Condition		Field Moisture				Tested By				AGI	
Calibration Date		1/2/2012										Loading Rate		< 30 seconds				UCS / Is(50)				18.0	
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests								PSM Strength Class							
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode									
Dacite	GT014	5.20	80	100	2.5	0.49	Break along incipient	80	45		1.3	0.3	0.31	Break along incipient	R2								
Dacite	GT014	10.60	80	100				80	46		8	1.7	1.98		R4								
Dacite	GT014	13.20	71	100				71	36		0.3	0.1	0.08		R0								
Dacite	GT014	15.25	74	100				74	48		0.5	0.1	0.12		R1								
Dacite	GT014	17.50	80	100	1.1	0.21		80	38		1.6	0.4	0.45		R2								
Dacite	GT014	21.60	76	100	0.3	0.06		76	39		0.5	0.1	0.15		R0 / R1								
Breccia	GT014	34.60	79	100	0.6	0.11		79	42		0.3	0.1	0.09		R1								
Breccia	GT014	44.70	58	100	0.2	0.07		58	36		0.4	0.1	0.14		R0 / R1								
Andesite	GT014	46.80	60	100	9.6	2.88		60	35		12.1	4.5	4.59		R4 / R5								
Andesite	GT014	51.70	60	100	8.5	2.57		60	55		8.9	2.1	2.39		R4								
Andesite	GT014	54.50	60	100	9.5	2.87		60	38		14.7	5.1	5.25		R4 / R5								
Andesite	GT014	58.70	60	100				60	39		3.9	1.3	1.35		R3								
Andesite	GT014	61.30	60	100	1.9	0.58		60	49		1.5	0.4	0.43		R2								
Andesite	GT014	63.70	60	100	2	0.6		60	43		2.6	0.8	0.84		R3								
Andesite	GT014	67.00	60	100	14.6	4.4		60	33		14.3	5.7	5.66		R4 / R5								
Andesite	GT014	68.70	60	100				52	40		1	0.4	0.37		R2								
Andesite	GT014	72.00	60	100	8	2.4	60	39		9.4	3.1	3.26	R4										
Andesite	GT014	75.00	60	100	12.2	3.69	60	50		14.8	3.9	4.25	R4										
Andesite	GT014	78.45	60	100	2.7	0.81	60	45		4.8	1.4	1.51	R3 / R4										
Andesite	GT014	83.00	60	100	6.4	1.93	60	50		11.7	3.1	3.36	R4										
Andesite	GT014	86.00	60	100	1.8	0.55	Break along incipient	60	40		2.9	0.9	0.98	R2 / R3									
Andesite	GT014	90.00	60	100	16.5	4.98		50	40		15	5.9	5.91	R5									
Andesite	GT014	95.00	60	100			Refusal						Refusal										
Andesite	GT014	100.00	60	100			Refusal						Refusal										
Andesite	GT014	104.50	60	100			Refusal						Refusal										
Andesite	GT014	110.00	60	100			Refusal						Refusal										
By:		AGI										Checked:		Date:								22/6/2017	



POINT LOAD STRENGTH INDEX TEST RESULTS

Job No.		PSM125										Sheet		1	of		2									
Project		Project Pye										GT015										Core Shed				
Test Method		AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique		Coring										Sampling Date		
												Storage History		Core Shed										Testing Date		28/06/2017
Test Machine		GSA 6500										Moisture Condition		Field Moisture										Tested By		AGI
Calibration Date		1/2/2012										Loading Rate		< 30 seconds										UCS / Is(50)		18.0
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests										PSM Strength Class								
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode												
Ignimbrite	GT015	6.30	80	100	1.1	0.21	Refusal Refusal	80	40		3.1	0.8	0.85	Refusal Refusal	R2 / R3 R2											
Ignimbrite	GT015	8.00	80	100	2.5	0.47		80	36		1.2	0.3	0.36													
Ignimbrite	GT015	19.00	80	100																						
Andesite	GT015	30.30	80	100																						
Andesite	GT015	34.00	80	100	13.1	2.53		80	65		7.9	1.2	1.49		R4											
Andesite	GT015	36.50	80	100	4.8	0.93		80	44		5.7	1.3	1.45		R3 / R4											
Andesite	GT015	39.30	80	100	0.6	0.11		80	65		0.5	0.1	0.09		R1											
Andesite	GT015	41.90	80	100	0.2	0.03	Break along incipient	80	50		0.2	0	0.04	Break along incipient	R0											
Andesite	GT015	42.40	80	100	0.2	0.03	Break along incipient	80	36		0.2	0.1	0.06	Break along incipient	R0											
Andesite	GT015	42.00	80	100	0.3	0.05	Break along incipient	80	40		0.3	0.1	0.07	Break along incipient	R0											
Andesite	GT015	44.36	80	100	3.3	0.63		80	49		6	1.2	1.41		R3 / R4											
Andesite	GT015	46.50	80	100	0.1	0.03	Disintegrate along incipient	80	50		2.2	0.4	0.5		R2											
Andesite	GT015	47.80	80	100	0.9	0.18		62	40		0.8	0.2	0.26		R2											
Andesite	GT015	49.60	80	100	5.5	1.07		80	44		2.2	0.5	0.56		R3											
Andesite	GT015	52.95	80	100	5.4	1.04		80	59		4.9	0.8	1		R3											
Andesite	GT015	56.00	80	100	1.1	0.2	Break along incipient	80	44		2.1	0.5	0.54		R2											
Andesite	GT015	59.60	80	100	2.2	0.43		40	32		1	0.6	0.56		R2 / R3											
Andesite	GT015	61.20	80	100	5.5	1.07		75	43		4.4	1.1	1.21		R3											
Andesite	GT015	65.10	80	100	4.6	0.89		65	44		1.9	0.5	0.57		R3											
Andesite	GT015	69.00	80	100	4.3	0.83		65	40		1.5	0.4	0.47		R2 / R3											
Andesite	GT015	73.75	80	100	2	0.39		80	37		2.1	0.5	0.6		R2 / R3											
Andesite	GT015	78.33	80	100	4.8	0.93		60	46		2.5	0.7	0.76		R3											
Andesite	GT015	81.50	80	100	1.2	0.24	Break along incipient	80	40		1.5	0.4	0.4	Break along incipient	R2											
Andesite	GT015	84.90	80	100	5.8	1.12		80	50		5.7	1.1	1.31		R3											
Andesite	GT015	89.80	80	100	4	0.77	Break along incipient	80	48		8.7	1.8	2.07		R3 / R4											
Andesite	GT015	94.20	80	100	5.4	1.04		60	30		2.1	0.9	0.9	Break along incipient	R3											
By:		AGI										Checked:												Date:		28/6/2017



POINT LOAD STRENGTH INDEX TEST RESULTS

Job No.		PSM125										Sheet		2		of		2					
Project		Project Pye										GT015										Core Shed	
Test Method		AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique		Coring				Sampling Date					
												Storage History		Core Shed				Testing Date				28/06/2017	
Test Machine		GSA 6500										Moisture Condition		Field Moisture				Tested By				AGI	
Calibration Date		1/2/2012										Loading Rate		< 30 seconds				UCS / Is(50)				18.0	
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests							PSM Strength Class								
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode									
Andesite	GT015	99.10	80	100	1.9	0.37	Break along incipient	70	43		1.7	0.5	0.5	Break along incipient	R2								
Andesite	GT015	102.10	80	100	3.8	0.74		73	46		2.7	0.6	0.7		R3								
Andesite	GT015	105.40	80	100	5.9	1.14		80	43		6	1.4	1.56		R3 / R4								
Andesite	GT015	111.00	80	100	2.3	0.44		80	44		2.1	0.5	0.53		R2								
Andesite	GT015	114.80	80	100	1.4	0.27		80	40		1.1	0.3	0.31	Break along incipient	R2								
Andesite	GT015	116.05	80	100	5	0.97		80	45		3.8	0.8	0.95		R3								
Andesite	GT015	120.30	80	100	4.8	0.93		80	76		3.8	0.5	0.62		R3								
Andesite	GT015	124.20	80	100	3.7	0.71		80	47		8.1	1.7	1.95		R3 / R4								
Andesite	GT015	127.50	80	100	7.8	1.51		80	50		7.2	1.4	1.66		R4								
By:		AGI										Checked:						Date:		28/6/2017			



POINT LOAD STRENGTH INDEX TEST RESULTS

Job No.		PSM125										Sheet		1		of		2					
Project		Project Pye										GT016										Core Shed	
Test Method		AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique		Coring		Sampling Date							
												Storage History		Core Shed		Testing Date		25/06/2017					
Test Machine		GSA 6500										Moisture Condition		Field Moisture		Tested By		AGI					
Calibration Date		1/2/2012										Loading Rate		< 30 seconds		UCS / Is(50)		18.0					
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests							PSM Strength Class								
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode									
Ignimbrite	GT016	16.60	76	100	2.4	0.5	Break along incipient	76	37		4.3	1.2	1.31		R2 / R3								
Ignimbrite	GT016	19.50	80	100	1.4	0.27		80	53		3.7	0.7	0.81		R2 / R3								
Ignimbrite	GT016	22.90	80	100	0.9	0.18		80	57		1.4	0.2	0.28		R2								
Ignimbrite	GT016	24.90	80	100	0.8	0.14		80	47		0.4	0.1	0.09		R1								
Andesite	GT016	47.60	69	100	0.2	0.05		69	40		0.3	0.1	0.1		R0 / R1								
Andesite	GT016	48.00	80	100	0.7	0.14		80	60		1.3	0.2	0.26		R1 / R2								
Andesite	GT016	48.75	80	100	2.5	0.49		80	60		1.7	0.3	0.34		R2								
Andesite	GT016	50.35	80	100	0.6	0.11		64	55		0.1	0	0.03		R1								
Andesite	GT016	52.50	80	100				80	50		0.6	0.1	0.13		R1								
Andesite	GT016	55.50	80	100	0.4	0.08		60	44		0.5	0.1	0.15		R1								
Andesite	GT016	59.60	80	100	0.8	0.15		80	70		0.9	0.1	0.16		R1								
Andesite	GT016	62.05	80	100	1.9	0.37		80	41		1	0.2	0.26		R2								
Andesite	GT016	64.80	80	100	2.8	0.55		80	53		2.2	0.4	0.49		R2								
Andesite	GT016	69.00	80	100	1.6	0.31		62	58		1.2	0.3	0.31		R2								
Andesite	GT016	72.80	80	100	1.7	0.34		80	41		1	0.2	0.27		R2								
Andesite	GT016	76.20	80	100	3.5	0.67		80	53		1.7	0.3	0.38		R2 / R3								
Andesite	GT016	79.50	80	100	1.3	0.25		76	53		1.7	0.3	0.4		R2								
Andesite	GT016	83.00	80	100	3.9	0.74		80	60		3.5	0.6	0.7		R3								
Andesite	GT016	84.50	80	100	0.4	0.07		80	57		0.5	0.1	0.11		R0 / R1								
Andesite	GT016	86.08	80	100	3	0.57		80	48		1.5	0.3	0.36		R2 / R3								
Andesite	GT016	89.00	80	100	0.7	0.14		70	48		0.5	0.1	0.13		R1								
Andesite	GT016	94.80	80	100	5.3	1.02		75	40		4.8	1.3	1.38		R3								
Andesite	GT016	97.40	80	100	1.7	0.33	Break along incipient	80	43		1.5	0.3	0.39	Break along incipient	R2								
Andesite	GT016	100.00	80	100	0.2	0.03	Disaggregates at low loads	80	50		0.5	0.1	0.12	Break along incipient	R1								
Andesite	GT016	101.00	80	100	0.3	0.05	Disaggregates at low loads	61	58		0.1	0	0.03	Disaggregates at low loads	R0								
Andesite	GT016	105.10	80	100	0.8	0.16	Disaggregates at low loads	80	57		0.5	0.1	0.1	Disaggregates at low loads	R1								
By:		AGI										Checked:				Date:		25/6/2017					



Pells Sullivan Meynink

POINT LOAD STRENGTH INDEX TEST RESULTS

Job No.	PSM125										Sheet	2	of	2	
Project	Project Pye GT016										Core Shed				
Test Method	AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index					Sampling Technique		Coring		Sampling Date					
Test Machine	GSA 6500					Storage History		Core Shed		Testing Date 25/06/2017					
Calibration Date	1/2/2012					Moisture Condition		Field Moisture		Tested By AGI					
						Loading Rate		< 30 seconds		UCS / Is(50) 18.0					
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests							PSM Strength Class
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode	
Andesite	GT016	108.50	80	100	0.5	0.1	Disaggregates at low loads	80	44		0.2	0	0.04	Disaggregates at low loads	R1
Andesite	GT016	112.50	80	100	0.2	0.03	Break along incipient	50	38		0.3	0.1	0.13	Disaggregates at low loads	R1
Andesite	GT016	115.00	80	100	2.1	0.41	Break along incipient	80	45		3.7	0.8	0.93		R2 / R3
Andesite	GT016	118.80	80	100	1	0.19		80	66		0.5	0.1	0.1	Disaggregates at low loads	R1 / R2
Andesite	GT016	121.50	80	100	0.6	0.12		55	45		0.5	0.2	0.18		R1 / R2
Andesite	GT016	125.00	80	100			Refusal							Refusal	
Andesite	GT016	128.50	80	100	13.3	2.57		80	50		7.8	1.5	1.8		R4
By: AGI Checked:															Date: 25/6/2017



POINT LOAD STRENGTH INDEX TEST RESULTS

Job No.		PSM125										Sheet		1	of		2																			
Project		Project Pye										GT017										Core Shed														
Test Method		AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique		Coring										Sampling Date												
												Storage History		Core Shed										Testing Date		26/06/2017										
Test Machine		GSA 6500										Moisture Condition		Field Moisture										Tested By		AGI										
Calibration Date		1/2/2012										Loading Rate		< 30 seconds										UCS / Is(50)		18.0										
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests										PSM Strength Class																		
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode																						
Breccia	GT017	30.35	80	100	3.1	0.6	Break along incipient	80	35		6.7	1.9	2.04	Break through matrix	R3 / R4																					
Breccia	GT017	33.70	80	100	3.7	0.71		55	44		3	1	1.02			R3																				
Breccia	GT017	37.80	80	100	0.9	0.17		80	49		0.6	0.1	0.15				R1 / R2																			
Andesite	GT017	40.50	80	100			Refusal							Refusal	R1																					
Andesite	GT017	41.30	80	100	0.6	0.12		80	38		0.5	0.1	0.13			R0 / R1																				
Andesite	GT017	44.65	80	100	0.3	0.06		70	37		0.3	0.1	0.1				R1																			
Andesite	GT017	48.90	80	100	0.2	0.03	Break along incipient	80	54		0.6	0.1	0.12	R0																						
Andesite	GT017	52.80	80	100	0.2	0.03		80	60		0.4	0.1	0.08		R2 / R3																					
Andesite	GT017	56.50	80	100	5.2	1		70	38		1.2	0.4	0.38			R3																				
Andesite	GT017	59.00	80	100	3.5	0.68	80	48		2.9	0.6	0.69	R2																							
Andesite	GT017	66.00	80	100	1.7	0.33	65	40		0.6	0.2	0.18		R2 / R3																						
Andesite	GT017	71.30	80	100	2	0.38	80	54		3.2	0.6	0.69			R2																					
Andesite	GT017	76.50	80	100	2.2	0.42	80	33		1.7	0.5	0.54	R2 / R3																							
Andesite	GT017	79.80	80	100	3	0.59	80	48		2.3	0.5	0.55		R3																						
Andesite	GT017	84.20	80	100	3.2	0.61	80	41		2.6	0.6	0.7			R2 / R3																					
Andesite	GT017	87.90	80	100	2.2	0.42	80	28		2	0.7	0.72	R2																							
Andesite	GT017	90.44	80	100	1.2	0.24	80	50		1.6	0.3	0.36		R4																						
Andesite	GT017	94.00	80	100	1.3	0.25	80	34		1.3	0.4	0.41			R4																					
Andesite	GT017	97.80	80	100	11.7	2.25	80	53		7	1.3	1.54	Refusal																							
Andesite	GT017	101.15	80	100	10.4	2	80	56		12.3	2.2	2.59		R2																						
Andesite	GT017	105.80	80	100			Refusal								R3																					
Andesite	GT017	109.50	80	100				80	46		2.1	0.4	0.5			R2																				
Andesite	GT017	113.65	80	100	3.5	0.68		60	51		2.4	0.6	0.68	R2																						
Andesite	GT017	116.00	80	100	1.4	0.27	80	78		2.3	0.3	0.38	R2																							
Andesite	GT017	119.00	80	100	1.5	0.29	80	53		0.9	0.2	0.2			R2																					
Andesite	GT017	121.35	80	100			No adequate sample	80	57		1.6	0.3		0.32		R2																				
By:		AGI										Checked:												Date:		26/6/2017										




Job No.	PSM125										Sheet	2	of	2												
Project	Project Pye										GT017				Core Shed											
Test Method	AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique				Coring				Sampling Date							
											Storage History				Core Shed				Testing Date				26/06/2017			
Test Machine	GSA 6500										Moisture Condition				Field Moisture				Tested By				AGI			
Calibration Date	1/2/2012										Loading Rate				< 30 seconds				UCS / Is(50)				18.0			
Rock Type	Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests								PSM Strength Class										
			D (mm)	L (mm)	P (kN)	Is(50) (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	Is (MPa)	Is(50) (MPa)	Failure Mode												
Andesite	GT017	124.80	80	100	3.3	0.64	Break along incipient	68	39		3.3	1	1.06	Break through matrix	R3											
Andesite	GT017	127.10	80	100	0.7	0.14	Break through matrix	80	50		2.2	0.4	0.51		R1 / R2											
Andesite	GT017	128.05	80	100	0.4	0.07	Break through matrix	80	29		0.2	0.1	0.06		R0											
Andesite	GT017	132.00	80	100	2.1	0.41		80	36		1.2	0.3	0.35		R2											
Andesite	GT017	135.10	80	100	0.8	0.15		80	34		0.5	0.1	0.15		R1											
Andesite	GT017	138.50	80	100	1.1	0.21		55	40		0.7	0.3	0.27		R2											
By: AGI															Checked:				Date: 26/6/2017							

Appendix K

Triaxial Testing Interpretation





	Cohesion (kPa)	Friction Angle (deg)
Upper Bound	56	27
Lower Bound	27	24
Indicated Strength	42	25

Anderson Lloyd
OceanaGold Project Quattro
Waihi, New Zealand


TRIAXIAL 'p' q' PLOT
IGNIMBRITE



Pells Sullivan Meynink

PSM125

Appendix K



	Cohesion (kPa)	Friction Angle (deg)
Upper Bound	52	15
Lower Bound	26	15
Indicated Strength	39	15

Anderson Lloyd
OceanaGold Project Quattro
Waihi, New Zealand


TRIAXIAL 'p' q' PLOT
VOLCANICLASTIC



Pells Sullivan Meynink

PSM125

Appendix K



	Cohesion (kPa)	Friction Angle (deg)
Upper Bound	103	29
Lower Bound	30	18
Indicated Strength	65	24

Anderson Lloyd
OceanaGold Project Quattro
Waihi, New Zealand


TRIAXIAL 'p' q' PLOT
CLASS 4 ANDESITE



Pells Sullivan Meynink

PSM125

Appendix K



	Cohesion (kPa)	Friction Angle (deg)
Upper Bound	31	14
Lower Bound	0	13
Indicated Strength	15	13

**Anderson Lloyd
OceanaGold Project Quattro
Waihi, New Zealand**

**TRIAXIAL 'p' q' PLOT
GT017 CLASS 4 ANDESITE**



Pells Sullivan Meynink

PSM125


Appendix K

Appendix L

RocLab



Gladstone Pit Failure Criterion



- ◆ Andesite Class 2 - Hoek Brown
- ◆ Andesite Class 2 - Equivalent Mohr-Coulomb
- Andesite Class 3 - Hoek Brown
- Andesite Class 3 - Equivalent Mohr-Coulomb
- ▲ Dacite - Hoek Brown
- ◆ Dacite - Equivalent Mohr-Coulomb
- ◆ Andesite Class 4 - Mohr Coulomb equivalent
- ◆ Andesite Class 4 Modified - Mohr Coulomb equivalent
- ◆ Volcaniclastic - Mohr Coulomb equivalent
- ◆ Ignimbrite - Mohr Coulomb equivalent

Anderson Lloyd
OceanaGold (New Zealand) Ltd Project Quattro
Waihi, New Zealand
MOHR COLOUMB - HOEK BROWN
FAILURE CRITERION



Pells Sullivan Meynink

PSM125-260R

Appendix L

PSM125 Favona and Gladstone - Andesite Class 2

Hoek-Brown Classification

intact uniaxial comp. strength (σ_{ci}) = 25 MPa
GSI = 40 m_i = 25 Disturbance factor (D) = 0
intact modulus (E_i) = 10000 MPa

Hoek-Brown Criterion



m_b = 2.933 s = 0.0013 a = 0.511

Mohr-Coulomb Fit


cohesion = 1.426 MPa friction angle = 35.42 deg

Rock Mass Parameters

tensile strength = -0.011 MPa
uniaxial compressive strength = 0.827 MPa
global strength = 5.527 MPa
deformation modulus = 1596.52 MPa



PSM125 Favona and Gladstone - Andesite Class 3



Hoek-Brown Classification

intact uniaxial comp. strength (σ_{ci}) = 12 MPa
GSI = 29 m_i = 25 Disturbance factor (D) = 0
intact modulus (Ei) = 4800 MPa
modulus ratio (MR) = 400

Hoek-Brown Criterion


m_b = 1.980 s = 0.0004 a = 0.524

Mohr-Coulomb Fit


cohesion = 0.571 MPa friction angle = 32.05 deg

Rock Mass Parameters

tensile strength = -0.002 MPa
uniaxial compressive strength = 0.192 MPa
global strength = 2.061 MPa
deformation modulus = 366.48 MPa



PSM125 Favona and Gladstone - Dacite



Hoek-Brown Classification

intact uniaxial comp. strength (σ_{ci}) = 8 MPa
GSI = 40 m_i = 25 Disturbance factor (D) = 0
intact modulus (E_i) = 3200 MPa
modulus ratio (MR) = 400

Hoek-Brown Criterion


m_b = 2.933 s = 0.0013 a = 0.511

Mohr-Coulomb Fit

cohesion = 0.456 MPa friction angle = 35.42 deg

Rock Mass Parameters


tensile strength = -0.003 MPa
uniaxial compressive strength = 0.265 MPa
global strength = 1.769 MPa
deformation modulus = 510.89 MPa



Appendix M

Kinematic





Symbol	TYPE	Quantity
◇	Breccia	21
×	CZ	7
◆	FT	26
■	SH	165

Color	Density Concentrations
	0.00 - 0.70
	0.70 - 1.40
	1.40 - 2.10
	2.10 - 2.80
	2.80 - 3.50
	3.50 - 4.20
	4.20 - 4.90

Contour Data	Pole Vectors
Maximum Density	4.45%
Contour Distribution	Fisher
Counting Circle Size	1.0%

Kinematic Analysis	Planar Sliding
Slope Dip	50
Slope Dip Direction	300
Friction Angle	20°
Lateral Limits	30°


	Critical	Total	%
Planar Sliding (All)	7	219	3.20%
Planar Sliding (Set 6: Set 6)	4	7	57.14%

Plot Mode	Pole Vectors
Vector Count	219 (219 Entries)
Hemisphere	Lower
Projection	Equal Area



Pells Sullivan Meynink
Engineering Consultants
Rock-Soil-Water

Client:	Anderson Lloyd					
Project:	Project Quattro					
Location:	Gladstone East Design Sector					
Analysis Description:	Orientated Core - IRA Planar Sliding					
Job No:	PSM125	By:	TM	Date:	27/08/2021	Scale: Stereo Plot
				Run:	Gladstone_rev5.dips8	



Symbol	TYPE	Quantity
◇	Breccia	21
×	CZ	7
◆	FT	26
■	SH	165
Symbol	Feature	
■	Critical Intersection	

Color	Density Concentrations
	0.00 - 0.70
	0.70 - 1.40
	1.40 - 2.10
	2.10 - 2.80
	2.80 - 3.50
	3.50 - 4.20
	4.20 - 4.90
Contour Data Pole Vectors	
Maximum Density 4.45%	
Contour Distribution Fisher	
Counting Circle Size 1.0%	


Kinematic Analysis	Wedge Sliding		
Slope Dip	50		
Slope Dip Direction	300		
Friction Angle	20°		
	Critical	Total	%
Wedge Sliding	2	15	13.33%

Plot Mode	Pole Vectors
Vector Count	219 (219 Entries)
Intersection Mode	Mean Set Planes
Intersections Count	15
Hemisphere	Lower
Projection	Equal Area



Pells Sullivan Meynink
Engineering Consultants
Rock-Soil-Water

Client:	Anderson Lloyd					
Project:	Project Quattro					
Location:	Gladstone East Design Sector					
Analysis Description:	Orientated Core - IRA Planar Sliding					
Job No:	PSM125	By:	TM	Date:	27/08/2021	Scale: Stereo Plot
				Run:	Gladstone_rev5.dips8	



Symbol	TYPE	Quantity
◇	Breccia	21
×	CZ	7
◆	FT	26
■	SH	165

Color	Density Concentrations
	0.00 - 0.70
	0.70 - 1.40
	1.40 - 2.10
	2.10 - 2.80
	2.80 - 3.50
	3.50 - 4.20
	4.20 - 4.90

Contour Data	Pole Vectors
Maximum Density	4.45%
Contour Distribution	Fisher
Counting Circle Size	1.0%

Kinematic Analysis	Planar Sliding
Slope Dip	50
Slope Dip Direction	210
Friction Angle	20°
Lateral Limits	30°


	Critical	Total	%
Planar Sliding (All)	7	219	3.20%

Plot Mode	Pole Vectors
Vector Count	219 (219 Entries)
Hemisphere	Lower
Projection	Equal Area



Pells Sullivan Meynink
Engineering Consultants
Rock-Soil-Water

Client:	Anderson Lloyd					
Project:	Project Quattro					
Location:	Gladstone North Design Sector					
Analysis Description:	Orientated Core - IRA Planar Sliding					
Job No:	PSM125	By:	TM	Date:	21/07/2021	Scale: Stereo Plot
				Run:	Gladstone_rev5.dips8	



Symbol	TYPE	Quantity
◇	Breccia	21
×	CZ	7
◆	FT	26
■	SH	165
Symbol	Feature	
□	Critical Intersection	

Color	Density Concentrations
	0.00 - 0.70
	0.70 - 1.40
	1.40 - 2.10
	2.10 - 2.80
	2.80 - 3.50
	3.50 - 4.20
	4.20 - 4.90
Contour Data Pole Vectors	
Maximum Density 4.45%	
Contour Distribution Fisher	
Counting Circle Size 1.0%	


Kinematic Analysis	Wedge Sliding		
Slope Dip	50		
Slope Dip Direction	210		
Friction Angle	20°		
	Critical	Total	%
Wedge Sliding	5	15	33.33%

Plot Mode	Pole Vectors		
Vector Count	219 (219 Entries)		
Intersection Mode	Mean Set Planes		
Intersections Count	15		
Hemisphere	Lower		
Projection	Equal Area		



Pells Sullivan Meynink
Engineering Consultants
Rock-Soil-Water

Client:	Anderson Lloyd					
Project:	Project Quattro					
Location:	Gladstone North Design Sector					
Analysis Description:	Orientated Core - IRA Planar Sliding					
Job No:	PSM125	By:	TM	Date:	21/07/2021	Scale: Stereo Plot
				Run:	Gladstone_rev5.dips8	



Symbol	TYPE	Quantity
◇	Breccia	21
×	CZ	7
◆	FT	26
■	SH	165

Color	Density Concentrations
	0.00 - 0.70
	0.70 - 1.40
	1.40 - 2.10
	2.10 - 2.80
	2.80 - 3.50
	3.50 - 4.20
	4.20 - 4.90

Contour Data	Pole Vectors
Maximum Density	4.45%
Contour Distribution	Fisher
Counting Circle Size	1.0%

Kinematic Analysis	Planar Sliding
Slope Dip	50
Slope Dip Direction	150
Friction Angle	20°
Lateral Limits	30°


	Critical	Total	%
Planar Sliding (All)	11	219	5.02%
Planar Sliding (Set 5: Set 5)	10	10	100.00%

Plot Mode	Pole Vectors
Vector Count	219 (219 Entries)
Hemisphere	Lower
Projection	Equal Area



Pells Sullivan Meynink
Engineering Consultants
Rock-Soil-Water

Client:	Anderson Lloyd					
Project:	Project Quattro					
Location:	Gladstone Northwest Design Sector					
Analysis Description:	Orientated Core - IRA Planar Sliding					
Job No:	PSM125	By:	TM	Date:	21/07/2021	Scale: Stereo Plot
						Run: Gladstone_rev5.dips8



Symbol	TYPE	Quantity
◇	Breccia	21
×	CZ	7
◆	FT	26
■	SH	165
Symbol	Feature	
■	Critical Intersection	

Color	Density Concentrations
	0.00 - 0.70
	0.70 - 1.40
	1.40 - 2.10
	2.10 - 2.80
	2.80 - 3.50
	3.50 - 4.20
	4.20 - 4.90
Contour Data Pole Vectors	
Maximum Density 4.45%	
Contour Distribution Fisher	
Counting Circle Size 1.0%	

Kinematic Analysis	Wedge Sliding		
Slope Dip	50		
Slope Dip Direction	150		
Friction Angle	20°		
	Critical	Total	%
Wedge Sliding	5	15	33.33%

Plot Mode	Pole Vectors		
Vector Count	219 (219 Entries)		
Intersection Mode	Mean Set Planes		
Intersections Count	15		
Hemisphere	Lower		
Projection	Equal Area		



Pells Sullivan Meynink
Engineering Consultants
Rock-Soil-Water

Client:	Anderson Lloyd					
Project:	Project Quattro					
Location:	Gladstone Northwest Design Sector					
Analysis Description:	Orientated Core - IRA Planar Sliding					
Job No:	PSM125	By:	TM	Date:	21/07/2021	Scale: Stereo Plot
				Run:	Gladstone_rev5.dips8	