

Engineering Geology Ltd

- 1 +64 9 486 2546
- info@egl.co.nz

 info@egl.
- Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752
- www.egl.co.nz

EGL Ref: 9702

MATAKANUI GOLD LIMITED BENDIGO-OPHIR GOLD PROJECT SITE GEOTECHNICAL FACTUAL REPORT

Prepared for: 08 August 2025

Matakanui Gold Limited







EXECUTIVE SUMMARY

Data and observations presented in this Site Geotechnical Factual Report relate to geology and landform features within the project study area and the results of geotechnical investigation completed during 2024 and 2025.

The investigation comprised field mapping, the drilling of seven machine boreholes and the excavation of 68 testpits. A total of 21 vibrating wire piezometers were installed in the geotechnical boreholes in this investigation. Insitu testing comprise selected standard penetration testing (SPT), acoustic televiewer and full sonic wave form testing. Selected material recovered from testpits were tested in the laboratory to assist with characterisation of site materials.

The geotechnical investigation and sampling undertaken are relevant for foundation conditions and construction material of the following BOGP facilities:

- Process Plant and Infrastructure Area
- Tailing Storage Facility
- Engineered Landforms, and
- Silt Ponds

Interpretation and technical assessments of geotechnical factual information is provided in technical reports specific to each type of facility.

DOCUMENT CONTROL

Document information

Title	Matakanui Gold Limited
	Bendigo-Ophir Gold Project
	Site Geotechnical Factual Report
Revision	2
Date	08/08/2025
EGL Reference	9702
Client Reference	
File Name	BOGP Site Geotechnical Factual Report Final_Rev 2.docx

Document roles and approvals

Role	Name	Credentials	Signature	Doc. Rev.	Date
Author:	P. Carter	BSc (Geology), PGDip (EngGeol), MESt (Geotechnical Engineering), CPEng, CMEngNZ		2	08/08/2025
Reviewer:	E. Torvelainen	BE (Hons) Civil, MEngNZ		2	08/08/2025
Approver:	E. Torvelainen	EGL Director		2	08/08/2025

Final version report issues require signatures.

Document revision and issue record

Revision.	Date	Revision Description	Issued by
0	03/6/2025	Final	E. Torvelainen
1	22/7/2025	Revised executive summary	J. Zou
2	08/08/2025	Update to disclaimers	J. Zou

Final report versions and subsequent revision are assigned numeric revision numbers.

Document applicability and disclaimers

This report has been prepared by EGL (Engineering Geology Limited) solely for the benefit of Matakanui Gold Limited as our client with respect to the particular brief given to us for the Bendigo-Ophir Gold Project. If used by other parties and/or used in any other context or for any other purposes, no warranty or representation is given as to its accuracy and no liability is accepted for loss or damage arising directly or indirectly from reliance on the information in it.

This report shall only be read in its entirety.

Where this report is issued in draft the contents shall be for initial information and review only and are subject to change and shall not be relied upon.

The author of this report acknowledges that this report will be relied on by a Panel appointed under the Fast Track Approvals Act 2024 and these disclaimers do not prevent that reliance.

CONTENTS

	Page No.
1.0 INTRODUCTION	1
1.1. Site Location	1
1.2. Project Description	2
1.3. Site topography and catchments	2
2.0 GEOLOGY	3
2.1. Geological Units	3
2.2. Structural Geology	4
2.3. Landforms	4
3.0 GROUND INVESTIGATION OBJECTIVES	4
4.0 GROUND INVESTIGATIONS	5
4.1. 2024/2025 Investigation	5
4.1.1. Machine Boreholes	5
4.1.2. Testpits	5
4.1.3. Logging Standards	6
4.1.4. Standard Penetration Testing (SPT)	6
5.0 GROUNDWATER MONITORING INSTALLATIONS	7
6.0 GROUNDWATER MONITORING	7
7.0 PERMEABILITY TESTING	7
7.1. Falling Head Testing	7
7.2. Packer Permeability Testing	7
8.0 LABORATORY TESTING	7
9.0 INSITU ACOUSTIC TELEVIEWER AND SONIC WAVE FORM TES	STING 8
10.0 REFERENCES	9
TABLES TABLE 1 – LIST OF BOREHOLES TABLE 2 – LIST OF TESTPITS TABLE 3 – SUMMARY OF PIEZOMETER INSTALLATION DEPTHS TABLE 4 – LIST OF PACKER PERMEABILITY TESTS TABLE 5 – SUMMARY LABORATORY TESTING	
FIGURES FIGURE 1 - LOCALITY PLAN	
FIGURE 2 – PROPOSED SITE GENERAL ARRANGEMENT	
FIGURE 3 – TOPOGRAPHIC PLAN WITH STREAMS FIGURE 4 – GEOLOGICAL MAP	
FIGURE 5 – STRUCTURAL GEOLOGICAL FIELD MEASUREMENT PLA	
FIGURE 6 – ANNOTATED PLAN WITH OBSERVED LANDFORM FEATU	RES

APPENDICES

APPENDIX A - GROUND INVESTIGATION LOCATION PLANS

APPENDIX B – BOREHOLE LOGS AND CORE PHOTOGRAPHS

APPENDIX C – TESTPIT LOGS AND PHOTOGRAPHS

APPENDIX D - CONE PENETRATION TEST RESULTS

APPENDIX E - GROUNDWATER MONITORING DATA

APPENDIX F – PERMEABILITY TEST RESULTS

APPENDIX G - LABORATORY TEST RESULTS

APPENDIX H – INSITU ACOUSTIC TEST RESULTS



Engineering Geology Ltd

- **)** +64 9 486 2546
- info@egl.co.nz
- Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752
- www.egl.co.nz

EGL Ref: 9702

08 August 2025

MATAKANUI GOLD LIMITED BENDIGO-OPHIR GOLD PROJECT SITE GEOTECHNICAL FACTUAL REPORT

1.0 INTRODUCTION

Engineering Geology Limited (EGL) has been engaged by Matakanui Gold Limited (MGL) to provide this Site Geotechnical Factual Report for the Bendigo-Ophir Gold Project (BOGP). MGL is a subsidiary company of Santana Minerals Limited (SML). This report presents data and observations relating to the geology and landform features within the project study area and the results of a ground investigation programme of test pits and boreholes completed during 2024 and 2025.

MGL are proposing to establish the BOGP, which comprises a new gold mine, ancillary facilities, and environmental mitigation measures, on the Bendigo and Ardgour Stations in the Dunstan Mountains of Central Otago. The location of the project study area is shown in Figure 1.

The BOGP involves mining the identified gold deposits at Rise and Shine ("RAS"), Come in Time ("CIT"), Sreks ("SRX") and Sreks East ("SRXE"). Both open pit and underground mining methods will be utilised within the project site. Infrastructure to support the project will be constructed in the lower Shepherds Valley. The Tailings Storage Facility (TSF) is to be constructed in the upper Shepherds Valley, upstream of an Engineered Landform (ELF) constructed of overburden rock.

This report presents factual data from geotechnical investigations relevant to the:

- Process Plant and Infrastructure Area
- Tailing Storage Facility
- Engineered Landforms, and
- Silt Ponds

Interpretation and technical assessments are provided in other reports.

1.1. Site Location

The proposed site is located approximately 20 km northeast of Cromwell as shown in Figure 1. It is on the edge of the Bendigo Terrace and within the Dunstan Mountains of Central Otago.







1.2. Project Description

The proposed site layout is shown on Figure 2. The proposed mine site will comprise the following surface infrastructure:

- Worker Accommodation and Administration Buildings
- Access Road into the mine site,
- Processing Plant and Infrastructure Area,
- Shepherds Creek realignment,
- Access tracks,
- Clean water diversion channels,
- Haul roads,
- Topsoil stockpiles
- Engineered landforms (ELFs storing mined overburden rock),
- Tailing Storage Facility (TSF),
- Seepage Collection Sump, and
- Silt ponds

1.3. Site topography and catchments

The site topography, named creeks, and main catchments are shown in Figure 3. The site extends across the gravels of the Bendigo Terrace and schist rock of the Dunstan Mountains.

The identified gold deposits are approximately located within schist rock found between the Shepherds Creek and the slopes to the southwest of Rise and Shine Creek.

Both creek catchments start from a divide at approximately 950 mRL in the southeast and flow to the northwest. The creeks flow over schist rock within the valleys and onto gravel terraces in the northwest. Shepherds Creek is approximately 150 m lower than Rise and Shine Creek. The ridge between the creeks is approximately 60 to 190 m above the floor of Rise and Shine Creek, and 200 to 350 m above the floor of Shepherds Creek. Rise and Shine Creek flows into Clearwater Creek at approximately 650 mRL which in turn flows into Bendigo Creek at about 570 mRL. Shepherds Creek and Bendigo Creeks flow off the schist rock onto gravel terraces at approximately 350 mRL.

Shepherds Creek is a tributary to the Lindis River, which flows to the Clutha River. Rise and Shine Creek flows into Clearwater Creek, and then Bendigo Creek which is a tributary of the Clutha River. Under normal flows Shepherds Creek has no surface flow connection with the Lindis River with the surface water infiltrating the gravels. Both Bendigo Creek and Shepherds Creek have surface water takes which reduce flows across and into the gravels. Bendigo Creek also has no surface flow connection to the Clutha River for most of the year.

2.0 GEOLOGY

2.1. Geological Units

The following geological description of the strata that is inferred to underlie the BOGP is based on a review of available site-specific investigation results and information published on the Geological and Nuclear Science (GNS) 1:250,00 scale geological map (Ref. 1) and in the memoir "Geology of the Wakatipu Area" by Turnbull et al (2000) (Ref. 2). The relevant excerpt from the GNS geological map is presented as Figure 4.

The summary of the main geological units within the Project Study Area are as follows (after Turnbull et al 2000. Ref. 2):

Dredge Tailings and sluiced gravels (Q1n): Washed and redeposited quartz -schist gravels and sand. This unit was encountered as a veneer overlying other pre-existing surfaces down stream of historic gold workings.

Loess: These deposits are not mapped on geological maps of the area and are described in the geological memoir as "too thin, diffuse and complex to be shown on a map". Locally, on the lower flatter slopes the loess may have been deposited as a thin 'blanket deposit' with a depth of 1 to 2m thick while on steeper slopes it has been remobilised and forms a thin loess / colluvium slope wash unit containing material from the underlying rock.

Holocene Landslide Deposits (Q11): Deposits ranging from shattered rock to clay and boulder breccias. These materials are typically derived from underlying adjacent rocks. It may be described in some references as colluvium and slope wash deposits.

Undifferentiated Quaternary landslide deposits (uQl): These deposits are older than the Holocene deposits but have a similar composition. In some locations they may have been overlain by more recent Holocene landslide deposits.

Alluvial Deposits and Fans (Q1a & Q1af): Undifferentiated, typically unconsolidated, variable weathered gravels with interbeds of sands, silts and clays. This unit was generally encountered in the valley floor. These materials comprise clays, silts, sands and gravels derived from parent materials upslope of the deposition location.

Till (Q12t & Q16t): These deposits comprise till and outwash gravels. They are generally present as terraces against the western side of the Dunstan Mountains to the east of the Lindis River.

Torlesse TZ3 Schist (*Rakaia Terrane*, *Whakatipu Group*) (Yt3): Permian to Triassic era undifferentiated pelitic and psammitic schist and greenschist sequences. This unit may be locally weathered to a silty gravel.

Torlesse TZ4 Schist (*Rakaia Terrane*, *Whakatipu Group*) (Yt4): Permian to Triassic era undifferentiated pelitic and psammitic schist and greenschist sequences. This unit may be variable segregated, veined and foliated.

Thomson Gorge Fault Gouge: This deposit was not noted on the geological map. It typically comprises a band of material 2 to 10m thick derived from movement on the Thomson Gorge Fault. In general, this material comprises clays with some angular gravel. The fault gouge forms a 'marker bed' separating the TZ3 and TZ4 schist within the Study Area.

2.2. Structural Geology

Torlesse TZ3 and TZ4 schist within and adjacent to the project study area outcrops in many locations. Figure 5 presents the orientation of joints, foliation and shear zones on schist outcrop as measured in the field. Figure 5 also illustrates interpreted foliation form lines and the location of local fault / shears within the schist as interpreted by the site geologists.

2.3. Landforms

General natural and manmade landform features are annotated on Figure 6. These are compiled from visual observations undertaken by EGL and MGL geologists and are subject to interpretation. The annotated features comprise, landslides, hummocky ground, and areas of sluiced ground from historic gold mining.

3.0 GROUND INVESTIGATION OBJECTIVES

The objectives of the geotechnical investigation documented in this report was to:

- Characterise the ground conditions in the Lower Shepherds Valley for planning bulk earthworks and provide preliminary geotechnical design parameters for the mine infrastructure.
- Characterise the depth and rock quality within the foundations of the Tailings Storage Facility (TSF).
- Characterise the ground strength and conditions for the Engineering Landform structures (ELFs).
- Enable the installation of groundwater monitoring standpipes and vibrating wire piezometers for groundwater level characterisation.
- Enable in-situ permeability testing.
- Enable sampling and associated geotechnical laboratory testing.

Many exploration boreholes have been drilled around the mineralised deposits. Exploration boreholes generally target the gold mineralisation zones in the Torlesse TZ4 Schist. They typically start diamond core recovery a short length above the Thompson Gorge Fault in the TZ3 and extend through mineralised material to end in unmineralised TZ4. Exploration boreholes designed to collect diamond core through TZ3 schist (e.g. geotechnical investigation of the rock mass around planned open pit high walls) typically have recovery in excess of 95%. The exploration borehole logs are not presented in this report. The locations of selected exploration boreholes are shown on Figures E2 and F3 in Appendix A around the proposed Process Plant as they provide some information on the rock in this area as the TZ3 and TZ4 contact outcrops at the surface around this area.

4.0 GROUND INVESTIGATIONS

4.1. 2024/2025 Investigation

The 2024/2025 geotechnical investigation program targeted the:

- Rise and Shine Valley
- Shepherds Process Plant and Infrastructure Area
- Shepherds Tailing Storage Facility
- Shepherds Engineered Landform, and
- Shepherds Creek Silt Pond

The program used the following investigation methodologies:

- Test pits, and
- Machine drilled boreholes.

The location of the geotechnical test pits and boreholes are shown on the figures presented in Appendix A.

4.1.1. Machine Boreholes

A series of seven rotary cored boreholes (RC) were drilled by Alton Drilling Limited to investigate locations of interest within the Rise and Shine and Shepherds Valleys. The geotechnical boreholes were drilled using the exploration drill rig. The boreholes were numbered using the internal MGL system.

A table summarising the geotechnical borehole drilling is in Table 1. Borehole logs and core photographs are in Appendix B.

Geotechnical boreholes MDD362 and MDD365 targeted lower Shepherds Valley where the Process Plant and Infrastructure Area was proposed to be sited. Boreholes MDD362 and MDD365 are shown in Figure F3 in Appendix A. Around this area as shown on Figures E2 and F3 in Appendix A are reference exploration holes MRC060, MRC063, MRC071, MRC071R, MRC072, MRC072R, MRC073, MRC077, MRC078, MRC243, MRC244, MRC245, MRC246, MRC247 and MRC248. Refer to MGL for exploration borehole information.

Geotechnical boreholes MDD394, MDD396, and MDD399 targeted the Shepherds TSF embankment location.

Geotechnical boreholes MDD333 and MDD327 targeted general areas of interest in Rise and Shine Valley.

4.1.2. Testpits

The test pits were excavated by a 20-tonne hydraulic excavator with a nominal maximum excavation depth of approximately 7m (if ground conditions allowed).

The test pits were logged by EGL or MGL geologists. Typically, the test pits which were logged by EGL have the naming convention prefix "EGLTP" while the test pits that were logged by MGL have the naming convention prefix "MTP".

56 testpits have been excavated within the Shepherds Valley and 12 have been excavated within the Rise and Shine Valley. The test pits were numbered sequentially with the naming convention prefix of EGL or MTP as appropriate.

A tabulated list of testpits is in Table 2.

Test pit logs and photographs are in Appendix C.

4.1.3. Logging Standards

Full time supervision of the test pits was undertaken by a geologist from EGL or MGL.

Part time supervision of the machine boreholes was undertaken by an MGL geologist, with the recovered core either being logged adjacent to the drill rig or at the MGL core shed.

All test pits and machine boreholes were logged in general accordance with the relevant guidelines which are set out in the New Zealand Geotechnical Society publication "Field Description of Soil and Rock: Guidelines for the Field Description of Soil and Rock for Engineering Purposes." (2005) (Ref. 3).

4.1.4. Standard Penetration Testing (SPT)

In-situ Standard Penetration Tests (SPT's) were undertaken in some holes as the hole was advanced through the surficial soils. Such testing was completed in accordance with the relevant recommendations of New Zealand Standard 4402.6.5.1:1988 Determination of the penetration resistance of a soil, Test Method 6.5.1 Standard Penetration Test (Ref. 4).

SPT testing was generally undertaken until a depth where three subsequent 'N' counts greater than 50 had been recorded. Further SPT tests were not undertaken after this point.

The Standard Penetration Test (SPT) is an in-situ test that measures the number of blows required to penetrate a split spoon (in cohesive materials) or steel solid cone (in granular materials or weak rock) 300 mm into the material being tested (following a 150 mm deep initial seating). The number of blows required to drive the SPT tip 300 mm into the subject material is quoted as the SPT 'N' value. In situations where the number of blows to penetrate 300mm exceeds 50, the depth which the spilt spoon or cone has penetrated after 50 blows is recorded and is used to extrapolate a pro-rata SPT N-value.

For those situations where the SPT N-value is greater than 50 blows, the actual distance penetrated is recorded in the 'in-situ testing' column on the borehole logs.

Prior to the 300mm test length a 150mm seating drive length is penetrated. In cases where the test is discontinued before the full seating drive has been penetrated (i.e. when 50 blows have been achieved prior in less than the 150mm seating drive length), extrapolated 'N' values are quoted based on the blow counts and penetration measured within the seating drive length. This is noted within the 'in-situ testing' column on the borehole logs.

No additional correction to the SPT result is recorded on the borehole logs.

5.0 GROUNDWATER MONITORING INSTALLATIONS

A total of 21 of vibrating wire piezometers (VWP's) were installed within seven separate boreholes by staff from MGL. The boreholes and piezometer installation depths are provided in Table 3 and Piezometer installation details presented in Appendix D.

All VWP's were installed as fully grouted (cement-bentonite grout) piezometers. A 25mm PVC 'tremmie' tube with the vibrating wires attached on the outside of the tube was permanently installed in the borehole. This technique allows control of the vibrating wire tip depth.

6.0 GROUNDWATER MONITORING

Periodic monitoring of the groundwater level has been undertaken by the MGL field geologists.

The initial groundwater level monitoring data is presented in Appendix E.

7.0 PERMEABILITY TESTING

7.1. Falling Head Testing

Falling head testing was done in the soils and weaker rock at the top of the boreholes, where packer testing was not achievable. This comprised advancing the drilling casing to the target depth and retracing it to expose a test zone. The casing was then filled with water and the fall of the water in the casing was monitored over time. The summary of falling head testing is presented in Table 4.

7.2. Packer Permeability Testing

Packer permeability testing was undertaken in selected boreholes where an effective seal was achievable. Typically, the testing used a single packer as the boreholes were advanced. The purpose of the packer testing was to determine the permeability of the Torlesse TZ3 and TZ4 Schist and associated fault or shear zones.

The Packer permeability test data is presented in Appendix F. A summary of the packer testing is presented in Table 4.

8.0 LABORATORY TESTING

Representative samples were retrieved from select boreholes and testing undertaken at the Central Testing Laboratory (CTL) facility in Alexandria. The purpose of this testing was to inform characterisation of the various materials that were encountered onsite.

The laboratory testing undertaken by CTL, as appropriate, in accordance with the following relevant standards.

• Atterberg Limits: NZS4402,1986; tests 2.2, 2.3 and 2.4

Triaxial Permeability: BS1377:1990 Part 6 Section 6

Natural Moisture Content: NZS4402, 1986; test 2.1

• Particle Size Distribution (PSD):

Hydrometer Grading: NZS4402:1986 Test 2.8.4
Wet Sieve NZS4402:1986 Test 2.8.1

A summary of laboratory tests is presented in Table 5.

Full details of the laboratory test results are presented in Appendix G.

9.0 INSITU ACOUSTIC TELEVIEWER AND SONIC WAVE FORM TESTING

Insitu acoustic televiewer testing and full sonic wave form testing was undertaken by Southern Geophysical Limited. Testing was undertaken in boreholes MDD333 in the Rise and Shine Valley and MDD399 in Shepherds Valley at the Shepherds TSF location.

The acoustic televiewer testing is to be used to correlate against core measurements of dip and dip direction of foliation and jointing measured in the boreholes.

The purpose of the full sonic testing was to obtain shear wave velocities and primary wave velocities of the underlying rock.

The data is presented in Appendix H.

10.0 REFERENCES

- 1. GNS. (2018). GNS Geological Map of New Zealand 1:250,000
- 2. Turnbull, I. M. (2000). Geology of the Wakatipu Area. Institute of Geological & Nuclear Sciences Limited.
- 3. New Zealand Geotechnical Society (2005). Guidelines description of soil and rock for engineering purposes
- 4. New Zealand Standard 4402.6.5.1:1988 Determination Test Method 6.5.1 Standard Penetration Test.

TABLES

TABLE 1. SUMMARY OF BOREHOLE INVESTIGATIONS.

Borehole Number	Easting (mE)	Northing (mN)	Elevation (mRL)	Depth (m)	Reason for termination	Groundwater Depth
MDD327	1319076	5015882	758	70.0	Target depth	-
MDD333	1318599	5016226	736	45.0	Target depth	-
MDD362	1316258	5018870	731.78	35.0	Target depth	-
MDD365	1316751	5018614.70	766.19	44.3	Target depth	-
MDD394	1319759.6	5017190.4	594.6	30.0	Target depth	
MDD396	1319794.5	5017294.5	628.2	70.1	Target depth	
MDD399	1319629.1	5017032.7	683.9	70.1	Target depth	

TABLE 2. SUMMARY OF TEST PIT INVESTIGATIONS.

Test Pit	Easting	Northing	Elevation	Depth	Reason for	Groundwater
Number	(mE)	(mN)	(mRL)	(m)	termination	Depth
EGLTP01	1318256	5016437	734.7	2.5	Refusal	-
EGLTP02	1318356	5016320	735.5	1.9	Refusal	1.8
EGLTP03	1318419	5016227	745.0	1.8	Refusal	-
EGLTP04	1318596	5016244	743.2	2.6	Refusal	1.7
EGLTP05	1318484	5016163	750.4	0.9	Refusal	_
EGLTP06	1318625	5016210	741.7	2.4	Refusal	2.2
EGLTP07	1318837	5015974	754.9	2.4	Refusal	-
EGLTP08	1318895	5015999	754.9	2.9	Refusal	-
EGLTP09	1318988	5016001	761.0	1.3	Refusal	-
EGLTP10	1319080	5015894	759.3	2.7	Refusal	2.0
EGLTP11	1318906	5015709	825.5	0.4	Refusal	-
EGLTP12	1318819	5015847	788.2	0.3	Refusal	-
MTP01	1316671	5018646	-	6.0	Target Depth	5.6
MTP02	1316500	5018713	-	6.0	Target Depth	4.0
MTP03	1316387	5018772	-	4.0	Refusal	3.0
MTP04	1316380	5018755	-	4.1	Refusal	-
MTP05	1316420	5018812	-	7.0	Target Depth	-
MTP06	1316414	5018801	-	7.0	Target Depth	5.0
MTP07	1316356	5018867	-	6.0	Target Depth	-
MTP08	1316041	5019118	_	5.0	Refusal	4.5
MTP09	1316100	5019058	-	7.0	Target Depth	5.0
MTP10	1315960	5019155	-	7.0	Target Depth	7.0
MTP11	1315942	5019119	-	5.0	Target Depth	3.8
MTP12	1316133	5018989	-	6.0	Refusal	3.5
MTP13	1316232	5018841	-	6.5	Target Depth	-
MTP14	1316087	5019006	-	6.5	Target Depth	6.2
MTP15	1316144	5018940	-	4.5	Refusal	3.2
MTP16	1316288	5018828	-	6.5	Target Depth	6.0
MTP17	1316345	5018779	-	1.0	Refusal	-
MTP18	1316358	5018814	-	6.5	Target Depth	4.0
MTP19	1316306	5018800	_	2.5	Refusal	-
MTP20	1316428	5018725	-	5.5	Refusal	-
MTP21	1317720	5018320	-	2.5	Refusal	-
MTP22	1317605	5018412	-	5.5	Refusal	3.8
MTP23	1316871	5018638	_	6.0	Target Depth	3.0
MTP24	1316764	5018601	-	7.5	Target Depth	-

File: BOGP Site Geotechnical Factual Report Final_Rev 2.docx This report shall only be read in its entirety.

MTP25	1316746	5018646	-	4.5	Refusal	3.0
MTP26	1316056	5018915	-	3.5	Refusal	-
MTP27	1319109	5017662	-	3.0	Refusal	-
MTP28	1319221	5017654	-	2.0	Refusal	1.8
MTP29	1318550	5017889	-	2.8	Refusal	2.8
MTP30	1318491	5017956	-	3.5	Refusal	3.5
MTP31	1318383	5017970	-	2.3	Refusal	2.3
MTP32	1318478	5017971	-	0.0	Refusal	-
MTP33	1319852	5017117	-	5.0	Refusal	-
MTP34	1319901	5016998	-	3.0	Refusal	-
MTP35	1319709	5017224	-	3.2	Refusal	-
MTP36	1319779	5017103	-	4.4	Refusal	-
MTP37	1318345	5018273	-	2.8	Refusal	2.7
MTP38	1319594	5017241	-	3.0	Refusal	-
MTP39	1319409	5017431	-	2.4	Refusal	2.3
MTP40	1315509	5019447	-	7.0	Target Depth	-
MTP41	1315509	5019488	-	7.5	Target Depth	-
MTP42	1315293	5019891	-	7.0	Target Depth	-
MTP43	1315234	5019984	-	6.0	Target Depth	-
MTP44	1315206	5019965	-	7.0	Target Depth	-
MTP45	1315045	5020491	-	6.0	Target Depth	-
MTP46	1315063	5020510	-	6.5	Target Depth	-
MTP47	1316637	5018629	423.398	2.8	Target Depth	-
MTP48	1316660	5018644	423.651	3.1	Target Depth	-
MTP49	1316659	5018632	423.297	3.1	Target Depth	-
MTP050	1316726	5018592	431.79	4.1	Target Depth	-
MTP051	1316720	5018581	432.317	6.9	Target Depth	-
MTP052	1316732	5018648	426.829	3.2	Target Depth	-
MTP053	1316803	5018621	430.258	3.8	Target Depth	-
MTP054	1316821	5018591	431.624	3.6	Target Depth	-
MTP055	1316891	5018614	431.521	3.5	Target Depth	-
MTP056				4.2	Target Depth	-

Note: RL of test pits to be confirmed

TABLE 3 – SUMMARY OF PIEZOMETER INSTALLATIONS

BH ID	PIEZO TYPE	TIP LEVEL (RL)	GEOLOGY
MDD327	VIBRATING WIRE	748.26	TZ3
MDD327	VIBRATING WIRE	723.66	TZ3
MDD327	VIBRATING WIRE	694.66	TZ4
MDD333	VIBRATING WIRE	726.02	TZ3
MDD333	VIBRATING WIRE	708.02	TZ3
MDD333	VIBRATING WIRE	698.02	TZ4
MDD362	VIBRATING WIRE	404.34	TZ3
MDD362	VIBRATING WIRE	394.34	TZ3
MDD362	VIBRATING WIRE	379.34	TZ3
MDD365	VIBRATING WIRE	425.60	TZ3
MDD365	VIBRATING WIRE	415.60	TZ3
MDD365	VIBRATING WIRE	398.60	TZ3
MDD394	VIBRATING WIRE	584.63	TZ3
MDD394	VIBRATING WIRE	579.63	TZ3
MDD394	VIBRATING WIRE	596.63	TZ3
MDD396	VIBRATING WIRE	603.19	TZ3
MDD396	VIBRATING WIRE	583.19	TZ3
MDD396	VIBRATING WIRE	569.19	TZ3
MDD399	VIBRATING WIRE	648.85	TZ3
MDD399	VIBRATING WIRE	638.85	TZ3
MDD399	VIBRATING WIRE	618.8	TZ3

TABLE 4 – SUMMARY OF PERMEABILITY TESTING

BH ID	DEPTH (m)	Test type	Permeability Value k (m/s)	NOTES
MDD327	49.4m to 54.9m	Packer	9.20E-07	Void Filling
MDD327	63.1m to 64.4m	Packer	1.30E-06	Dilation
MDD362	20.7m to 28.2m	Packer	3.10E-07	Void filling
MDD362	29.9m to 35m	Packer	4.50E-09	
MDD365	35.3m to 41.3m	Packer	1.20E-09	
MDD394	5 to 7	Falling Head	2.90E-07	
MDD394	8 to 10	Falling Head	4.00E-08	
MDD394	11 to 13	Falling Head	1.80E-08	Artesian
MDD394	13.4 to 16	Falling Head	8.20E-09	
MDD394	11.5 to 16	Packer	2.00E-06	Dilation
MDD394	23 to 28.4	Packer	7.10E-07	Dilation
MDD396	5 to 7	Falling Head	4.50E-06	
MDD396	8 to 10	Falling Head	4.30E-06	
MDD396	19 to 22	Falling Head	4.00E-06	
MDD396	19 to 22	Packer	8.80E-08	Void filling
MDD396	41.3 to 44	Packer	1.80E-07	Void filling
MDD396	50.4 to 54	Packer	2.80E-07	Void filling
MDD396	61 to 64	Packer	7.8E-07	
MDD396	64 to 70.1	Packer	4.50E-08	Void filling
MDD399	5 to 7	Falling Head	3.30E-06	
MDD399	8 to 10	Falling Head	6.50E-06	
MDD399	11 to 13	Falling Head	6.20E-06	
MDD399	15 to 17	Falling Head	6.40E-06	
MDD399	17 to 19	Falling Head	6.40E-06	
MDD399	20 to 22	Falling Head	6.30E-06	
MDD399	25 to 27	Falling Head	7.30E-06	
MDD399	62.2 to 65.3	Packer	7.00E-06	Void Filling

EGL Ref: 9702 08 August 2025 Page 6

TABLE 5 - SUMMARY OF LABORATORY TESTING


Field	Sampling						ı	ab Testing				
Samples Names	Sample Size	Sample number	Particle Solid Density	Natural Moisture Content	Organic Content	Weathering	Crushing Resistance	Atterberg Limit	Wet Sieve	Hydrometer	Compaction curve (Standard)	Compaction Curve (heavy
TZ4 PQ Material	150kg		yes	43	(-	yes	yes	-	yes	-		-
Cherri Terrace cobbles/boulders	150 kg	MG 41762	2	4)	2	yes	yes	-	-	-	1	4
Cherri Terrace Fines/gravel	80kg	MG 41761	yes	yes	-	-	-	yes	yes	yes	yes	yes
Bendigo Borrow – Terrace Gravel	150kg	MG 41764		-	-	yes	yes	-	9	3	-	-
Bendigo Borrow – Terrace Gravel Fines	60kg	MG 41763	yes	Yes	-	-	-	yes	yes	yes	-	3
Loess	80kg	MG 41754	yes	yes	9	į.	-	yes	yes	yes	yes	yes
		MG 41756										
Weathered brown schist x2	150kg	MG 41755	yes (SD test one 1 sample)	yes		-	-	Yes	yes	yes	yes	yes
		MG 41758										
Topsoil x3	5kg	MG 41757	yes (SD test only 1 sample)	yes	yes	-	i	-	yes	yes	Ī	7
		MG 41759						•		•	•	
		MG 41760										
Alluvium/colluvium	150kg	MG41765	yes		1 -	15		yes	yes	yes	yes	
		Number of Tests	6	5	3	3	3	5	5	5	3	

Key:

yes

Test Completed

FIGURES




EGL
Geotechnical, Earthquake
and Dam Engineers
Engineering Geology Ltdwww.egl.co.nz



BENDIGO-OPHIR GOLD PROJECT SHEPHERDS CREEK & RISE & SHINE CREEK AREA GENERAL SITE ARRANGEMENT LOCALITY PLAN

DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	ET.	20/01/2025	9702	1:100,000	1








BENDIGO-OPHIR GOLD PROJECT SHEPHERDS CREEK & RISE & SHINE CREEK AREA SITE WIDE FACTUAL REPORT GENERAL SITE ARRANGEMENT

DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	13/01/2025	9/02	1:25,000	1








BENDIGO-OPHIR GOLD PROJECT SHEPHERDS CREEK & RISE & SHINE CREEK AREA SITE WIDE FACTUAL REPORT TOPOGRAPHY PLAN

DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	20/01/2025	9/02	1:25,000	1





Geotechnical, Earthquake and Dam Engineers
Engineering Geology Ltdwww.egl.co.nz



BENDIGO-OPHIR GOLD PROJECT SHEPHERDS CREEK & RISE & SHINE CREEK AREA SITE WIDE FACTUAL REPORT GENERAL SITE ARRANGEMENT

DRAWN CHECKED	R.M.	DATE	JOB No	SCALE (A3)	REV
	ET.	06/03/2025	9/02	1:50000	1






APPENDICES

APPENDIX A

Ground Investigation Location Plans








BENDIGO-OPHIR GOLD PROJECT COMPLETE LOCATIONS GROUND INVESTIGATION PLANS SITE PLAN

DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV
CHECKED	E.T.	09/03/2025	9/02	1:25,000	A








BENDIGO-OPHIR GOLD PROJECT COMPLETE LOCATIONS GROUND INVESTIGATION PLAN

DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	ET.	23/01/2025	9702	1:2,500	Α











BENDIGO-OPHIR GOLD PROJECT COMPLETE LOCATIONS GROUND INVESTIGATION PLAN

DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	ET.	23/01/2025	9702	1:2,500	I A















GROUND INVESTIGATION PLAN


DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	23/01/2025	9702	1:2,500	A





DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	23/01/2025	9/02	1:2,500	A












DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	23/01/2025	9/02	1:2,500	A






DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	23/01/2025	9702	1:2,500	A






COMPLETE LOCATIONS GROUND INVESTIGATION PLAN


DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	23/01/2025	9/02	1:2,500	A





MATAKANUI


DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV
CHECKED	E.T.	23/01/2025	9/02	1:2,500	ΙA







							7
DRA	AWN	R.M.	DATE	JOB No	SCALE (A3)	REV.	
CHE	ECKED	E.T.	23/01/2025	9702	1:2,500	Α	








DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	23/01/2025	9/02	1:2,500	A








DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	23/01/2025	9/02	1:2,500	ΙA





DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV
CHECKED	E.T.	23/01/2025	9702	1:2,500	I A



Geotechnical, Earthquake and Dam Engineers
Engineering Geology Ltd www.egl.co.nz



DRAWN	R.M.	DATE	JOB No	SCALE (A3)	REV.
CHECKED	E.T.	23/01/2025	9702	1:2,500	I A

APPENDIX B

Borehole Logs and Core Photographs



BOGP

Bendigo

COORDINATES: East 5015899.0 North 1319078.0

PROJECT:

LOCATION:

EGL

Engineering Geology Ltd

- +649 486 2546 info@egl.co.mz
- Unit 7C, 331 Rosedale Road, Albany, Awoklund PO Box 301054, Albany, Auckland 0752

RL GROUND: 756.0

NZVD 2016

DATUM:



DRILLHOLE No .: MDD327

SHEET 1 OF 8

Job No.:

HOLE STARTED: 28/05/2024 HOLE FINISHED: 09/06/2024

HOLE DEPTH: 70.0m INCLINATION:

Vertical

GRID: NZTM 2000 ORIENTATION: **Core Description Rock Defects Drilling & Testing** PT LOAD / UCS (MPa) FREQUENCY ROCK STRENGTH ENS SSOT 90 WEATHERING WATER LEVEL DEFECT DESCRIPTION GEOLOGICAL CORE LENGTH WATER (%) **ROCK / SOIL MATERIAL DESCRIPTION** DEPTH (m) FIELD TESTS 전 CORE (%) SAMPLES GRAPHIC & ADDITIONAL NOTES (%) ROD (DEP 885 292 - (2) 0,40 sandy SILT, fine to coarse sand; brown 0 0.30 0 sandy gravel, coarse sand, fine to medium gravel; 0.40 0 sandy SILT, fine to coarse sand; brown sandy gravel, coarse sand, fine to medium gravel; 0 7846 7847 754,6 brown 3 S Ó sandy SILT, fine to coarse sand; brown 0 Core Loss 0 Gravely sandy SILT, fine to medium gravel, greyish brown mottled brownish grey and grey 0 Silty CLAY, greyish brown gravelly SAND, fine gravels; brownish grey and grey 0.30 0 gravelly SILT, fine to coarse gravels; brownish grey with brownish grey, brown, and grey gravels 0.30 0 F washed coarse gravels; brownish grey and grey N/R MS Š gravelly SILT, fine to coarse gravels; brown, with 0 Š 3 brown, brownish grey, and grey gravels 752.6 silty GRAVEL, coarse gravels; Brown, grey, and N. 020 0,20 ì ₹ 0 gravelly SILT, fine to medium gravels; gray with grey, brown, and white gravel SW 0 washed coarse gravels; brown, white, and grey gravelly SILT, fine to medium gravels; grey with 0.50 SW MS Not Encountered grey, brown, and white gravels gravelly SILT some clay, fine to coarse gravels; with brown and brownish grey gravels 0.50 ₹ ₹ 0 Fragmented Schist, polyhedral blocks up to 30mm; grey 5.3m - 5.3m: Brown and white schist en 0.20 3 0 Groundwater SW 0 silty GRAVEL, fine to coarse gravels; grey and light 0,30 0 0.70 SW # Schist, greenish grey and light grey. Moderately deformed gently inclined foliation foliation shear slickensided polished day/gouge, measure dip reletive to the core centre line 60degree dip ≥ SW 0.80 38 MS foliation shear, slickensided, planar, Silt and Fragmented Pelitic Schist, polyhedral blocks graphite, measured reletive center of core dipping 70degrees up to 30mm; grey 0.40 0 SW W VW TZ3 foliation shear, smooth, planar, day/gouge, measured dip reletive to 7.5m - 7.6m: Clay smear over gravels < Log - 25/06/2024 2:34:43 pm - Produced with Core-GS by Gerac 0.30 20 center of core dipping 50degrees 0.80 29 foliation parting, smooth, planar, chlorite, no one but measured from SS Pelitic Schist, greenish grey and light grey, slightly deformed gently inclined foliation MS center of core 70degrees dip Fragmented Pelitic Schist, tabular up to core width 1 0 fault, 60°, rough, irregular, clay/gouge, pug fault 0.1cm wide on by 30mm and polyhedral blocks up to 10mm Pelitic Schist, greenish grey and light grey. Moderately deformed gently to moderately inclined present fault, 60°, rough, irregular, ŝ 8 20 MS day/gouge, pug fault 0,1cm wide ori foliation parting, 60°, smooth, planar, fold axis, 70°, rough, irregular, clean, Crush zone, grey, polyhedral blocks less than 10mm 74065 F3 fold with fracture ripping up axis, weak point rock2mm wide zone, fold 090 S 22 Pelitic Schist, grey and light grey, slightly deformed 3 zone 3cm long NOTES: LOGGED: DRILLER: WS

CHECKED: PC

DRILL TYPE:




BOGP

PROJECT:

LOCATION:

Engineering Geology Ltd





DRILLHOLE No.: MDD327

SHEET 2 OF 8

Job No.: HOLE STARTED: 28/05/2024

HOLE FINISHED: 09/06/2024

Bendigo DATUM: NZVD 2016 HOLE DEPTH: 70.0m COORDINATES: East 5015899.0 North 1319078.0 INCLINATION: Vertical

RL GROUND: 756.0

	Core Description				Rock Defects								Drill	ing 8	Testing	
100000000000000000000000000000000000000	ROCK / SOIL MATERIAL DESCRIPTION	DЕРТН (m)	DEPTHRL	GRAPHIC LOG	DEFECT DESCRIPTION & ADDITIONAL NOTES	FRACTURE THE OUT OF THE OUT OUT OF THE OUT OUT OF THE OUT OUT OF THE OUT OUT OF THE OUT OF THE OUT	WEATHERING	ROCK STRENGTH	PT LOAD / UCS (MPa)	B CORE LOSS 라 (%)	CORE LENGTH / TYPE	RQD (%)	SAMPLES	WATER LEVEL	22 WATER LOSS 54 (%)	FIELD TESTS
	gently inclined foliation Pelitic Schist, grey and light grey. Moderately deformed subhorizontal to moderately inclined foliation Crush zone, grey, polyhedral blocks up to 10mm within a matrix Pelitic Schist, grey. Highly deformed foliation Washed Psammitic Schist fragments, tabular up to 70mm by 20mm Crush zone, grey, polyhedral blocks up to 10mm within a matrix Core Loss Washed Psammitic Schist fragments, with fines layered below Clay gauge, grey Core Loss Washed Pelitic Schist fragments, tabular up to 60mm by 20mm Crush zone, grey, polyhedral blocks up to 10mm within a matrix Core Loss Washed Pelitic Schist fragments, tabular up to 60mm by 20mm Crush zone, grey, polyhedral blocks up to 10mm within a matrix Clay gauge, grey Core Loss Washed rock fragments, tabular up to 60mm by 20mm Crush zone, grey, polyhedral blocks up to 10mm within a matrix Clay gauge, grey Crush zone, grey, polyhedral blocks up to 10mm within a matrix Usashed Pelitic Schist fragments, tabular along foliation up to 60mm by 20mm 17.7m - 17.8m: Clay present, unkown if on outside only 17.9m - 18.8m: Clay present, unkown if on outside only 17.9m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m: Clay present, unkown if on outside only 18.4m - 18.8m; Clay present, unkown if on outside only 18.4m - 18.8m; Clay present, unkown if on outside only 18.4m - 18.8m; Clay present, unkown if on outside only 18.4m - 18.8m; Clay present, unkown if on outside only 18.4m - 18.8m; Clay present present	11 - 12 - 13 - 14 - 15 - 16 - 19 - 19 - 19 - 19 - 19 - 19 - 19	10.2 10.2 10.5 10.5 10.7		fault, rough, planar, claylgouge, no ori dip taken from center line of rook 50 degrees from center line of rook 50 degrees from center line fault, 45°, rough, irregular, claylgouge, shear/fault surface, zone 2 wide fault, 85°, rough, planar, claylgouge, micro fault dipping down hole, 5mm wide pug and fractured material foliation shear, 70°, smooth, planar, claylgouge, micro shear crosscutting foliation clay fill joint, rough, irregular, rock fragments, no ori line dips 50 degres up hole foliation, 65°, smooth, planar, clean, foliation meausrement dipp 65 degree, ori line present igon, foliation meausrement dipp 65 degree, ori line present foliation, 83°, smooth, planar, claylgouge, dipping 80uh, Ori present foliation, 83°, smooth, planar, clean, 83 dip dwn hole ori present foliation, smooth, planar, clean, no ori line dips 85 shear zone, claylgouge, no ori line. Puggy day zone with brittle fracturing crush zone, rock fragments, no ori line, wash drilled broken and grounded tz3 shear zone, claylgouge, no ori line, wash drilled broken and grounded tz3 shear zone with brittle rock fragments.		UN U	MS WW MS WW MS W W W WS W W W W W W W W			0.20 hallowing 0.30 0.20 0.30 0.30 0.30 0.20 hg 0.30 0.20 hg 0.30 0.20 0.30 0.20 0.30 0.20 0.30 0.20 hallowing 0.20 0.20 0.20 hallowing 0.20 0.30 hallowing 0.20 0.20 0.20 0.20 0.20 0.20 0.20 0.2	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Groundwater Not Encountered		

EGL - SMI Rock Log - 25/06/2024 2:34:44 pm - Produced with Care-GS by Geroc

CHECKED: PC

DRILL TYPE:



COORDINATES: East 5015899.0 North 1319078.0

Engineering Geology Ltd

+64 9 486 2546 info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Au-PO Box 301054, Albany, Auckland 0752 www.egl.co.nz



DRILLHOLE No.: MDD327

SHEET 3 OF 8

Job No.: 9702

HOLE STARTED: 28/05/2024 PROJECT: **BOGP RL GROUND: 756.0** LOCATION: Bendigo DATUM: NZVD 2016

HOLE FINISHED: 09/06/2024 **HOLE DEPTH:** 70.0m INCLINATION: Vertical

GRID: NZTM 2000 **ORIENTATION: Core Description Rock Defects Drilling & Testing** FRACTURE FREQUENCY ROCK STRENGTH Ħ PT LOAD / UCS (MPa) LOSS ဗို LEVEL WEATHERING DEFECT DESCRIPTION GEOLOGICAL CORE LENGTH WATER I **ROCK / SOIL MATERIAL DESCRIPTION** DEPTH (m) FIELD TESTS CORE 1 (%) ح SAMPLES GRAPHIC RQD (%) & ADDITIONAL NOTES NATER DEPTH 20 20 8 8 8 deformed subhorizontal inclined foliation MS 20 ⋚ ≥ C/L ≷ Crush zone, grey, polyhedral blocks up to 10mm 21 0 with a fine matrix (drilling induced?) ≥ 0 0.20 22 0.30 ≥ 0.20 ≥ 23 TZ3 0,20 24 0 ≥ Pelitic Schist, greenish grey and light grey. Moderately deformed gently inclined foliation 0.30 fault, 84°, polished, polished, 0 clay/gouge, puggy fault Crush zone, grey, polyhedral blocks up to 10mm within a matrix foliation, 86°, smooth, planar, clean, 0.30 Š ≥ Psammitic Schist, grey and light grey. Moderately deformed gently inclined foliation Groundwater C/L Washed Psammitic Schist fragments, tabular along foliation up to 60mm by 20mm Š joint, 84°, rough, planar, carbonate, SIN white powdery carb on joint surface 33 Washed Psammitic Schist fragments, tabular along foliation up to 60mm by 20mm ≥ 26 S Pelitic Schist, greenish grey and light grey. highly deformed foliation 0.60 29 foliation, 80°, smooth, planar, clean, clean smooth fault, 82°, rough, planar, clay/gouge, Crush zone, grey, polyhedral blocks up to 10mm 7289.47 729.6 ≷ ≷ largefault, pug filled with broken fresh 0.40 25 Washed Psammitic Schist fragments, with fines layered below foliation parting, 88°, smooth, planar, Psammitic Schist with clay smear on outside of core clean, near vertical parting on qz တ 0.50 80 Pelitic Schist, greenish grey and light grey. highly deformed foliation with crush seams up to 40mm joint, 83°, very rough, planar, rock fragments, light green sericitic alt wide following foliation schist very weak material TZ3 Pelitic Schist, grey and light grey. highly deformed 91 foliation parting, 86°, rough, irregular, clay/gouge, foliation hard to gauge due to heavly deformed material ≥ foliation, 70°, smooth, planar, clean, S foliation parting, 60°, rough, planar, clay/gouge, measurementup hole Psammitic Schist, grey and light grey. highly deformed foliation foliation shear, 70°, rough, planar, clay/gouge, clay filled sheared 8 85 29 joint shear, 60°, smooth, planar, Pelitic Schist, grey and light grey. highly deformed foliation 726.6 S clay/gouge, clay filledshear smooth foliation shear, 83°, rough, undulating, rock fragments, rockfragment 0.50 9

surfaceundulating

≥ ≥

JF

DRILLER:

DRILL TYPE:

LOGGED:

CHECKED: PC

25/06/2024 2:34:44 pm - Produced with Core-GS by Geroc Log-SMI Rock

EGL

NOTES:



BOGP

Bendigo

PROJECT:

LOCATION:

Engineering Geology Ltd

- +649 486 2546 info@egl.co.mz

RL GROUND: 756.0

DATUM:

NZVD 2016

Unit 7C, 331 Rosedale Road, Albany, Awoklund PO Box 301054, Albany, Auckland 0752 www.egl.co.nz



DRILLHOLE No.:

MDD327

SHEET 4 OF 8

Job No.:

HOLE STARTED: 28/05/2024 HOLE FINISHED: 09/06/2024

HOLE DEPTH:

Vertical

COORDINATES: East 5015899.0 North 1319078.0 INCLINATION: GRID: NZTM 2000 ORIENTATION: **Core Description Rock Defects Drilling & Testing** PT LOAD / UCS (MPa) FREQUENCY ENS ROCK STRENGTH COSS 90 WEATHERING WATER LEVEL DEFECT DESCRIPTION GEOLOGICAL CORE LENGTH WATER (%) **ROCK / SOIL MATERIAL DESCRIPTION** Ê FIELD TESTS 굺 CORE (%) SAMPLES GRAPHIC & ADDITIONAL NOTES (%) DEPTH DEPTH RQD (節用な 292 fault, 80°, rough, planar, rock fragments, rock fragment with cloritic Pelitic Schist, grey and light grey, highly deformed 30 schist foliation shear, 80°, polished, planar, clean, mirror slicken slide black Š 33 3 ≥ surface fault, 80°, very rough, planar, rock 3 SM 0.60 93 fragments, in theguts of fault foliation shear, 82°, polished, 31 WS. ž undulating, clay/gouge, polished foliation shear CO. 0,40 20 joint, 85°, very rough, irregular, rock fragments, very rough break 3 3 S 0.40 3 75 31.8 724, 32 3 > Washed Pelitic Schist fragments, with fines layered below 90 Pelitic Schist trace chlorite, grey and light grey. Moderately deformed moderately inclined foliation. foliation shear, 87°, polished, 3 irregular, clay/gouge, polished slickenslid co 0.50 20 Crush zone, grey, polyhedral blocks up to 20mm within a matrix (Possibly Drilling Induced) foliation parting, 83°, very rough, irregular, rock fragments, broken fac-3 ≥ 33 0.20 0 Pelitic Schist, grey and light grey. Moderately deformed subhorizontal to moderately inclined 3 u 0.60 foliation 83 722.6 Crush zone, grey, polyhedral blocks up to 40mm within a matrix (Possibly Drilling Induced) 3 3 Pelitic Schist, grey and light grey, slightly deformed moderately inclined foliation foliation parting, 80°, very rough, irregular, rock fragments, carbnate powder in fracture S 090 34 35 3 powder in tracture foliation shear, 75°, polished, planar, dean, polished slipped face foliation shear, 70°, smooth, planar, dean, almost polished face Washed Pelitic Schist fragements, with fines layered MS Groundwater Not Encountered ₹ 50 Highly fractured Psammitic Schist, grey and light 35 grey, moderately deformed gently inclined foliation 0.60 17 MS Fragmented Psammitic Schist broken along foliation, 0.20 0 0,20 0 123 3 0,30 33 foliation shear, 87°, polished, planar, dean, polished 3 0.40 0 0,20 20 0 Core Loss C/L 0 0 0 Fragmented Psammitic Schist broken along foliation, fines present as seperate layers 20 ≥ 0 Log - 25/06/2024 2:34:44 pm - Produced with Core-GS by Gerbo 20 ≥ 0 0 3 3 0.40 0 3 3 Psammitic Schist, grey and light grey, moderately deformed gently to moderately inclined foliation 3 09'0 67

foliation parting, 80°, smooth, planar dean, 80 dip

NOTES:

SM

EGL

crush zone, foliation present in tabular blocks up to

fragmented Psammitic Schist up to 50mm wide

20mm high matrix between

LOGGED:

3 ≥

DRILLER:

0.50 0

0.40 0

CHECKED: PC

DRILL TYPE:



Engineering Geology Ltd

+649 AR6 2546

info@egl.co.mz

Unit 7C, 331 Rosedale Road, Albany, Awakiwid PO Box 301054, Albany, Auckland 0752



DRILLHOLE No.:

MDD327

SHEET 5 OF 8

Job No.:

PROJECT: LOCATION:

GRID:

BOGP

COORDINATES: East 5015899.0 North 1319078.0

Bendigo

RL GROUND: 756.0

DATUM:

NZVD 2016

HOLE STARTED: 28/05/2024 HOLE FINISHED: 09/06/2024

HOLE DEPTH: 70.0m

Vertical

INCLINATION: ORIENTATION:

NZTM 2000 **Core Description Rock Defects Drilling & Testing** PT LOAD / UCS (MPa) FREQUENCY ROCK STRENGTH ENS COSS 90 WEATHERING WATER LEVEL DEFECT DESCRIPTION GEOLOGICAL CORE LENGTH WATER (%) **ROCK / SOIL MATERIAL DESCRIPTION** Ê FIELD TESTS 전 CORE (%) SAMPLES GRAPHIC & ADDITIONAL NOTES (%) DEPTH ROD (DEP 節田野 292 fragmented Psammitic Schist up to 50mm wide 715.5 Pelitic Schist, grey and light grey, highly deformed 12 foliation parting, 88°, rough, planar. Pelitic Schist, dark grey and light grey- highly deformed foliation 40.8m - 40.9m; crush seam 50mm rock fragments, rough surface о. 0.90 0 wide no foliation remaining 41.0m - 41.1m: crush seam 50mm wide no foliation remaining 05 41,2m - 41,3m; crush seam 50mm, wide no foliation remaining joint shear, 80°, rough, undulating, 41.5m - 41.6m; crush seam 50mm wide no foliation remaining rock fragments, rough surface foliation, 60°, ₹ Pelitic Schist, grey and light grey, moderately deformed gently inclined foliation 8 joint, 30°, rough, planar, rock fragments, 69 42 joint, 60°, stepped, undulating, dean, foliation, 60° Pelitic Schist, grey and light grey, slightly deformed subhorizontal inclined foliation fracture zone, rock fragments, broker fractured zone joint, 60°, stepped, stepped, rock fragments. joint, 70°, stepped, planar, rock 43 40 4 joint, 30°, smooth, undulating, clean, joint, 50°, rough, undulating, rock shear zone, clay/gouge, puggy clay zone with small rock frags Can't tell from photo N N/R 43,8 Pelitic Schist, grey, moderately deformed gently inclined foliation joint, 70°, rough, stepped, clean, shear zone, rock fragments, weak 250 0,60 55 Crush zone, grey, polyhedral blocks up to 20mm fractured shear zone with rock frags Encountered 3 Pelitic Schist, grey, moderately deformed gently foliation, 40°, fragmented Pelitic Schist along foliation up to 10mm 0.60 22 joint, 30°, rough, undulating, rock fragments, polished clay pug on the Pelitic Schist, grey and light grey, moderately deformed steeply to vertically inclined foliation Not 3 123 surface 45.1 710.9 Pelitic Schist, grey and light grey, highly deformed, fractures following foliation present shear zone, rock fragments, weak Groundwater shear zone 0,80 Schist, greenish grey and light grey, moderately 52 joint, 40°, smooth, undulating, rock 710.5 deformed gently to moderately inclined foliation. banding of greener present along foliation fragments. foliation 40° Pelitic Schist, grey and light grey, moderately deformed gently to moderately inclined foliation joint, 40°, rough, planar, rock fragments. 0,50 shear zone, rock fragments, weak 4 shear zone with large rock frags can't tell from photo joint, 60°, smooth, planar, clean, foliation, 60°, Pelitic Schist, grey and light grey, moderately deformed gently inclined foliation shear zone, rock fragments, weak r zone with some day joint, 40°, rough, planar, rock 9 69 Pelitic Schist, grey and light grey, highly deformed joint, 20", smooth, undulating, rock 47.3m - 47.4m: Fault offsetting foliation approx 45 degrees joint, 40°, rough, planar, rock 3 fragments Psammitic Schist, grey, moderately deformed gently inclined foliation Pelitic Schist, greyish green and light grey. moderately deformed moderately inclined foliation shear zone, rock fragments, brittle shear zone with rock frag Crush zone, grey, polyhedral blocks within a matrix (can't estimate size in photo) 30 09 joint, 70°, smooth, planar, clean, Pelitic Schist, dark grey and light grey. highly joint, 60°, smooth, planar, clean, deformed Pelitic Schist, grey and light grey, moderately deformed moderately inclined foliation Pelitic Schist, grey and light grey, highly deformed foliation, 60°. Pelitic Schist, grey and light grey, moderately deformed moderately inclined foliation 0.80 8 joint, 60°, smooth, planar, clean, 49.5 706,5 Pelitic Schist, grey and light grey, highly deformed 20 3 12 oint, 70°, smooth, planar, clean, NOTES: LOGGED: JF DRILLER:

CHECKED: PC

DRILL TYPE:

Log - 25/06/2024 2:34:44 pm - Produced with Core-GS by Gerbo WS

EGL



COORDINATES: East 5015899.0 North 1319078.0

Engineering Geology Ltd

+64 9 486 2546 info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752 www.egl.co.nz





DRILLHOLE No.: MDD327

SHEET 6 OF 8

Job No.: 9702

PROJECT: **BOGP RL GROUND: 756.0** LOCATION: Bendigo DATUM: NZVD 2016

HOLE FINISHED: 09/06/2024 **HOLE DEPTH:** 70.0m INCLINATION: Vertical

HOLE STARTED: 28/05/2024

ORIENTATION:

GRID: NZTM 2000 **Core Description Rock Defects Drilling & Testing** ROCK STRENGTH Ħ FRACTURE FREQUENCY PT LOAD / UCS (MPa) LOSS LOSS ဗို WEATHERING **NATER LEVEL** DEFECT DESCRIPTION GEOLOGICAL CORE LENGTH WATER I **ROCK / SOIL MATERIAL DESCRIPTION** FIELD TESTS DEPTH (m) CORE 1 (%) ح SAMPLES GRAPHIC RQD (%) & ADDITIONAL NOTES DEPTH 8 8 8 v 2 0 0 Pelitic Schist, grey and light grey. highly deformed ioint, 80°, smooth, planar, clean, -joint, 50°, smooth, planar, clay/gouge .20 Pelitic Schist, greenish grey and light grey. moderately deformed moderately inclined foliation 72 foliation, 50°, joint, 50°, smooth, undulating, clean, 51 joint, 60°, smooth, planar, clean, ഗ 20 85 52 ≷ Pelitic Schist, greenish grey and light grey. moderately deformed subhoriztonal foliation shear zone, rock fragments, 0.30 0 shear zone, rock fragments, 53 53 MS ioint, 40°, smooth, planar, clean, ∽foliation, 60°. 0.50 9/ Pelitic Schist, greenish grey and light grey. >shear zone, rock fragments, moderately deformed moderately inclined foliation 0.50 38 54 shear zone, clay/gouge, clay puggy shear zone coming into the TGF sandy CLAY fault gauge, minor polyhedral schist fragments up to 10mm fault, clay/gouge, TGF Encountered 0.40 Gorge Fault sandy CLAY fault gauge, trace polyhedral schist fragments up to 10mm 0.30 ≥ sandy CLAY fault gauge, minor polyhedral schist fragments up to 10mm Groundwater Not 0.50 0 sandy CLAY fault gauge, trace polyhedral schist fragments up to 10mm 0.30 100 Psammitic Schist, dark grey and light grey. moderately deformed moderately inclined foliation 7509.6 700.1 joint, 70°, smooth, undulating, Pelitic Schist, dark grey and light grey. highly deformed moderatelyno foliation present clay/gouge. Psammitic Schist, dark grey and light grey. highly joint, 70°, smooth, undulating, rock deformed foliation 4 91 fragments shear zone, 40°, rock fragments, joint, 40°, rough, planar, rock fragments, joint, 50°, smooth, undulating, clean, joint, 20°, smooth, planar, clay/gouge 57 ≥ joint, 60°, smooth, planar, clean, 57.5m: Fold present in foliation -∽joint, 60°, smooth, planar, clean, Pelitic Schist, dark grey and light grey. highly .20 87 joint, 70°, smooth, planar, clean, **TZ4** ഗ Pelitic Schist, dark grey and light grey. moderately deformed moderately to steeply inclined foliation joint, 70°, smooth, irregular, clean, joint, 60°, smooth, planar, clean, joint, 50°, smooth, irregular, clean, joint, 30°, stepped, planar, clean, 06.0 94 ∽joint, 40°, smooth, planar, clean, fracture zone, 20°, rock fragments, 00. 5 696.6 Pelitic Schist, dark grey and light grey, highly

LOGGED:

CHECKED: PC

JF

DRILLER:

DRILL TYPE:

Log - 25/06/2024 2:34:44 pm - Produced with Core-GS by Geroc SMI Rock

EGL

NOTES:



COORDINATES: East 5015899.0 North 1319078.0

Engineering Geology Ltd

+64 9 486 2546 info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752 www.egl.co.nz



DRILLHOLE No.: MDD327

SHEET 7 OF 8

Job No.: 9702

HOLE STARTED: 28/05/2024 PROJECT: **BOGP RL GROUND: 756.0** HOLE FINISHED: 09/06/2024 LOCATION: Bendigo DATUM: NZVD 2016

HOLE DEPTH: 70.0m INCLINATION: Vertical

ORIENTATION:

GRID: NZTM 2000 **Core Description Rock Defects Drilling & Testing** ROCK STRENGTH Ħ FRACTURE FREQUENCY PT LOAD / UCS (MPa) LOSS ဗို LEVEL WEATHERING DEFECT DESCRIPTION GEOLOGICAL CORE LENGTH WATER I **ROCK / SOIL MATERIAL DESCRIPTION** FIELD TESTS DEPTH (m) CORE 1 (%) 枟 SAMPLES GRAPHIC RQD (%) & ADDITIONAL NOTES NATER DEPTH 20 20 8 8 8 v 2 0 0 deformed foliation Pelitic Schist, dark grey and light grey. slightly deformed subhorizontally inclined foliation joint shear, 60°, smooth, planar, ഗ 30 65 Pelitic Schist, dark grey and light grey. moderately 61 joint, stepped, planar, clean, deformed very steeply inclined foliation >shear zone, rock fragments, Crush zone, grey, polyhedral blocks up to 20mm MS within a matrix Pelitic Schist, dark grey and light grey. moderately deformed gently inclined foliation ioint, 20°, smooth, planar, clean, 62 joint, 50°, smooth, undulating, clean, 40 66 ∽joint, 30°, smooth, planar, clean, Pelitic Schist, dark grey and light grey. slightly deformed moderately inclined foliation -joint, 60°, smooth, undulating, clean, -foliation, 30°, 63 joint shear, 30°, smooth, planar, clean, ∖joint, 60°, smooth, planar, clean, ∖joint, 60°, smooth, planar, clean, 4 6/ Pelitic Schist, dark grey and light grey. highly deformed foliation 64 joint, 60°, smooth, undulating, rock fragments Groundwater Not Encountered joint, 30°, smooth, planar, clean, Pelitic Schist, dark grey and light grey. moderately deformed subvertically inclined foliation Pelitic Schist, dark grey and light grey, highly deformed foliation 0.90 9/ $\stackrel{>}{\sim}$ TZ4 joint, 80°, smooth, curved, clean, foliation, 20° joint, 20°, smooth, undulating, clean, ഗ ioint shear, 60°, smooth, undulating, .50 29 66 >joint, 20°, smooth, planar, clean, Pelitic Schist, dark grey and light grey. moderately deformed moderately inclined foliation ∽joint, 60°, smooth, planar, clean, joint, 20°, smooth, planar, clean, ∽joint, 40°, smooth, planar, clean, 67 ∽joint, 50°, smooth, planar, clean, 8 88 Psammitic Schist, grey and light grey. slightly deformed subhorizontally inclined foliation ioint, 60°, smooth, planar, clean, Pelitic Schist, dark grey and light grey. moderately deformed subhorizontally inclined foliation joint, 50°, smooth, planar, rock 68 fragments ioint, 70°, smooth, planar, clean, Pelitic Schist, dark grey and light grey. moderately deformed subvertically inclined foliation 697.8 .50 67 Psammitic Schist, dark grey and light grey.
moderately deformed gently inclined foliation fracture zone, rock fragments, ∽joint, 70°, stepped, planar, clean, 69 Pelitic Schist, dark grey and light grey. moderately deformed gently inclined foliation 0.80 86 joint shear, 40°, stepped, planar NOTES: LOGGED: JF DRILLER:

CHECKED: PC

DRILL TYPE:

EGL



BOGP

Bendigo

COORDINATES: East 5015899.0 North 1319078.0

NZTM 2000

PROJECT:

LOCATION:

GRID:

Engineering Geology Ltd

+64 9 486 2546 info@egl.co.nz Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752 www.egl.co.nz



DRILLHOLE No.: MDD327

SHEET 8 OF 8

Job No.: 9702

> HOLE STARTED: 28/05/2024 **HOLE FINISHED**: 09/06/2024

HOLE DEPTH: 70.0m INCLINATION: Vertical

ORIENTATION:

RL GROUND: 756.0

DATUM:

Core Description Rock Defects Drilling & Testing CORE LENGTH / TYPE GEOLOGICAL UNIT ROCK STRENGTH PT LOAD / UCS (MPa) WATER LOSS (%) FRACTURE FREQUENCY CORE LOSS (%) GRAPHIC LOG WEATHERING **WATER LEVEL DEFECT DESCRIPTION ROCK / SOIL MATERIAL DESCRIPTION** DEPTH (m) FIELD TESTS DEPTH RL SAMPLES RQD (%) & ADDITIONAL NOTES

NZVD 2016

EGL - SMI Rock Log - 25/06/2024 2:34:44 pm - Produced with Core-GS by Geroc

NOTES: LOGGED: DRILLER:

> CHECKED: PC DRILL TYPE:



EGL Job No.	9702
Location:	Bendigo-Ophir Gold Project

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 0m to 1.4m



Depth: 1.4m to 2.7 m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 2.7m to 4.3m



Depth: 4.3m to 6.3m



EGL Job No.	9702
Location:	Bendigo-Ophir Gold Project

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 6.3m to 8.2m





EGL Job No.	9702

Location: Bendigo-Ophir Gold Project

 Start Date
 29 May 2024
 End Date
 8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 10.0m to 11.2m



Depth: 11.2m to 11.9m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 11.9m to 14.3m



Depth: 14.3m to 16.4m



EGL Job No.	9702

Location:

Bendigo-Ophir Gold Project

Start Date

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 16.4m to 18.7m



Depth: 18.7m to 20.4m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702


29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 20.4m to 21.1m

Depth: 21.1m to 22.3m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 22.3m to 23.8m



Depth: 23.8m to 24.8m



I ocation:	Bendigo-Ophir Gold Project	
EGL Job No.	9702	

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 24.8m to 26.3m



Depth: 26.3m to 28.4m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 28.4m to 30.3m



Depth: 30.3m to 32.1m



l ocation:	Rendigo-Ophir Gold Project
EGL Job No.	9702

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 32.1m to 33.5m



Depth: 33.5m to 34.4m



EGL Job No.	9702
Location:	Bendigo-Ophir Gold Project

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 34.4m to 37.3m



Depth: 37.3m to 39.7m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 39.7m to 42.2m



Depth: 42.2m to 44.9m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 44.9m to 47.4m



Depth: 47.4m to 50.0m



EGL Job No.	9702
Location:	Bendigo-Ophir Gold Project

29 May 2024

End Date

8 June 2024

Title:

MDD327 - CORE PHOTOGRAPHS



Depth: 50.0m to 52.5m



Depth: 52.5m to 54.9m



EGL Job No.	9702

Location: Bendigo-Ophir Gold Project

 Start Date
 29 May 2024
 End Date
 8 June 2024

Title:



Depth: 54.9m to 57.2m



Depth: 57.2m to 59.6m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

29 May 2024

End Date

8 June 2024

Title:



Depth: 59.6m to 62.2m



Depth: 62.2m to 64.6m



EGL Job No.	9702

Location:

Bendigo-Ophir Gold Project

Start Date

29 May 2024

End Date

8 June 2024

Title:



Depth: 64.6m to 67.2m



Depth: 67.2m to 69.7m



l ocation:	Rendigo-Ophir Gold Project
EGL Job No.	9702

29 May 2024

End Date

8 June 2024

Title:



Depth: 69.7m to 70.0m





GRID:

COORDINATES: East 5016220.3 North 1318602.7

NZTM 2000

Engineering Geology Ltd

+64 9 486 2546 info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752 www.egl.co.nz



DRILLHOLE No.: MDD333

SHEET 1 OF 10

Job No.: 9702

PROJECT: **BOGP** RL GROUND: 741.0 LOCATION: Bendigo DATUM: NZVD 2016

HOLE FINISHED: 14/06/2024 HOLE DEPTH: 45.0m INCLINATION: Vertical

HOLE STARTED: 12/06/2024

ORIENTATION:

Drilling & Testing Core Description Rock Defects FRACTURE FREQUENCY P00 DEFECT DESCRIPTION **ROCK / SOIL MATERIAL DESCRIPTION** FIELD TESTS & ADDITIONAL NOTES

ROCK STRENGTH WATER LOSS (%) GEOLOGICAL UNIT PT LOAD / UCS (MPa) CORE LOSS (%) WEATHERING WATER LEVEL CORE LENGTH DEPTH (m) SAMPLES DEPTH RL GRAPHIC RQD (%) 25 50 75 5 5 5 0 0 2 2 2 2 Topsoil Gravelly sandy SILT, fine to coarse gravel, greyish brown mottled brownish grey and grey 0.60 0.60 ≷ Š 0.50 Colluvium 0.60 2 Silty sandy GRAVEL, fine to coarse gravel, greyish Groundwater Not Encountered brown mottled brownish grey and grey 0.30 20 0.20 20 ≥ Core loss C/L Washed Pelitic Schist fragments, brown, polyhedral 22 0 24 0 ⋛ 0.20 0 Washed Pelitic Schist fragments, grey, tabular up to 60mm by 20mm 0.20 20 ≥ 23 **TZ3** 0.30 0 ≥ SE SW 0.30 Washed Pelitic Schist fragments, brown, polyhedral up to 20mm ≥ foliation, 65°, smooth, planar, clean, foliation no ori line just captured dip 0.30 MS Š MS

NOTES:

LOGGED: JF DRILLER:

CHECKED: PC

DRILL TYPE:

EGL - SMI Rock Log - 10/07/2024 8:57:06 am - Produced with Core-GS by Geroc



GRID:

Log - 10/07/2024 8:57:07 am - Produced with Core-GS by Geroc

SM

EGL

Engineering Geology Ltd

- +649 486 2546 info@egl.co.mz
- Unit 7C, 331 Rosedale Road, Albany, Awakiwid PO Box 301054, Albany, Auckland 0752



DRILLHOLE No .:

MDD333

SHEET 2 OF 10

INCLINATION: Vertical

ORIENTATION:

www.egl.co.nz Job No.: HOLE STARTED: 12/06/2024 RL GROUND: 741.0 PROJECT: BOGP HOLE FINISHED: 14/06/2024 LOCATION: Bendigo NZVD 2016 DATUM: HOLE DEPTH: COORDINATES: East 5016220.3 North 1318602.7

NZTM 2000 **Core Description Rock Defects Drilling & Testing** PT LOAD / UCS (MPa) LING FREQUENCY ROCK STRENGTH COSS 90 WEATHERING WATER LEVEL DEFECT DESCRIPTION **SEOLOGICAL** CORE LENGTH WATER (%) **ROCK / SOIL MATERIAL DESCRIPTION** Ê FIELD TESTS 굺 CORE (%) SAMPLES GRAPHIC & ADDITIONAL NOTES (%) DEPTH DEPTH ROD (節用な 292 882 au Washed Pelitic Schist fragments, grey, tabular up to 0.70 75 MS 60mm by 20mm Pelitic Schist, grey and light grey. Moderately deformed gently inclined foliation 0,60 29 Washed Pelitic Schist fragments, tabular up to 60mm by 30mm joint, 54°, defined ridges, irregular, clean, fbroken irregular face wavey texture, likely crenular texture 3 en Pelitic Schist, grey and dark grey. Highly deformed shear zone, 78°, very rough, planar, day/gouge, day filled fault 2cm wide foliation, day smear on core shear zone, 58°, very rough, planar, day/gouge, day filled fault 2cm wide 0.60 6 75 Pelitic Schist fragments, grey, polyhedral up to Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation foliation parting, 59°, rough, planar, clean, clean break foliation foliation parting, 77°, rough, planar, rock fragments, rock fragson foliation Pelitic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation (X) 0.80 80 joint, 59°, rough, irregular, rock fragments, irregular surface rock fraged face Pelitic Schist, grey and dark grey. Moderately deformed steeply inclined to subvertical foliation 3 Groundwater Not Encountered 7,3m: Fold present in foliationfold axis, 60°, rough, stepped, rock fragments, measurement should be retaken on rocket launcher, dip taken 0,40 733 73 elitic Schist, grey and dark grey, Highly deformed foliation. of brocken face likely be foliation. Ineation needs to be taken at shed 173 S shear zone, 44°, rough, planar, day/gouge, day filled faault 25mm 0.70 foliation, 56°, smooth, undulating, clean, wavey surface crest of f2 f3 in measure surface good lineation of fold access. No or line 0 8.1m - 8.1m: Fold present in foliationfold axis, 40°, smooth, planar, clean, measurent inaccurate, f3 fold in tz3 strong kink 3 Ó Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation 0.40 80 foliation parting, 70°, smooth, planar, clean, undulating surface Pelitic Schist fragments, grey, polyhedral up to stronglyfolded 0,10 0 CIL 0 Washed Pelitic Schist fragments, grey, polyhedral up 14 ≥ 30 3 Core loss 0 C/L 0 Pelitic Schist fragments, grey, polyhedral up to 20mm 9.3m - 9.4m: Clay present, unkown if on outside only 0.20 92 Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation foliation parting, 70°, smooth, planar 9,5m: Fold present in foliation 0.40 7 foliation shear, 80°, slickensided, MS planar, clean, measurement contacted on UHC of F3 fold surface, tecinically foliation shear? 731,3 Pelitic Schist, grey and dark grey, Moderately deformed gently to moderately inclined foliation 9.7m: Fold present in foliation 0.70 1 NOTES: LOGGED: DRILLER:

CHECKED: PC



GRID:

COORDINATES: East 5016220.3 North 1318602.7

NZTM 2000

Engineering Geology Ltd

#64 9 486 2546 info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752





NZVD 2016

DRILLHOLE No.: MDD333

SHEET 3 OF 10

Job No.: 9702

PROJECT: BOGP RL GROUND: 741.0

LOCATION: Bendigo

DATUM:

HOLE FINISHED: 14/06/2024 HOLE DEPTH: 45.0m INCLINATION: Vertical

HOLE STARTED: 12/06/2024

ORIENTATION:

Core Description Rock Defects Drilling & Testing ROCK STRENGTH PT LOAD / UCS (MPa) Ħ FRACTURE FREQUENCY LOSS ဗို WEATHERING **NATER LEVEL** DEFECT DESCRIPTION GEOLOGICAL CORE LENGTH WATER I **ROCK / SOIL MATERIAL DESCRIPTION** FIELD TESTS DEPTH (m) CORE 1 (%) ح SAMPLES GRAPHIC RQD (%) & ADDITIONAL NOTES DEPTH 20 20 8 8 8 v 2 0 0 Pelitic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation joint, 86°, rough, irregular, clean, 3 joint fractures coinsidering together, splayed across core 0.70 77 joint shear, 80°, slickensided, planar, clean, planar with slicken slide surface texture x cuts foliation joint, 20°, rough, stepped, clean, Pelitic Schist fragments, grey, tabular up to 60mm by 30mm shallow dipping joint fracture joint, 70°, smooth, irregular, clay/gouge, residure of 1 mm blue clay on surface, core very brittle, most pronouced fracture measured Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation 0.70 69 joint, 82°, rough, stepped, clay/gouge residure of 1mm blue clay on surface, core very brittle, most pronouced fracture measured 11 foliation parting, 70°, smooth, planar, foliation, 80°, rough, irregular, clay/gouge, clay filled fracture/foliation, irregurlar surface joint shear, 15°, rough, planar, clay/gouge, shallow slickened joint MS. racture running up hole crush zone, 88°, very rough, planar, (rock fragments, steeply dipping crush zone, cavity filled with rock fragments approx 10-30mm wide planar 82 joint, 81°, very rough, irregular, rock fragments, fractured material x cutting core surface, carbanate infulx 12 vertical streaks of carb overlaying folation perpenticular joint, 50°, rough, planar, rock fragments, moderate dipjoint Encountered vein type 3, 85°, 0, planar, carbonate dipping up hole joint, 86°, smooth, planar, rock fragments, at least 4 fractures over Š ≥ space of 20mm terminanting into schist, fracture measeared at the top Groundwater of fracturing zone 0.70 64 foliation, 87°, rough, planar, clay/gouge, py specks over surface of qz band, 80mm thick with cholrite qz fill Pelitic Schist fragments, grey, tabular up to 60mm by TZ3 joint shear, 30°, very rough, planar, clay/gouge, 5mm wide shear x cutting foliation 13 foliation parting, 79°, rough, planar, rock fragments, half a mm of clay residue on face but more fractured 0.40 72 material > foliation shear, 80°, slickensided. Iroliation shear, 80°, slickensided, undulating, clean, wavey surface foliation shear, 85°, smooth, planar, clay/gouge, clay filled smooth surface foliation, 89°, stepped, planar, clean, stepped foliation looks like you Fractured Pelitic Schist, grey and light grey. Highly couldclimb it joint, 78°, very rough, irregular, rock fragments, terminates across core 1.10 9 shear zone, 65°, very rough, undulating, clay/gouge, clayfilled with veinlet of py 2mm wide following edge of micro fault 10mm wide. Contects too joint SM joint shear, 82°, rough, planar, clay/gouge, faulted zone 30mm wide with fractures followfault plane, Pelitic Schist fragments, grey, tabular up to 60mm by joint, 86°, rough, irregular, clean, irregular surface rock fraged face 0.40 92 NOTES: LOGGED: DRILLER:

SMI Rock Log - 10/07/2024 8:57:07 am - Produced with Core-GS by Geroc

EGL

DTES: LOGGED: JF DRILLER:

CHECKED: PC DRILL TYPE:



BOGP

Bendigo

PROJECT:

LOCATION:

Engineering Geology Ltd

+649 486 2546

info@egl.co.mz

Unit 7C, 331 Rosedale Road, Albany, Awakiwid PO Box 301054, Albany, Auckland 0752 www.egl.co.nz

RL GROUND: 741.0

DATUM:

NZVD 2016



DRILLHOLE No.:

MDD333

SHEET 4 OF 10

Job No.:

HOLE STARTED: 12/06/2024 HOLE FINISHED: 14/06/2024

HOLE DEPTH:

COORDINATES: East 5016220.3 North 1318602.7 INCLINATION: Vertical GRID: NZTM 2000 ORIENTATION: **Core Description Rock Defects Drilling & Testing** PT LOAD / UCS (MPa) LINS FREQUENCY ROCK STRENGTH COSS 90 WEATHERING WATER LEVEL DEFECT DESCRIPTION GEOLOGICAL CORE LENGTH WATER (%) **ROCK / SOIL MATERIAL DESCRIPTION** Ê FIELD TESTS 굺 CORE (%) SAMPLES GRAPHIC & ADDITIONAL NOTES (%) DEPTH ROD (885 292 882 au Pelitic Schist fragments, grey, tabular up to 60mm by 0.70 5 foliation parting, 88°, smooth, undulating, clean, steeply dipping and Pelitic Schist, grey and dark grey, Moderately deformed subhorizontal to gently inclined foliation hammocky surface i.e wavey foliation parting, 87°, rough, planar, dean, level laminated schist SE 0,60 0 Pelitic Schist, grey and light grey. Highly deformed foliation parting, 87°, smooth, planar, clean, near vertical dip. Slight time up Pelitic Schist fragments, grey, polyhedral up to 20mm 16 7 3 3 Core loss 0 0 Pelitic Schist, grey and dark grey. Moderately 78 rately to steeply inclined foliation foliation parting, 78°, smooth, undulating, clay/gouge, venear of day over black smoother surface. Was able to break with hand, Low strength 17 foliation shear, 35°, polished, planar, day/gouge, polished surface of black day fill 10mm wide S 0.80 31 Not Encountered joint, 80°, rough, planar, rock fragments, rought face Pelitic Schist, grey and dark grey, Moderately deformed gently to moderately inclined foliation 3 3 joint, 65°, rough, undulating, rock fragments, joint x cutting puggy core with rock fragmented face 173 Groundwater foliation parting, 70°, rough, planar, clean, rought surface in puggy tz3 ₹ 0.60 99 Pelitic Schist, grey and dark grey, highly deformed core foliation, day p 17.9m; Clay seam 50mm wide moderately inclined joint, 86°, rough, planar, clay/gouge, puggy tz3 with clay skin, rock inside shows irrgeulatr rock surface 3 18,0m: Clay seam 50mm wide moderately inclined 3 0.40 0 joint, 89°, rough, imegular, rock fragments, vertical face slight dip up hole MS 8 0 Pelitic Schist, grey and dark grey, Moderately deformed moderately to steeply inclined foliation foliation shear, 40°, slickensided, polished, clean, change infoliation less deformed steeper 3 foliation parting, 52°, smooth, planar, clean, undulating surface with semi smoother surface borderline rough 19.8m - 19.8m: Crush seam, fragments up to 8mm within clay matrix; 50mm 0.90 wide, gently inclined 0 Pelitic Schist, grey and dark grey, Moderately deformed gently to moderately inclined foliation

Log - 10/07/2024 8:57:07 am - Produced with Core-GS by Geroc

WS

EGL

NOTES:

LOGGED:

DRILLER:

CHECKED: PC



COORDINATES: East 5016220.3 North 1318602.7

NZTM 2000

Engineering Geology Ltd

J +64 9 486 2546

info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752

www.egl.co.nz





DRILLHOLE No.: MDD333

SHEET 5 OF 10

Job No.: 9702

RL GROUND: 741.0 PROJECT: BOGP

LOCATION: Bendigo

GRID:

DATUM: NZVD 2016

HOLE STARTED: 12/06/2024 **HOLE FINISHED**: 14/06/2024

HOLE DEPTH: 45.0m INCLINATION: Vertical

ORIENTATION:

	Core Description				Rock Defects				_		1		וווווזט	ıy a	Testing	
GEOLOGICAL UNIT	ROCK / SOIL MATERIAL DESCRIPTION	DEPTH (m)	DEPTH RL	GRAPHIC LOG	DEFECT DESCRIPTION & ADDITIONAL NOTES	FRACTURE FREQUENCY FREQUENCY	WEATHERING	ROCK STRENGTH	PT LOAD / UCS (MPa)	25 CORE LOSS 50 (%)		RQD (%)	SAMPLES	WATER LEVEL	25 WATER LOSS 50 (%)	FIELD TESTS
	Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation	-	721.0		shear zone, 40°, very rough, planar, clay/gouge, 60mm wide fault		,	MS			06:0	0				
	Pelitic Schist fragments, grey, tabular up to 60mm by 20mm 20.3m: Clay seam 50mm wide, steeply inclined	-	720.7		crush zone, 88°, very rough, planar, rock fragments, crush zone at base o run, potenially driller inducedbut looks natural joint, 85°, very rough, irregular, rock	f	MU				0.20	0				
	Pelitic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation	- 21 _	20.6 720.4		fragments, jointed face dhc core above very broken joint, 85°, very rough, irregular, rock fragments, roughfracture x cutting rock			MS			0.70	0	-			
		-			shear zone, 70°, rough, planar, clay/gouge, pug filled 70cm fault											
	Dalkie Cabiet many	-	21.7 719.3		fragments, roughtrock fraged break joint, 78°, rough, planar, clean, rought steep dip											
	Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation	22 _	719.3		joint shear, 65°, smooth, planar, sulphides, smooth face with py semi polished across face						1.20	0		Encountered		
671	Pelitic Schist, grey and dark grey. Slightly deformed subhorizontal to gently inclined foliation	-	22.7 718.3		shear zone, 90°, rough, planar, rock fragments, diiping slightly up hole shear zone, 40°, rough, planar, clay/gouge, uh measuresment joint shear, 70°, slickensided, planar, chlorite, chloritic slickentslide fill		UW	NS					-	Groundwater Not Enco		
		23 _			foliation parting, 80°, smooth, undulating, clay/gouge, undulatingsurface with 1mm clay residue on surface foliation, 88°, polished, undulating, clean, mirror finish joint, 82°, very rough, irregular, rock fragments, rock frags in brocken bit foliation shear, 60°, polished,						1.00	0		0		
	Pelitic Schist fragments, grey, polyhedral up to 50mm	- 24 _	24.0 717.0		polished, sulphides, pyrite filled folation shear, mirrow polish joint shear, 70°, slickensided, planar, chlorite, chloritic slickentslide fill joint, 65°, rough, planar, rock fragments, roush joint DHC joint, 55°, smooth, planar, clean, joint downhole measurement foliation, 80°, smooth, planar, clean, uh measuresment joint, 86°, polished, planar, sulphides,			W			0.70	0				
	Pelitic Schist, grey and dark grey. Slightly deformed subhorizontal to gently inclined foliation	-	24.2 716.8		pyrites surface with black venear clay joint, 73°, polished, planar, sulphides, pyrites surface with black venear clay joint, 80°, rough, irregular, rock fragments, rock fragmented surface joint, 88°, smooth, planar, clean, steeply dipping planar joint foliation, 82°, rough, stepped, clean, stepped foliation but near vertical			MS			0.50	53				
	Crush zone, grey, polyhedral blocks up to 8mm within a matrix		24.8 716.2		joint shear, 70°, smooth, planar, clay/gouge, possible fautl but put in						0.70	0				
ОТ	TES:					LOGGED:		IF					DRI	LLE	R:	



COORDINATES: East 5016220.3 North 1318602.7

Engineering Geology Ltd

+64 9 486 2546 info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Au PO Box 301054, Albany, Auckland 0752

www.egl.co.nz



DRILLHOLE No.: MDD333

SHEET 6 OF 10

Job No.: 9702

HOLE STARTED: 12/06/2024 PROJECT: **BOGP** RL GROUND: 741.0 **HOLE FINISHED:** 14/06/2024 LOCATION: Bendigo DATUM: NZVD 2016

HOLE DEPTH: 45.0m INCLINATION: Vertical

ORIENTATION:

GRID: NZTM 2000 **Core Description Rock Defects Drilling & Testing** Ħ FRACTURE FREQUENCY ROCK STRENGTH PT LOAD / UCS (MPa) LOSS LOSS ဗို WEATHERING **NATER LEVEL** DEFECT DESCRIPTION GEOLOGICAL CORE LENGTH WATER I **ROCK / SOIL MATERIAL DESCRIPTION** FIELD TESTS DEPTH (m) CORE 1 (%) ح SAMPLES GRAPHIC RQD (%) & ADDITIONAL NOTES DEPTH 20 20 8 8 8 v 2 0 0 Crush zone, grey, polyhedral blocks up to 8mm as joint shear as it has been sheared 716,0 within a matrix foliation parting, 80°, smooth, SE Pelitic Schist, grey and dark grey. Moderately polished, clean, clean foliation 0 deformed gently to moderately inclined foliation Pelitic Schist, grey and dark grey. Moderately ≥ deformed subhorizontal to gently inclined foliation crush zone, 85°, rough, irregular, rock ≷ fragments, crush zone 30mm wide fragmented material fill Pelitic Schist, grey and dark grey. Moderately deformed moderately to steeply inclined foliation joint, 75°, rough, irregular, rock ഗ 8 fragments, softer material in joint. slight chloritic influx in foliation 26 foliation shear, 80°, very rough, planar, rock fragments, brittle host jointsome what following foliation ≷ shear zone, 85°, very rough, planar, ≥ clay/gouge, puggy fault 10cm long Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation joint, 86°, rough, planar, clean, cleanface clean break no fill joint, 70°, rough, planar, clean, clean face now fill 27 714.0 Pelitic Schist, grey and dark grey. Moderately joint shear, 71°, slickensided, planar, 30 deformed gently to moderately inclined foliation clean, slicken slide semi polished Encountered joint shear, 10°, polished, planar, rock fragments, shallow joint shear with black venear of clay 2mm wide clay Groundwater Not **TZ3** foliation parting, 80°, rough, planar, rock fragments, foliation break ≥ ഗ Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation joint shear, 50°, smooth, planar, clay/gouge, semi sheared joint with pug clay fill, more of the same up 10 28 0.70 Pelitic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation joint, 65°, rough, planar, rock fragments, rock fragment fill fracture foliation parting, 80°, rough, planar, rock fragments, rough surface clean break foliation parting, 70°, rough, planar, rock fragments, rough foliatio break 0.80 22 joint shear, 40°, smooth, planar, ≷ Pelitic Schist fragments, grey, polyhedral up to clay/gouge, clay filledsurfaceblackclay ≥ 50mm filledsurfaceblackclay shear zone, 20°, smooth, planar, clay/gouge, clay filld surface pug androck fragment fill zone joint shear, 5°, polished, planar, Pelitic Schist, grey and dark grey. highly deformed clay/gouge, clay slip surface joint shear, 3°, slickensided, irregular, foliation \leq 1.20 ഗ clay/gouge, very shallow dipping uh measurement foliation parting, 70°, smooth, planar clay/gouge, clay filled break Crush zone, grey, polyhedral blocks up to 15mm shear zone, 5°, rough, planar, rock fragments, rock fragment filled very within a matrix Pelitic Schist, grey and dark grey. Moderately

Log - 10/07/2024 8:57:07 am - Produced with Core-GS by Geroc SMI Rock

EGL

NOTES:

LOGGED: JF

DRILLER:

CHECKED: PC



BOGP

Bendigo

COORDINATES: East 5016220.3 North 1318602.7

PROJECT:

LOCATION:

EGL - SMI Rack Log - 10/07/2024 8:57:07 am - Produced with Cons-GS by Gerac

Engineering Geology Ltd

+649 486 2546
 info@egi.co.nz
 Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0/52
 www.egi.co.nz
 www.egi.co.nz



DRILLHOLE No.:

MDD333

SHEET 7 OF 10

INCLINATION: Vertical

Job No.: HOLE STARTED: 12/06/2024 RL GROUND: 741.0 HOLE FINISHED: 14/06/2024 DATUM: NZVD 2016 HOLE DEPTH: 45.0m

	Core Description				Rock Defects								Drill	ing 8	Testin	ig .
GEOLOGICAL UNIT	ROCK / SOIL MATERIAL DESCRIPTION	DЕРТН (m)	DEPTHRL	GRAPHIC LOG	DEFECT DESCRIPTION & ADDITIONAL NOTES	FRACTURE FREQUENCY	WEATHERING	ROCK STRENGTH	PT LOAD / UCS (MPa)	E CORE LOSS	CORE LENGTH / TYPE	RQD (%)	SAMPLES	WATER LEVEL	23 WATER LOSS 75 (%)	FIELD TESTS
	deformed gently to moderately inclined foliation Pelitic Schist, grey and dark grey, slightly deformed		36,8 710,2		soft schist, crumbles in hand joint shear, 80°, rough, planar, day/gouge, up filed joint break joint shear, 75°, rough, planar, day/gouge, step dipj oint shear zone, 65°, smooth, planar, day/gouge, 20mm wide foliation, 72°, smooth, planar, clean, foliation break joint shear, 45°, slickensided, planar, clean, slicken slide semi polished face joint, 75°, rough, planar, clean, zoneof			S WS S		1	1.20	0				
	steeply inclined foliation 31.1m - 31.2m: Crush seam, fragments up to 10mm no matrix: 50mm wide, triangular shape in core Pelitic Schist, grey and dark grey, Moderately deformed gently to moderately inclined foliation	31 -	31.2 709.8		20cm of heavily fractured area at least 7 fractures crush zone, 60°, very rough, planar, rock fragments, brittle broken joint, 2°, rough, planar, rock fragments, fracture heading uphole		MO	S)			1,10	0				
23	Pelitic Schist fragments, grey, polyhedral bimodal distribution, approx 20mm and 50mm Pelitic Schist, grey and dark grey. Highly deformed foliation 32.3m - 32.5m: Three Crush seams, fragments up to 8mm within clay matrix; 50mm wide, gently inclined.	32 -	32.0 703.0 32.2 703.8		Joint, 65°, smooth, planar, clean, uhc joint, 60°, very rough, irregular, rock fragments, rock fragmented surface foliation parting, 50°, rough, planar, day/gouge, uhomeasurement terminatesinto joint shear zone, 80°, rough, planar, rock fragments, larged brittle schist zonemeasureed astargestructure		Ŵ				05'0	0		Groundwater Not Encountered		
123	spaced 60mm apart Pelltic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation	33 _	33.0		foliation, 80°, rough, planar, clay/gouge, clay filled foliation surface joint, 45°, rough, planar, clay/gouge, roughish surfacethink layer/mm of clay on innsurface foliation shear, 40°, smooth, planar, clay/gouge, smoothingfacewithsomeminor		wo	s			1.20	0		Groundwater N		
	Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation Pelitic Schist, grey and dark grey. Highly deformed foliation	34 _	33.5 707.5 33.8 707.2		slickensurface joint shear, 80°, smooth, planar, day/gouge, smooth day filled joint joint shear, 70°, smooth, planar, day/gouge, shear zone, 30°, smooth, planar, day/gouge, day gouge filled with rock fragments 10mm wideapprox joint shear, 75°, smooth, planar, day/gouge, steeply dipping joint						1,10	0				
Gorge	Sandy CLAY fault gauge, trace polyhedral schist fragments up to 10mm Psammitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation		706.8 34.4 706.6		shear zone, 48°, smooth, undulating, day/gouge, tgf tz3 contact, very rough measurement hard to gage contact		Mn	W					1		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
TZ4	Pelitic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation		34.6 706,4		joint, 70°, rough, irregular, clean, clean break		MO	en			1.20	0			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
NO.	TES:		1		10	00000		Œ	14	111			DD	are		
						OGGED:		JF.					DR	ILLE	N.	



Engineering Geology Ltd

J +64 9 486 2546

info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752

www.egl.co.nz





DRILLHOLE No.: MDD333

HOLE STARTED: 12/06/2024

HOLE FINISHED: 14/06/2024

SHEET 8 OF 10

Job No.: 9702

RL GROUND: 741.0 PROJECT: BOGP LOCATION: Bendigo

DATUM: NZVD 2016

HOLE DEPTH: 45.0m INCLINATION: Vertical

COORDINATES: East 5016220.3 North 1318602.7

GR	ID: NZTM 2000										0	RIEN	ITAT	ION:	
	Core Description				Rock Defects							Drill	ing 8	Testin	g
GEOLOGICAL UNIT	ROCK / SOIL MATERIAL DESCRIPTION	DEPTH (m)	DEPTH RL	GRAPHIC LOG	DEFECT DESCRIPTION & ADDITIONAL NOTES	FRACTURE FREQUENCY FREQUENCY	WEATHERING	PTIOAN/IICS (MPa)	25 CORE LOSS	CORE LENGTH / TYPE	RQD (%)	SAMPLES	WATER LEVEL	25 WATER LOSS 50 %)	FIELD TESTS
	Pelitic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation	-			foliation, 50°, smooth, planar, clean, mostly very undulatingin core hard to find clear measurement shear zone, 70°, rough, planar, rock fragments, brittle fault		WU WU	20	1 1	1.20	0				
	Psammitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation	- - 36 _	35.9 705.1		foliation shear, 80°, smooth, planar, rock fragments, crumberly joint shearclay androck fragments		_	MS		20	0				
	Psammitic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation		36.3 704.7		joint, 3°, rough, planar, rock fragments, frature running up hole		MN			i					
	Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation	- 37 _	36.7 704.3		clean, uh measurement clean joint, 70°, rough, undulating, rock fragments, undulating join has wavey tsurface texture foliation parting, 85°, rough, irregular, clean, steeply dipping foliation foliation parting, 63°, rough,		4	w		-					
-	37.4m: Crush seam, fragments up to 10mm within clay matrix; 50mm wide, gently inclined Crush zone, grey, polyhedral blocks up to 10mm within a sand matrix	-	37.3 703.7		undulating, rock fragments, tappering outtoshallowerdip joint, 55°, rough, planar, clean, planar and rough surface shear zone, 60°, rough, planar, clay/gouge, clay pug filled fault 30mm wide		MN	SE SE		0.80	0		Encountered		
	Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation		37.5 703.5		joint, 89°, rough, irregular, rock fragments, near vertical aloha shear zone, 86°, rough, planar, rock fragments, slight uphole dip brittle pug and fracturing further up foliation, 85°, smooth, planar, clean,		H	A		-			Groundwater Not		
TZ4		38 _			strong core lot of qz foliation parting, 84°, rough, stepped, rock fragments, stepped folation parting		>			1.50	0		Ō		
	Pelitic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation Pelitic Schist, grey and dark grey. Slightly deformed subhorizontal inclined foliation	-	38.4 702.6 38.5 702.5		voic turo 2. 5° amonth, planer		WN	88		: : : : : : : : : :					
-	Pelitic Schist, grey and dark grey. Moderately deformed gently to moderately inclined foliation Fractured Pelitic Schist, grey and light grey. Highly	39 _	38.9 702.1 39.1 701.9		vein type 3, 5°, smooth, planar, carbonate, shallow dipping uh vein 3 8mm wide and 15ccm long over core, intact not breaks foliation parting, 86°, defined ridges, planar, dean, defined ridges definitely										
	deformed foliation Pelitic Schist, grey and dark grey. Slightly deformed subhorizontal inclined foliation Crush zone, grey, polyhedral blocks up to 10mm within a matrix Psammitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation	-	39.2 701.8 39.3 701.7 39.4 701.6		not slickens shear zone, 60°, smooth, undulating, clay/gouge, undulating jfault clay been compaced on contact to tz4 host rock, appears smooth and wavey joint, 30°, very rough, planar, rock fragments, rock fragment filled joint approx 5mm wide joint, 60°, rough, planar, clean, rock fragmentted but clean break	, , , , , , , , , , , , , , , , , , , ,	<	SW SY		1.30	0				
 TON	TES:		<u></u>			LOGGED:	JF			<u> </u>			RILLE	R: TYPE:	



Engineering Geology Ltd

J +64 9 486 2546

info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752

www.egl.co.nz





DRILLHOLE No.: MDD333

SHEET 9 OF 10

Job No.: 9702

RL GROUND: 741.0 PROJECT: BOGP LOCATION:

Bendigo DATUM:

GRID: NZTM 2000

EGL - SMI Rock Log - 10/07/2024 8:57:07 am - Produced with Core-GS by Geroc

COORDINATES: East 5016220.3 North 1318602.7

NZVD 2016

HOLE STARTED: 12/06/2024 **HOLE FINISHED**: 14/06/2024

HOLE DEPTH: 45.0m INCLINATION:

Vertical

ORIENTATION:

Core Description Rock Defe	-4-	- 1								
	is I	4	_		Luc		Drill	ing &	Testing	g
ROCK / SOIL MATERIAL DESCRIPTION ROCK /	% Z 2 2 5 FRACTURE 20 FREQUENCY	WEATHERING ROCK STRENGTH	PT LOAD / UCS (MPa)	25 CORE LOSS 50 (%)	CORE LENGTH / TYPE	RQD (%)	SAMPLES	WATER LEVEL	25 WATER LOSS 50 (%)	FIELD TESTS
Psammitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation clean, slicken slide surface clean been pulled apart vein type 3, 11°, smooth, plan carbonate, carb vein approx 5 wide, heading up hole foliation parting, 6°s , rough, p clean, rought face	ar,	MO			1.30	0	_			
Pelitic Schist, grey and dark grey. Highly deformed foliation Pelitic Schist, grey and dark grey. Highly deformed foliation Pelitic Schist, grey and dark grey. Moderately deformed subhorizontal to gently inclined foliation		wo sy			1.60	0				
shear zone, 70°, smooth, plar clay/gouge, large zone of hea folded schisosity with pugclay at base foliation parting, 80°, rough, ir clean, rock face fracture	vley 30mm 1111111111111111111111111111111111									
joint, 58°, rough, planar, clear fracture shallower dip foliation parting, 60°, smooth, sulphides, pyriates specked in blebsacroos surface joint, 80°, rough, irregular, cle crosscuts foliation shear zone, 70°, rough, plana clay/gouge, 20mm widepug fe shear zone, 84°, very rough, plana clay/gouge, clay gouge filled with some platey rock fragem foliation shear, 70°, very roug irregular, rock fragments, crus sheare jointunsure?	planar, nn, r, ult ulanar, ault ns	MO			0.90	0	-	Groundwater Not Encountered		
foliation parting, 80°, rough, p clean, fol joint, 80°, defined ridges, plan clean, dipping down hole joint, 9°, very rough, irregular, fla lyingfracturedownholemeasur foliation parting, 80°, smooth, clean, planar dip foliation parting, 80°, smooth, clean, planar dip foliation parting, 80°, smooth, clean, planar dip	anar,ana	, o			0.70	0				
foliation parting, 88°, smooth, clay/gouge, thin layer of black surface foliation shear, 70°, rough, plk clay/gouge, 20-30mm wide fol shear some pugfill, py blebs of foliation parting, 75°, smooth, clean, clean folition break	planar, clay on line in a clay of the clay of th				0.50	0	_			
45.0 = = = = = = = = = = = = = = = = = = =	LOGGED:	 JF		1:::	1		L DR	L RILLE	; ; ; ; R:	

CHECKED: PC



BOGP

Bendigo

COORDINATES: East 5016220.3 North 1318602.7

NZTM 2000

PROJECT:

LOCATION:

GRID:

Engineering Geology Ltd

J +64 9 486 2546

info@egl.co.nz

Unit 7C, 331 Rosedale Road, Albany, Auckland PO Box 301054, Albany, Auckland 0752

www.egl.co.nz



DRILLHOLE No.: MDD333

SHEET 10 OF 10

Job No.: 9702

> **HOLE STARTED**: 12/06/2024 **HOLE FINISHED**: 14/06/2024

ORIENTATION:

RL GROUND: 741.0 DATUM: NZVD 2016 HOLE DEPTH: 45.0m INCLINATION: Vertical

	Core Description				Rock Defects		Drilling & Testing
GEOLOGICAL UNIT	ROCK / SOIL MATERIAL DESCRIPTION	DEPTH (m)	DEPTH RL	GRAPHIC LOG	DEFECT DESCRIPTION E	FRACTURE FREQUENCY WEATHERING	OOAD / OO

EOH: 45.00 m

EGL - SMI Rock Log - 10/07/2024 8:57:07 am - Produced with Core-GS by Geroc

NOTES: LOGGED: JF DRILLER:

CHECKED: PC DRILL TYPE:



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

12 June 2024

End Date

14 June 2024

Title:

MDD333 - CORE PHOTOGRAPHS



Depth: 0.0m to 2.1m



Depth: 2.1m to 3.5m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

12 June 2024

End Date

14 June 2024

Title:



Depth: 3.5m to 4.8m



Depth: 4.8m to 6.3m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

12 June 2024

End Date

14 June 2024

Title:



Depth: 6.3m to 8.0m



Depth: 8.0m to 9.0m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

12 June 2024

End Date

14 June 2024

Title:



Depth: 9.0m to 10.7m



Depth: 10.7m to 12.7m



EGL Job No.	9702
Location:	Bendigo-Ophir Gold Project

12 June 2024

End Date

14 June 2024

Title:



Depth: 12.7m to 15.1m



Depth: 15.1m to 17.0m



EGL Job No. 9702

12 June 2024

End Date

14 June 2024

Title:



Depth: 17.0m to 19.0m



Depth: 19.0m to 20.6m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

12 June 2024

End Date

14 June 2024

Title:

MDD333 - CORE PHOTOGRAPHS



Depth: 20.6m to 22.5m



Depth: 22.5m to 24.2m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

12 June 2024

End Date

14 June 2024

Title:

MDD333 - CORE PHOTOGRAPHS



Depth: 24.2m to 25.8m



Depth: 25.8m to 27.7m



Location:	Bendigo-Ophir Gold Project
EGL Job No.	9702

12 June 2024

End Date

14 June 2024

Title:

MDD333 - CORE PHOTOGRAPHS



Depth: 27.7m to 29.45m



Depth: 29.45m to 31.5m